

**Appendix B**  
**Site Reconnaissance Photographs**

**Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR**



**Photo 1:** The Rufus N. Garrett Jr. U.S. Army Reserve Center occupies an approximately 150,000-square-foot site at 815 West 8<sup>th</sup> Street in El Dorado, Arkansas. View of front lawn looking to the northwest.



**Photo 2:** View of north adjacent property which is occupied by a church and is zoned commercial.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



**Photo 3:** View of east adjacent property. The eastern adjoining properties are all residential and the zoning is also residential.



**Photo 4:** View to the south of subject property. The southern boundary adjoining properties are residential and also zoned residential. Note, pole-mounted transformers circled in left background. Right background shows Storage Building.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



**Photo 5:** View to the west along the south side of the Training Building showing residential apartments. West side of subject property is zoned commercial/residential.



**Photo 6:** View to the west of subject property showing a residential area.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 7: Looking west from northwest corner of subject property at commercial garage.



Photo 8: Looking north of subject property at church parking lot. Note, fire hydrant and storm water drain occupying northwest corner of property.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



**Photo 9:** View of pole mounted transformers located in northeast corner of property.



**Photo 10:** Looking north from gazebo. View of war trophy on the Site.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



**Photo 11:** Looking south, at gazebo, from northeast corner of property. Note, Dumpster and storm water drain on left and kitchen grease trap in the right background.



**Photo 12:** View of Dumpster looking east from Training Building. Note, residential adjoining properties in background.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 13: Looking north from Dumpster at storm water drain.



Photo 14: Looking north at the south side of the Training Building. The arrow points to a storm drain on the Site.



Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



**Photo 17:** Looking southwest at grease trap on east side of Training Building. The kitchen and this associated grease trap are not in use.



**Photo 18:** View of water inside the grease trap.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 19: View looking southwest at cooling equipment associated with the Training Building.



Photo 20: Looking north, inside Training Building boiler room. The piping insulation appeared new.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 21: View inside boiler room in Training Building. Fluorescent tubes are stored here pending offsite recycling.



Photo 22: Typical office inside of Training Building.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 23: View of workout equipment in Training Building.



Photo 24: View of basic household strength cleaning supplies found in janitor closet in Training Building.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR




Photo 25: View of kitchen in Training Building. The kitchen is not in use.



Photo 26: Floor drain in center of kitchen in Training Building.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



**Photo 27:** Looking north from the west side of the Storage Building, note storage containers in the center, surplus motor pool vehicle on the left, and a tarp covering a forklift on the right side (see arrow) of the small container. Also, the shaded area is the former vehicle wash rack (VWR) location as indicated by the 1998 Historic Architectural Resources report.



**Photo 28:** View inside of larger storage container. Container holds field food preparation equipment.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 29: View inside of smaller storage container. Container holds field food preparation equipment.



Photo 30: Looking north from Storage Building at motor pool vehicles. Adequately sized, empty, oil catch pans to prevent engine oil from leaking onto the ground surface were under each vehicle. No stains were observed on the asphalt MEP area.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 31: View of oil catch pan under a motor pool vehicle.



Photo 32: Looking southwest at the north side (front) of the Storage Building.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 33: View looking to the east, showing west side of Storage Building.



Photo 34: Looking north at rear of Storage Building. Note lighter colored room off back of building formerly used for petroleum, oil, and lubricants (POL) storage. Also note forklift in right foreground and salvage drum to left of former POL storage.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



**Photo 35:** View of forklift behind Storage Building. This forklift is not operational.



**Photo 36:** Salvage drum full of sand behind Storage Building, next to former POL storage room.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



**Photo 37:** Looking northwest from the south side of the Storage Building at what appeared to be a removed grease rack.



**Photo 38:** View inside of former POL storage room. Room now houses field equipment.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 39: View of inside Storage Building, field equipment stored inside of locked cage (right) and on rolling shelves (left side).



Photo 40: View of shelved field equipment in Storage Building.

Rufus N. Garrett Jr. USAR Center  
815 West 8<sup>th</sup> Street  
El Dorado, AR



Photo 41: Looking south at front of Storage Building and flammable storage room.



Photo 42: Typical storage in cabinets in flammable storage room.