

Appendix B
Site Reconnaissance Photos

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 1: Sign on west side of the USAR Center Administrative Building.



Photo 2: Looking northeast, site view of the Administrative Building from the southwest corner of the Site.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 3: Looking north along South Lancaster Road, site view from the southwest corner of the property. Dallas Area Rapid Transit light rail line shown to the left.



Photo 4: Looking southwest, site view from the northwest corner of the MEP lot.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 5: Looking west from the northwest corner of the MEP lot. The facility Dumpster is in center of view, north end of Administration Building is in the left background, South Lancaster Road is in the background, and a car wash on adjoining property is to the right.



Photo 6: Looking south from the northwest corner of the MEP lot. Administrative Building is in the right background.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 7: Looking east from the southwest corner of the site. The adjoining property to the right is the apartment complex that was destroyed by a tornado.



Photo 8: Looking southwest toward Administrative Building from northwest corner of MEP lot. Note dirt pile in foreground and dumpster to the right.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 9: Looking west from the southwest corner of the OMS Building. The adjoining property to the left is the apartment complex that was destroyed by a tornado.



Photo 10: View of adjoining property to the north; a self-serve car wash.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 11: View of adjoining property to the south. A tornado destroyed an apartment complex at this location, and the remnants have been removed, with the exception of the foundations.



Photo 12: View of MEP lot to east from northwest corner of MEP lot.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 13: Looking north, view of vehicle wash pad. Note grates that drain spent wash water and direct it to the facility OWS.



Photo 14: Looking east across the MEP lot. Twin manhole covers are the OWS that service the vehicle wash pad in the background.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 15: View of manhole for vehicle wash pad water supply.



Photo 16: Looking west. Pot washing area of kitchen to left. Twin manhole covers are for kitchen grease trap. Note HVAC equipment in background. Smaller concrete squares in foreground and behind grease trap are for grease trap discharge line.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 17: Looking north down the west side of the OMS Building. Vehicle wash pad is in the background.



Photo 18: Looking east along south side of OMS Building. The adjoining property to right was an apartment complex destroyed by a tornado.

William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas



Photo 19: View of compressor in mechanical room of Administrative Building.



Photo 20: View showing asbestos-free pipe insulation in mechanical room of Administrative Building.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 21: View showing floor drain in mechanical room of Administrative Building.



Photo 22: Parts washer inside OMS Building.

William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas



Photo 23: Inside view of OMS Building.



Photo 24: Inside view of OMS Building showing leaking fork lift.

William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas



Photo 25: View of empty flammable storage materials cabinet inside OMS Building.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 26: View of sorbents placed over fluid drippage from vehicles in OMS Building.



Photo 27: View of spill containment equipment in a locker inside the OMS Building.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 28: View of chemicals stored inside OMS Building.



Photo 29: View of potential lead seal on wastewater discharge pipe at the southwest corner of the Administrative Building.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 30: View of pole-mounted transformers at the northwest corner of the property. This transformer services the car wash on the adjoining property to the north.

**William Herzog Memorial USAR Center
4900 South Lancaster Road
Dallas, Texas**



Photo 31: View of pole-mounted transformers at southwest corner of Administrative Building. This transformer services the USAR Center.