

Appendix B
Site Reconnaissance Photos

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 1: View of Houston #2 USAR Center, looking west across Perimeter Park Drive.



Photo 2: View of Houston #2 USAR Center, looking west across Perimeter Park Drive. Note newly constructed white, corrugated metal building in center of photograph.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 3: View of former vault located within an office in the main facility building.



Photo 4: View of newly installed wall lockers and cabinetry within the main facility building.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 5: View of kitchen located within the main facility building.



Photo 6: View of janitor's closet located in the women's restroom and a water heater in the background. An overhead access ladder is located on the wall to the right.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 7: View of grassy area located behind the main facility building, looking east.



Photo 8: View of north end of the main facility building. Note storm water catch basin located in the grass.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 9: View of unlabeled 55-gallon drum located along the western side of the corrugated metal building. It appeared to have been used as a door prop.



Photo 10: View of the inside of the corrugated metal building. Note caged storage in the background and overhead ventilation system.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 11: View of hazardous/flammable storage lockers and caged storage located along the northern MEP area.



Photo 12: View of northern MEP area, looking west. Container boxes were used for storage and deployment.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 13: View of MEP area, looking west. Note military vehicles and trailers parked.



Photo 14: View of 55-gallon drums located on spill pallets located along the northern MEP area. The northern property line is on the right of the photograph. The rusty cream colored container boxes are no longer used and are waiting for removal/disposal.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 15: View of container boxes located in the northwest corner of the MEP area. The rusty cream colored container boxes are no longer used and are waiting for removal/disposal. Note railroad line in the background in the left of the photograph.



Photo 16: View of the warehouse, looking west. Note the new storage locker (located in the left of the photograph), recently delivered to the Site and not permanently placed.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 17: View of recently replaced concrete due to buried electrical line problems. Note cracking in older concrete (grass/weed growth).



Photo 18: View of hazardous/flammable storage locker located along the eastern wall of the warehouse, looking west. This locker was empty during the August 2006 Site visit.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 19: View of hazardous/flammable storage locker located in front of the warehouse, looking south.



Photo 20: View of arms vault located within the warehouse.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 21: View of flammable materials locker located inside a caged storage area within the warehouse.



Photo 22: View of white floor tiles located in the women's restroom within the warehouse.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 23: View of the pole-mounted transformers just south of the warehouse along Perimeter West Drive, outside of the fenced area. Note the electric power box on the south wall of the warehouse.



Photo 24: View of the main electric boxes located within the warehouse on the south wall. A restroom is located in the left of the photograph.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 25: View of the MEP area looking north. Note the corrugated metal building in the background of the photograph on the right.



Photo 26: View of adjoining commercial office space/warehouses to the north of the Site.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 27: View of adjoining property to the east of the Site (Iron Mountain-Records Management). Vegetation along the fence line, which does not adjoin the Site, appeared to have been sprayed with herbicide.



Photo 28: View of Houston #3 USAR Center, adjoining the Site to the south.

Houston #2 USAR Center
7077 Perimeter Park Drive
Houston, Texas



Photo 29: View of warehouses constructed in 2005 adjoining the Site to the west.