



Photograph 1. East exterior of the Oswald USARC Administration Building



Photograph 2. South exterior of the Oswald USARC Administration Building



Photograph 3. Approximate location of Former 2,000-Gallon UST Adjacent to Former Boiler Room



Photograph 4. Boiler room



Photograph 5. View of the drill hall located in the Oswald USARC Administration Building



Photograph 6. View of a typical classroom room in the Oswald USARC Administration Building




Photograph 7. View of a typical office in the Oswald USARC Administration Building



Photograph 8. View of a typical hallway in the Oswald USARC Administration Building



Photograph 9. View of the kitchen in the Oswald USARC Administration Building



Photograph 10. Grease trap access situated on the southwest exterior of the Oswald USARC Administration Building



Photograph 11. View of the bay doors situated on the south exterior of the OMS Building



Photograph 12. Interior of the OMS Building vehicle maintenance area



Photograph 13. View of oil and grease storage in the OMS Building




Photograph 14. Solvent sink located in the OMS Building vehicle maintenance area



Photograph 15. View of Hazmat Storage Structure situated west of the OMS Building



Photograph 16. View of the interior area of the Hazmat Storage Structure



Photograph 17. View of the former Hazmat Storage Shed situated immediately west of the OMS Building



Photograph 18. OWS separator situated on the northeast portion of the Site



Photograph 19. View of the portable Hazmat Storage Sheds #1 and #2 (pictured left) and a CONEX trailer (pictured right), looking northeast



Photograph 20. Interior view of Hazmat Storage Shed #1



Photograph 21. Interior view of Hazmat Storage Shed #2



Photograph 22. Interior view of the flammable storage cabinet situated in Hazmat Storage Shed #2



Photograph 23. View of the northeastern portion of the Site in the approximate location of a suspected former UST



Photograph 24. Gated entrance to the northern portion of the Site, looking southwest from Rainier Avenue



Photograph 25. OWS situated in a planter area adjacent to the POV parking lot on the eastern portion of the Site



Photograph 26. Pad-mounted transformer situated on the southern perimeter of the Site



Photograph 27. MEP area on the southwestern portion of the Site, looking north



Photograph 28. Storm drain situated on the southeast portion of the MEP area



Photograph 29. Gated entrance accessible via 12th Street, looking south from the Site towards the adjoining property (across 12th Street) occupied by an apartment complex



Photograph 30. Meadows Apartments situated east of the Site across Rainier Avenue, looking southeast



Photograph 31. View of the adjoining shopping plaza situated north of the Site



Photograph 32. View of the adjacent residential property west of the Site