



Photograph 1. POV area on east side of USARC administration building



Photograph 2. POV area on east side of administration building



Photograph 3. Gravel MEP area with vehicles and OMS



Photograph 4. Gravel MEP area



Photograph 5. Security fence between OMS (left) and administration building



Photograph 6. Chain link and wire reinforced fence around administration building



Photograph 7. Landscaping on west side of administration building



Photograph 8. Gravel area by OMS



Photograph 9. Open space with scrub grasses and low growing vegetation



Photograph 10. South entrance of administration building



Photograph 11. South side of administration building



Photograph 12. West side of administration building



Photograph 13. East side of administration building



Photograph 14. North exterior of administration building



Photograph 15. Front entry area of administration building



Photograph 16. Main hallway in administration building



Photograph 17. Typical classroom setup in administration building



Photograph 18. Typical office setup in administration building



Photograph 19. Former indoor firing range, now weight and physical training room



Photograph 20. Pitting in block walls from former indoor firing range use



Photograph 21. Drill hall



Photograph 22. Interior of unit storage cage in drill hall area



Photograph 23. Interior of unit storage cage in drill hall area (water cans are empty)



Photograph 24. Weapons vault door



Photograph 25. Boiler in administration mechanical room



Photograph 26. Administration building air conditioning unit



Photograph 27. OMS exterior looking east



Photograph 28. OMS exterior looking south



Photograph 29. OMS exterior



Photograph 30. Relatively empty OMS interior



Photograph 31. Fire proof cabinet in OMS



Photograph 32. Fire proof cabinet in OMS showing contents



Photograph 33. Fire proof cabinet in OMS with partially empty lubricating oil and antifreeze



Photograph 34. Grease trap at rear of administration building



Photograph 35. Grass infiltration pond and overflow drywell (center)



Photograph 36. View of adjacent open space north of USAR Center



Photograph 37. Port of Pasco administration office south of USAR Center



Photograph 38. Wondrack Distributing gasoline station east of USAR Center



Photograph 39. M&M Bolt south east of USAR Center



Photograph 40. Safety Kleen southwest of USAR Center



Photograph 41. Rear of Safety Kleen southwest of USAR Center




Photograph 42. Cracked floor tile in administration building



Photograph 43. Torn insulation wrap on boiler piping



Photograph 44. Drum of waste groundwater from monitoring wells



Photograph 45. Label on 55 gallon drum of wastewater from monitoring wells