


APPENDIX B
SITE RECONNAISSANCE PHOTOGRAPHS



Photograph 1. Administration Building facing north



Photograph 2. Administration Building facing west



Photograph 3. POV facing north



Photograph 4. OMS facing southwest



Photograph 5. Administration Building and OMS



Photograph 6. OMS facing northwest



Photograph 7. OMS facing west



Photograph 8. Administration Building facing west



Photograph 9. OMS facing northwest



Photograph 10. 5000-gallon Diesel Tanker



Photograph 11. 100-gallon Diesel Spill Location (southwest of OMS)



Photograph 12. Insulation in Boiler Room



Photograph 13. Insulation in Boiler Room



Photograph 14. Used auto battery storage



Photograph 15. Waste Containers



Photograph 16. Hazmat Shed



Photograph 17. Caged Hazmat Storage Area. Used oil AST is grey structure in center of shed.



Photograph 18. Hazmat Cabinet and Solvent Wash Station



Photograph 19. Mobile Hydraulic Lifts



Photograph 20. Former Indoor Firing Range



Photograph 21. New oil lines and drums in OMS



Photograph 22. Hazmat cabinet #1



Photograph 23. Hazmat cabinet #2



Photograph 24. Janitorial Supply Room



Photograph 25. Peeling paint in Boiler Room



Photograph 26. Off-site (Cintas) facing east



Photograph 27. Off-site in background facing north



Photograph 28. Industrial Park southeast of Site



Photograph 29. Industrial Park Building east of Site



Photograph 30. Spokane Valley Recycling/Treatment Center Facing West



Photograph 31. LaQuinta Hotel south of Site



Photograph 32. Construction Supply Center southwest of Site



Photograph 33. OWS next to former Vehicle Wash Rack



Photograph 34. Grease trap in kitchen and cleaning chemicals



Photograph 35. Former vehicle wash rack



Photograph 36. Hazmat storage shed #1 includes anti-freeze, lube oil, and grease



Photograph 37. Grassy area on west side of administration building showing Drywell #1