

Appendix B
Site Reconnaissance Photos

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 1: The Grimes Memorial USAR Center as viewed from South Treadaway Boulevard. The red tile roof is on the portion of the building that was built in 1951.



Photo 2: View of the VWR located on the east side of the OMS. Grates in the center are the OWS. Bill Reed Distributing, to the north, is in the background.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 3: View of foundation of former grease rack on east side of OMS. The VWR is adjacent east of the grease rack, just out of view to the left. View is toward the south with the MEP area in the background.



Photo 4: Building addition to USAR Center constructed in 1979. Note the flat tar roof on the addition as opposed to the red tile roof on the original building (Photograph 1).

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 5: Hazardous materials storage shed located south of the OMS in the MEP area.



Photo 6: Indoor firing range with concrete floor and plywood walls.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 7: Indoor firing range showing the concrete roof and plywood covered walls.



Photo 8: Cracked wall in office area of building constructed in 1951. This crack is present down the full length of the wall, across the floor and up the opposing wall.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 9: Floor drain in OMS restroom. This floor drain is typical of other floor drains at the USAR Center.



Photo 10: North room of hazardous materials shed showing empty and partially full used oil and antifreeze drums.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 11: Shelves in south room of hazardous materials shed showing consumer-sized POLs.



Photo 12: MEP area south of the OMS. The hazardous materials storage shed is visible behind the pick up truck.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 13: Janitor's closet located in the USAR Center Training Building.



Photo 14: South end of the former grease rack. The tan area in the concrete is fill material. USAR Center personnel were not familiar with why this area had been filled in. The OMS is the building in the background.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 15: Area west of the Assembly Hall that is depicted on a map in the Parsons 1998 Architectural Assessment report as having two USTs.



Photo 16: Indoor firing range. The range was decommissioned and the exhaust vent was covered with a metal plate.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 17: Bill Reed Distributing, located adjacent to the north of the Site.



Photo 18: View of the former drive-in theater (vacant lot) across Treadaway from the Site. The southern POV parking area is in the foreground.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 19: Crescent Supply Company is directly across Treadaway from the Site. Crescent is an oil field equipment supply company. A vacant drive-in is at left of photograph.



Photo 20: Willow Creek Center is located southwest of the Site across Treadaway. Crescent Supply Company can be seen at the left of the photograph.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 21: Street Foundation Drilling located adjacent to the south of the Site. The fence on the right side of the photograph is the USAR Center boundary.



Photo 22: Soil pile west of the MEP area. The soil pile composition is similar to the fill material at the former grease rack. View is to the northwest.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 23: Area of broken concrete near the southeast corner of the fenced area of the Site.



Photo 24: Clogged drain in the kitchen of the USAR Center Training Building. Several other drains in the kitchen were also clogged and backing up onto the floor.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 25: Clogged drain outside the north kitchen wall. This drain services the outside wash area near the north exterior door of the kitchen.



Photo 26: Three pole-mounted transformers located north of the northern POV parking area (west pole). All three PMTs are listed as "not tested" in the 1997 PCB Assessment Report.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 27: Two pole-mounted transformers located north of the northern POV parking area. One transformer is listed as “non-PCB” and one is listed as “not tested” in the 1997 PCB Assessment Report.



Photo 28: Peeling paint and toweled on texture on the north exterior wall of the Assembly Hall.

**Grimes Memorial USAR Center
4300 S. Treadaway Boulevard
Abilene, Texas**



Photo 29: Peeling ceiling paint in Office 102 at the northeast corner of the USAR Center Training Building.



Photo 30: Peeling paint on an I-beam on the north side of the Assembly Hall.