

Appendix B
Site Reconnaissance Photographs

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 1: Looking south from the POV parking area, across a field adjacent to the USAR Center, to the Alice Independent School District Maintenance Department complex.



Photo 2: Looking southeast from the POV parking area at the southeast corner of the Site and across the adjacent Alice High School Athletic Field.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 3: Looking northeast through the OMS fence at the adjacent Alice High School Athletic Field.



Photo 4: Looking north through the OMS fence, across Houston Street, at the First Community Bank building.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 5: Looking west-southwest from the center of the Site, across Stadium Road, at the Alice High School Stadium.




Photo 6: Pole with one transformer located on the west-central Site property boundary.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 7: Pole with three transformers located on the northwest Site property boundary.



Photo 8: View of the front (west side) of the Administration Building. Photo was taken looking northeast from the POV parking area entrance. The bank adjacent to the property (north) can be seen in the background left.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 9: View of the back (east side) of the Administration Building, looking southwest from the fenced OMS Building area. The fence in the foreground surrounds the OMS building, container boxes, flammable materials storage sheds, vehicle washing station, and MEP area. The Alice High School Stadium adjacent to the property (west) can be seen in the background left.



Photo 10: This sand filled drum outside the side door to the Administration Building is designed to be used by soldiers returning from the rifle range. Before a soldier enters the building with a rifle, the muzzle is pointed at the sand in the drum and the trigger pulled to ensure there are no weapons with live rounds in the building. According to USAR personnel, the drum has not been used.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 11: View looking down the Administration Building hallway.



Photo 12: This is a photograph of the weapons vault door. USAR personnel on the Site did not know why there is a radiation hazard placard on the door.

Alice USAR Center
100 South Stadium Road
Alice, TX



Photo 13: View inside the Administration Building's janitor's closet. Household cleaning supplies were observed.



Photo 14: View inside the mechanical room. Most pipe insulation appeared new.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 15: Photograph of the air conditioning condensate discharge pipe. The pipe discharges to the floor drain seen in the center of the photograph. The drain leads to the sanitary sewer.



Photo 16: Looking south from the OMS area to the open areas within the southeast portion of the USAR property.

Alice USAR Center
100 South Stadium Road
Alice, TX



Photo 17: A concrete pad in the southwest corner of the OMS fenced area has a concrete ramp leading over the curb and a bottom drain.



Photo 18: Vehicle wash rack (VWR) with a forklift on it. This is located north of the pad in Photograph 17, and within the OMS fenced area. According to USAR personnel, the pad is not used as a VWR. During the Site visit, the pad appeared in good condition and no signs of a release were observed.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 19: This is the oil-water separator (OWS) associated with the VWR. It is located north of the VWR and immediately east of the two flammable materials storage sheds (background). During the Site visit, the OWS was empty and no liquid, oily residue, or sludge was observed in it. Also, no signs of a release were observed.



Photo 20: Looking west at the two flammable materials storage sheds located within the OMS fenced area. The OWS can be seen in front of the sheds. There were no signs of a release from these two sheds. Photograph 21 provides an inventory of the contents.

**Alice USAR Center
100 South Stadium Road
Alice, TX**

Office DEPOT.

INVENTORY OF POL ITEMS.

NAME	SIZE	QTY	QTY/USED
1.Coastal antifreeze/coolant	1Gal	2	
2.Zerex antifreeze/coolant	1Gal	1	
3.Detergent,general purpose	16floz	3	
4.Brake fluid	12floz	1	
5.Silcone spray	10oz	1	
6.WD-40	8oz	1	
7.Ink,marking stencil,opaque (black)	10.5oz	1	
8.Hand cleaner gel	1Gal	2	
9.Handcleaneer waterless cream form	1lb	26	
10.Lubricating oil weapons	5Gal	1	
11.Hydraulic fluid auto transmission	1Qts	26	
12.Hydraulic fluid auto transmission	1Qts	2	
13.Superflo motor oil (30wt)	1Qts	10	
14.Superflo auto transmission fluid	1Qts	8	
15.Dexron iie/mercon auto transmission fluid	1Qts	1	
16.B.B grease grease,auto&artillery	1Qts	1	
17.Lube oil engine	5Gal	1	
18.10WT	5Gal	1	
19.Lubricating oil, engine (10W)	5Gal	1	
20.Lubricating oil,gear (80W-90)	5Gal	1	
21.WD40/spray bottle (HALF FULL)	5Gal	1	
22. Black spray paint	18-POL	2-CANS	

SFC RICHARDSON 887TH QM CO
MOTOR SERGEANT

Photo 21: Petroleum, oil, and lubricant (POL) storage list for the two flammable materials storage sheds.



Photo 22: Looking north at four container boxes stored within the OMS fenced area. The boxes were being used for inert storage such as furniture, electronic equipment, field equipment, etc.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 23: Looking west at the same container boxes shown in Photo 22.



Photo 24: This is a fifth container box located in the northeast corner of the fenced OMS area. This container box is also used for inert storage. There are two empty mobile storage tanks on the asphalt pavement next to the container box. Details of the tanks are given in the next photograph (Photograph 25) caption.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 25: One of two empty 600-gallon, single-walled, steel, mobile diesel tanks. Part of the second tank can be seen to the right. These tanks are set on a flatbed trailer when in use. According to USAR personnel, the tanks have not been used since 2003 when the unit mobilized to Kuwait. Fuel for military vehicles is purchased at a local gas station and is not stored on the Site.



Photo 26: In addition to the forklift on the VWR, there were five military vehicles parked along the eastern fence line. All vehicles had oil drip pans positioned beneath them. Minor staining was observed on the asphalt pavement as shown in this photograph.

**Alice USAR Center
100 South Stadium Road
Alice, TX**



Photo 27: View of the fenced-in OMS area looking east-northeast from the western property line. The OMS is the largest building and can be seen in the upper center of the photograph. A concrete pad from a former grease rack has a vehicle parked on it in front of the OMS.



Photo 28: View of the front (south side) of the OMS. The OMS has not been used for vehicle maintenance since 2002 according to USAR personnel. During the Site visit, no evidence of ongoing maintenance activities was observed and the main room inside the OMS was a weight room for physical training. Part of the concrete pad remaining from the former grease rack can be seen in the extreme left of the photograph.

Alice USAR Center
100 South Stadium Road
Alice, TX



Photo 29: Shower located in the OMS.



Photo 30: Storage area in the OMS. This set of shelving is used for parts and tools; no chemicals were stored here.

Alice USAR Center
100 South Stadium Road
Alice, TX



Photo 31: This storage room inside the OMS was used to store small quantities of chemicals and parts such as cleaning fluid, antifreeze, and oil filters.