

Appendix B
Site Reconnaissance Photographs

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 1: Looking southwest at the front of the Training Building.



Photo 2: Looking northeast toward the east side of the Training Building and Drill Hall.

Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas



Photo 3: View inside a mechanical room within the Training Building.



Photo 4: View inside of the Drill Hall of the Training Building. The kitchen area is behind the van in the photograph.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 5: Typical view of an office in the Training Building.



Photo 6: View of the hazardous materials storage building in the MEP area.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 7: View of northeast side of the MEP area showing military vehicles along the southeast boundary and 20-foot steel transport containers along the southwest boundary.



Photo 8: Looking northwest along the southwest boundary of the USAR Center, Church Street is visible along with the entrance to the POV parking area in the right background.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 9: Looking southwest from the northwest end of the MEP area are military vehicles and two pole mounted electrical transformers at the southwest boundary of the Site.



Photo 10: Looking east from the northeast corner of the MEP area, one of two dumpsters on the Site is shown along with Blackburn Street in the background.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 11: Looking northwest across the POV parking lot, the second of two dumpsters on the Site is visible.



Photo 12: Looking northeast from the northwest corner of the MEP area, the Drill Hall in the Training Building and pole mounted transformers are visible in the background along with 40-foot storage containers to the right.

Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas



Photo 13: Looking southeast at the vehicle wash rack. The red building extension to the left houses the wash water recirculating system.



Photo 14: An old OWS on the Site now is used as a sediment trap.

Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas



Photo 15: Looking at the vehicle wash rack from the southwest, the slotted floor drain that drains wash water is visible.



Photo 16: Looking southeast along the southwest side of the OMS, the parts washer is visible inside the bay door.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 17: Looking northeast along the northwest side of the OMS are two empty fuel pods.



Photo 18: Overpack drums are stored on a pallet on the southwest side of the hazardous materials storage building.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 19: Spill containment for drums is located on the northwest side of the hazardous materials storage building.



Photo 20: View inside of the hazardous materials storage building which has a catchment basin below the floor.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 21: Another view of storage inside the hazardous materials storage building.



Photo 22: View of minor spillage inside the hazardous materials storage building.

Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas



Photo 23: Waste materials waiting transfer to a disposal facility.



Photo 24: Inside view of a paint locker in the OMS.

Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas



Photo 25: Inside view of the OMS across the top of equipment storage rooms toward air compressor mounted above the paint storage closet.



Photo 26: Another inside view of the OMS.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 27: Materials used for vehicle maintenance are stored in the hazardous materials storage building.



Photo 28: Military trucks are parked in the MEP area with drip pans under the engines of the parked vehicles.

Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas



Photo 29: Drip pan beneath engine of parked truck. Note staining on gravel around drip pan.



Photo 30: Former mechanics pit located in the north bay of the OMS. The former pit is capped with concrete at the level of the surrounding OMS shop floor.

Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas



Photo 31: Miscellaneous equipment is stored between the vehicle wash rack and the OMS.



Photo 32: The OWS and water recirculating system for the vehicle wash rack.

Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas



Photo 33: A 500-gallon water storage tank is part of the OWS.



Photo 34: Oil staining was visible in the oil skimmer of the OWS.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 35: View of flammable materials storage cabinet inside the OMS.



Photo 36: Looking east across Blackburn Street toward the adjoining storage unit property.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 37: Looking northwest across Church Avenue from the USAR Center toward First Christian Church.



Photo 38: Looking northeast across Duniven Circle toward the adjoining office building property.

**Blucher S. Tharp Memorial USAR Center
2801 Duniven Circle
Amarillo, Texas**



Photo 39: Looking northwest across Blackburn Street toward Pancake Station restaurant (USAR Center is to the right in the photograph).