

Appendix B
Site Reconnaissance Photos

**Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas**



Photo 1: View of front of Jules E. Muchert USAR Center from East Northwest Highway.



Photo 2: View of west side of USAR Center and west POV.

**Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas**



Photo 3: View of west side of OMS and vehicle staging area. A residential area abuts the Site to the north in the background.



Photo 4: MEP area west of OMS. TU Electric substation in background abuts the west side of the Site.

Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas



Photo 5: Floor drain for air conditioning condensate. This drain is typical of other condensate floor drains at the facility.




Photo 6: Floor drain in first floor female restroom. This floor drain is typical of other drains in restrooms at the facility.

Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas



Photo 7: Vehicle wash rack. Hose bib in foreground and new concrete associated with post 1997 awning. View to facing south.



Photo 8: Oil-water separator that processes wash rack water. Separator is located east of the wash rack, next to the Site boundary fence.

**Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas**



Photo 9: OMS with hazmat shed (far left) and general storage shed (background). A spill kit can be seen in front of the hazmat shed.



Photo 10: Front view of the hazmat shed.

Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas



Photo 11: Interior view of the hazmat shed showing empty drums.



Photo 12: Used oil and antifreeze stored in a safety pack on the north side of the hazmat shed.

**Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas**



Photo 13: Storm drain located on the west edge of the POV parking lot. Two such drains divert storm water from the western portion of the Site.



Photo 14: Two storm drains are located in the grassy area near the southeast corner of the property. The pink building in the background is the East Lake Veterinary Hospital.

Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas



Photo 15: Hazmat locker in the OMS. The locker contained consumer quantities of various vehicle POLs and spray paint.



Photo 16: Indoor firing range. The range was decommissioned in 1997 and the metal bullet stops were removed.

**Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas**



Photo 17: Indoor firing range. The firing range is now used exclusively for storage.



Photo 18: View of northern boundary of the Site. Fences on the right side of photo (north) are the rear of single family residences.

**Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas**



Photo 19: An apartment complex abuts the northeast corner of the USAR Center. The vacant lot in the foreground is directly across Thurgood Lane from the OMS.



Photo 20: White Rock Park abuts the northwest one-fourth of the USAR Center. The fence post in the foreground is the northwest corner of the Site.

**Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas**



Photo 21: TU Electric's Lake Highland Substation abuts the southern three-fourths of the west boundary of the Site. The fence on the far right of the photo is the USAR Center.



Photo 22: East Northwest Highway viewed from the southeast corner of the Site. Trees on the left side of the photograph are in the yards of single family residences.

**Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas**



Photo 23: A shopping center is across Thurgood Lane to the east with the Disabled Veterans and Knights of Columbus buildings. Goodyear (UST Database – Table 4) is in the background.



Photo 24: East Lake Veterinary Hospital located across Thurgood Lane from the southeast corner of the Site.

**Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas**



Photo 25: Three pole-mounted transformers located east of the Training Building. The lighter colored transformer is believed to have replaced the leaking transformer discussed in Section 6.6.



Photo 26: Two pole-mounted transformers located east of the OMS and just outside the Site boundary fence.

Jules E. Muchert USAR Center
10031 E. Northwest Highway
Dallas, Texas



Photo 27: A sign on the storage cage in the assembly hall indicates a radioactive source.