

Appendix B
Site Reconnaissance Photos

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 1: View of Houston #3 USAR Center looking to the southwest.



Photo 2: A weight scale is along the north side of the facility building, looking to the east.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 3: View of a storm water catch basin in the driveway along the north side of the property.



Photo 4: View of north MEP area, looking to the southeast.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 5: Vehicles parked in the north MEP area have had all maintenance or repair work completed.



Photo 6: View of the storage cages, covered secondary containment pallets, and tire pallets along the wash rack.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 7: View of drains in the wash rack area, connected to the OWS (looking to the south).



Photo 8: View of SAGE oil-vacuum system, located under the wash rack roof. Secondary containment surrounds the system. (Picture from EBS [ECCL, 2005])

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 9: View of the covered secondary containment pallets located along the wash rack.



Photo 10: View of storage cages along the wash rack, used for cylinder storage.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 11: View of two work bays in the AMSA shop area, looking to the south.



Photo 12: View of OWS manhole covers, and work bays in the AMSA shop area, looking to the north.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 13: View of break room in the AMSA shop. Note floor tiles, which replaced the previous floor tile that tested positive for asbestos.



Photo 14: View inside a work bay of the AMSA shop. Note floor drain reportedly connected to the OWS, storage cage, and parts washer shown on the left side.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 15: View of gas heater located in a work bay within the AMSA shop.



Photo 16: View of a parts washer and Oberg oil filter crusher located in a work bay of the AMSA shop.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 17: A FloJet mobile washer was stored on the floor within the AMSA shop.



Photo 18: View inside a work bay of the AMSA shop, looking to the south. Note second floor storage shown in the upper right of the photograph.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 19: View of second floor storage in the AMSA shop.



Photo 20: View of cage storage located in the cargo bay at the AMSA shop.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 21: View of office area inside the AMSA shop.



Photo 22: View of gas heater within an office in the AMSA shop.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 23: View of capped drain in an office in the AMSA shop.



Photo 24: View of the southern MEP area located at the AMSA shop, looking to the east. Note pole-mounted transformers in the background (left) of the photograph.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 25: View of pole-mounted transformers located between the office area and AMSA shop.



Photo 26: View of loading dock located at the southern end of the facility building.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 27: View of catch basin/drain located at the loading dock. Note electrical line and piping running to the drain.



Photo 28: View of cage storage located at the southern end of the office area of the facility building.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 29: View of compressor located adjacent to the loading dock area on the southern end of the office area of the facility building.



Photo 30: View of four hazardous/flammable materials storage sheds located in the paved southwest corner of the AMSA shop area, looking to the southwest.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 31: View inside a hazardous/flammable materials storage shed.



Photo 32: Another view inside a hazardous/flammable materials storage shed.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 33: A hazardous/flammable materials storage shed storing drums with grounding wires.



Photo 34: View of the unpaved MEP area, looking to the southeast.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 35: View of unpaved MEP area, looking west. Note large ruts caused by vehicles and wet conditions at the Site.



Photo 36: View of catch basin with concrete pad, located in the unpaved MEP area. There are four catch basins located in this area.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 37: View of hazardous/flammable materials storage sheds and covered secondary containment pallets on a concrete pad in the MEP area.



Photo 38: View inside another hazardous/flammable materials storage shed.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 39: More containers inside a hazardous/flammable materials storage shed.



Photo 40: Containers inside a small hazardous/flammable materials storage shed.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 41: View of spill houses/pallets located in the MEP area.



Photo 42: View of container boxes in the unpaved MEP area. These structures are used for storage and deployment.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 43: View of vehicles and tankers located in the unpaved MEP area.



Photo 44: View of Houston #2 USAR Center located to the north of the Site.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 45: View of Iron Mountain (records management) located to the east of the Site.



Photo 46: View of West Little York Road/Fisher Road and commercial businesses beyond, located to the south of the Site.

Houston #3 USAR Center
6903 Perimeter Park Drive
Houston, Texas



Photo 47: View of West Little York Road and commercial businesses beyond, to the south of the Site.



Photo 48: View of new warehouses to the west of the Site. A railroad line is visible in the foreground and the fence line between the Site and the warehouses is shown to the right.