

Appendix B
Site Reconnaissance Photographs

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 1: The property adjacent to the north side of the Site, across 9th Street, is a residence.



Photo 2: View from the Site to the northeast.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 3: View from the Site to the northwest.



Photo 4: Adjacent properties west of the Site across West Wenonah Boulevard are residential.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 5: Adjacent properties east of the Site across East Wenonah Boulevard are residential.



Photo 6: Adjacent properties south of the Site across 10th Street are residential.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 7: Westerly Drive south of the Site and south of 10th Street is a residential street.



Photo 8: North side exterior of the Training Building.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 9: Three pole mounted transformers on the north side of Training Building near the property line.



Photo 10: West side exterior of the Training Building.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 11: South side exterior of the Training Building.



Photo 12: East side exterior of the Training Building where there is a grease trap from the former kitchen.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 13: Wash pad on east side of the Training Building.



Photo 14: Training building hallway.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 15: Training building classroom.



Photo 16: The Training Building has several offices.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 17: The supply room in the Training Building was a former firing range.



Photo 18: The lead drop from the former firing range was filled with concrete.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 19: Supply room locker with radioactive label.



Photo 20: Equipment in the locker has a fluorescent dial with low-level radioactivity.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 21: Drill hall in the Training Building.



Photo 22: Breakroom within the Training Building.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 23: Drain in breakroom for condensate.



Photo 24: Former kitchen area converted into office space.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 25: Chemicals were stored on wood shelving inside the janitor closet.



Photo 26: Boiler room equipment.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 27: Boiler room drain.



Photo 28: Chiller inside enclosure on west side of Training Building.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 29: Drum of ethylene glycol outside of chiller enclosure.



Photo 30: Dumpster between the Training and OMS buildings.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 31: OMS building exterior east side.




Photo 32: OMS building exterior south side.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 33: Storage container by the OMS building on a pad for a former grease rack.



Photo 34: A vehicle wash rack on the east side of the OMS building has an oil/water separator.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 35: Close-up of the oil/water separator for the vehicle wash rack.



Photo 36: OMS exterior north side.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 37: OMS exterior west side.



Photo 38: Pipe near northwest corner of the OMS building.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 39: MEP area, north of the OMS building.



Photo 40: OMS secondary storage containers in MEP area.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 41: Fuel bowsers and parts washer fluid in secondary containment.



Photo 42: Used oil in drum in secondary containment.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 43: Flammable storage cabinet in MEP area.



Photo 44: The interior of the flammable storage cabinet is empty and it was reportedly never used.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 45: Bay inside the OMS building.



Photo 46: Parts washer inside the OMS building.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 47: Spent absorbent from OMS cleanup.



Photo 48: Spill kits inside OMS building.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 49: Test equipment inside the OMS building.



Photo 50: Oil crusher inside the OMS building.

Wichita Falls USAR Center, TX
3315 9th Street
Wichita Falls, TX



Photo 51: OMS building office.