

# **APPENDIX B**

## **SITE RECONNAISSANCE PHOTOGRAPHS**



**Photograph 1. View of the main entrance to the Leisy Hall from the POV area, looking southwest**



**Photograph 2. Eastern exterior of the Leisy Hall, looking southwest**



**Photograph 3. View of Leisy Hall from the south, looking north**



**Photograph 4. View of the 4,000 gallon capacity diesel fuel AST (pictured left) and associated diesel generator (pictured right) situated south of Leisy Hall**



**Photograph 5. Grease trap access located south of the Leisy Hall**



**Photograph 6. View of freight elevator access**



**Photograph 7. Oil/water separator situated in the POV area northeast of Leisy Hall**



**Photograph 8. Typical office area in Leisy Hall**



**Photograph 9. Typical hallway in Leisy Hall**



**Photograph 10. Training room interior**



**Photograph 11. Drill hall interior**



**Photograph 12. View of the AMSA 79 Building**



**Photograph 13. South and eastern exterior of the AMSA 79 Building**



**Photograph 14. Western exterior of the AMSA 79 Building**



**Photograph 15. Hazmat storage shed situated on the western portion of the AMSA 79 Site**



**Photograph 16. Used oil 500-gallon capacity AST located inside of the hazmat storage shed**



**Photograph 17. POL storage in the hazmat storage shed**



**Photograph 18. Interior view of the hazmat storage shed utilized for corrosives and a radioactive storage cabinet**



**Photograph 19. Hazardous material storage structure situated on the southeast portion of the AMSA 79 Site**



**Photograph 20. View of the former hazardous materials storage building (pictured left), overhang, and former UST location (right of overhang area)**



**Photograph 21. Vehicle wash rack area north of AMSA 79**



**Photograph 22. Oil/water separator situated downgradient of the AMSA 79 wash rack area**



**Photograph 23. Oil/water separator situated north and outside of the AMSA 79 fence area**



**Photograph 24. View of concrete pad associated with a former fuel island and UST area situated on the northwest portion of the AMSA 79 Site**



**Photograph 25. View of the interior vehicle maintenance bay areas inside of the AMSA 79**



**Photograph 26. Oil and grease storage in the AMSA 79**



**Photograph 27. Solvent sink, filter crusher, 55-gallon drum containing crushed oil filters and a flammable storage cabinet**



**Photograph 28. View of flammable storage cabinets**



**Photograph 29. View of approximately 200-gallon capacity hydraulic oil AST utilized for the vehicle lift**



**Photograph 30. View of the vehicle lift**



**Photograph 31. Acetylene and oxygen canister storage in the AMSA 79 Building**



**Photograph 32. Diesel powered forklift**



**Photograph 33. Battery charging room**



**Photograph 34. View of the break room in the AMSA 79 Building**



**Photograph 35. View of Harvey Hall, an adjoining USARC installation situated south of Leisy Hall and southwest of the AMSA 79**



**Photograph 36. View of the Fort Lawton Army Reserve Center (FLARC) OMS Building on the adjoining property to the north of Leisy Hall and to the northeast of AMSA 79**



**Photograph 37. View of the FLARC administration building situated west of AMSA 79**



**Photograph 38. View of residential area situated east of Leisy Hall, looking south along 36<sup>th</sup> Avenue West**