

Appendix B
Site Reconnaissance Photographs

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 1: Looking northwest across the privately owned vehicle (POV) parking lot at the exterior of Building 1. The rollup door reportedly has lead-based paint (LBP). Some small oil stains are in the POV lot.



Photo 2: Interior of the Building 1 Drill Hall with view of the rollup door that may have LBP from the inside. Condition of the paint on the door is poor.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 3: Interior of the Building 1 Drill Hall with a view of a door to the exterior. This door has also been reported to have LBP.



Photo 4: Building 1 Drill Hall assembly area, looking toward the northwest corner where the printing press previously on Site was operated for a time. No staining or marks on the floor were noted.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 5: Building 1 Drill Hall air conditioning unit reportedly had some asbestos containing material which was abated.



Photo 6: Building 1 warehouse storage area, first floor.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 7: Building 1 warehouse storage area, second floor.



Photo 8: Radioactive items storage area in Building 1 warehouse, second floor.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 9: Building 1 janitor closet contained small quantities of cleaning products. No floor drain was present in this closet.



Photo 10: Computers in Building 1 supply room.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 11: Air conditioner and heater in Building 1 supply room. The air conditioner is listed in the ozone depleting chemicals survey as containing R-22 refrigerant.



Photo 12: Building 1 mechanical room boiler.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 13: Building 1 mechanical room and view of one of the four floor drains in the room.



Photo 14: Building 1 mechanical room drain.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 15: Building 1 mechanical room drain.



Photo 16: Building 1 mechanical room floor with water stains.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 17: Building 1 mechanical room shelving with stored paints.



Photo 18: Chiller outside of Building 1.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 19: Gazebo and wooded area on north side of the Site. Wooded parkland is north and east of the Site.



Photo 20: Building 2 cubicle offices.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 21: Building 2 hallway.



Photo 22: Roofed vehicle wash rack (VWR) with curbing and sump. VWR has not been used in recent years.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 23: Oil water separator south of VWR.



Photo 24: Organizational maintenance shop (OMS) interior.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 25: OMS interior with flammable materials cabinet and parts washer.



Photo 26: OMS floor with absorbent on oil spills.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 27: Room in OMS on east side of the garage bay has electronic equipment for calibrating the biodetection unit equipment.



Photo 28: Hazardous material unit south of the OMS has a drum of oil and a drum of antifreeze.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 29: Hazardous material unit also has smaller quantities of vehicle maintenance chemicals.



Photo 30: A second hazardous material unit contains tools, equipment, and a 5-gallon can of fuel.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 31: Drain outside of hazardous material units may discharge to the sanitary sewer, according to USAR Center personnel. One drum of used oil was staged outside the hazardous material units. The raised concrete was the location of a grease rack formerly at the Site.



Photo 32: Storage cage for pressurized gas cylinders.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 33: Portable storage units were south and north of the OMS.



Photo 34: The interior of the portable storage units held equipment, tools, and other items. Only some of the units were accessible; some storage unit interiors were not viewed.

Leroy R. Pond USAR Center
1616 N. Woolsey Street,
Fayetteville, AR



Photo 35: Many of the military vehicles parked on the north side of the OMS, in the military equipment parking (MEP) area, had drip pans under them to catch oil from leaks.



Photo 36: Solid waste from the USAR Center is placed in this container and picked up by the City of Fayetteville.