

APPENDIX B
SITE RECONNAISSANCE PHOTOGRAPHS



Photograph 1. View of the main entrance (southern exterior) to Sears Hall



Photograph 2. Eastern exterior of Sears Hall



Photograph 3. Western exterior of Sears Hall



Photograph 4. Northern exterior of Sears Hall



Photograph 5. View of air conditioning unit and gas pipes located on the exterior of Sears Hall



Photograph 6. View of the exterior stairwell leading to the boiler room in Sears Hall



Photograph 7. View of the drill hall portion of Sears Hall, looking west



Photograph 8. View of a classroom formerly occupied by an indoor firing range in Sears Hall



Photograph 9. View of the boiler located in Sears Hall



Photograph 10. View of the overflow tank associated with the boiler



Photograph 11. Drill hall interior



Photograph 12. Typical hallway in Sears Hall



Photograph 13. Conference room located in Sears Hall



Photograph 14. Typical office area in Sears Hall



Photograph 15. Southern exterior of the OMS Building



Photograph 16. Eastern exterior of the OMS Building



Photograph 17. View of a typical maintenance bay in the OMS Building



Photograph 18. View of the solvent sink, portable container utilized for used oil, and oil filter crusher



Photograph 19. View of flammable storage cabinets in the OMS Building



Photograph 20. View of the interior of the flammable storage cabinet



Photograph 21. View of the portable Hazmat Storage Shed and Hazmat Storage Structure situated east of the OMS Building



Photograph 22. View of drum storage within the Hazmat Storage Structure



Photograph 23. View of 5-gallon containers and drums located within the Hazmat Storage Structure



Photograph 24. View of the MEP area



Photograph 25. View of a storm drain situated in the MEP area of the site



Photograph 26. View of a storm drain located in an unpaved area east of Sears Hall



Photograph 27. View of the eastern exterior of the Storage Building



Photograph 28. Southern exterior of the Storage Building



Photograph 29. View of the interior of the Storage Building



Photograph 30. View of Multnomah Boulevard looking east from the Site



Photograph 31. View of the adjoining residential area situated west of the Site