

Appendix B
Site Reconnaissance Photos

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 1: Facing East – The front of the Boswell Street USAR Center.



Photo 2: Facing Southeast – The front of the Boswell Street USAR Center.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 3: Facing Northeast – The front of the Boswell Street USAR Center.



Photo 4: The adjacent property to the west of the USAR Center is the City Public Services Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 5: The adjacent property to the north of the USAR Center is a church.



Photo 6: The adjacent property to the south of USAR Center is a commercial business.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 7: The adjacent property to the east of the USAR Center is a commercial business.



Photo 8: Another view of the adjacent property to the east of the USAR Center.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 9: Grease trap on the north side of the Training Building.



Photo 10: Can washing area on the north side of the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 11: Pole Mounted Transformers on the north side of the Training Building.



Photo 12: A Vehicle Wash Rack is west of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 13: Military Vehicle Parking (note drip pans under vehicle) area is southwest of the OMS.



Photo 14: POL storage and a filter crusher are within the OMS.

Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas



Photo 15: A parts washer is in the OMS.



Photo 16: An oil/water separator (OWS) unit is west of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 17: A water recycling system is associated with the OWS.



Photo 18: MEP area has hazardous material storage lockers and PMTs in the background; area is southwest of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 19: Storm drain in the area south of the OMS Building.



Photo 20: Hazardous materials storage locker is south of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 21: Exterior view of a hazardous materials storage locker south of the OMS.



Photo 22: A drum storage pad is south of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 23: Another view of the drum storage pad south of the OMS.



Photo 24: Container storage boxes are stored southeast of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 25: Container storage boxes are also stored southeast of the OMS.



Photo 26: Discarded concrete debris is on the eastern portion of the Site.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 27: Discarded fencing/debris is also on the eastern portion of the Site.



Photo 28: Container storage boxes along the fence southeast of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 29: Facing north looking at the east perimeter fence.



Photo 30: Facing east looking at the MEP area.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 31: Facing east in the MEP area, the VWR is visible in the background.



Photo 32: West side of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 33: Flammable storage lockers along the south side of the OMS.



Photo 34: Drainage grate associated with trench drains on the south end of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 35: Interior of OMS showing the painted ceiling.



Photo 36: Flammable storage locker on the west side of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 37: Another flammable storage locker on the west side of the OMS.



Photo 38: View of an additional flammable storage locker on the west side of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 39: View of the interior of the OMS.



Photo 40: Floor drain in the OMS storage area.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 41: Floor drain in the OMS janitorial closet.



Photo 42: Floor drain in an OMS bathroom.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 43: Typical office area within the OMS.



Photo 44: Compressor room on the north side of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 45: VWR on the west side of the OMS.



Photo 46: Facing south shows the OMS bays (note trench drains) on the west side of the OMS.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 47: Facing southeast looking at the MEP area south of the OMS.



Photo 48: View of the interior of the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 49: The air handling system in the Training Building is shown.



Photo 50: A floor drain in the kitchen of the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 51: The hot water heater in the kitchen of the Training Building.



Photo 52: A floor drain in the kitchen of the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 53: Another floor drain in the kitchen of the Training Building.



Photo 54: The main assembly hall in the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 55: Typical storage area within the Training Building.



Photo 56: Typical storage areas within the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 57: NBC room in the Training Building (note the radiation storage area).



Photo 58: NBC Room in the Training Building (note the radiation storage area).

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 59: The mechanical room in the Training Building.



Photo 60: A floor drain in the mechanical room of the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 61: Another floor drain in the mechanical room of the Training Building.



Photo 62: Fluorescent light bulbs in the mechanical room of the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 63: Another floor drain in the mechanical room of the Training Building.



Photo 64: Another floor drain in the mechanical room of the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 65: Another floor drain in the mechanical room of the Training Building.



Photo 66: A pipe chase within the mechanical room of the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 67: The weapons cleaning station in the Training Building.



Photo 68: Air handling equipment in the arms room of the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 69: The small arms vault within the Training Building.



Photo 70: The administrative office in the Training Building.

**Boswell Street USAR Center
423 Boswell Street
San Antonio, Texas**



Photo 71: The 2nd floor hallway of the Training Building.



Photo 72: The classified storage area within the Training Building.