

**Appendix B**  
**Site Reconnaissance Photos**

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 1:** The Administration Building entrance looking west at the Jonesboro USAR Center (AR022).



**Photo 2:** The front of the Administration Building looking south at the Jonesboro USAR Center. Also, shown is the adjacent retail property to the south.

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 3:** Military equipment parking (MEP) as viewed from the southwest corner of the MEP looking southeast at the OMS and vehicle wash rack.



**Photo 4:** MEP as viewed from the southwest corner of the MEP and looking east at the Administration Building and vehicle wash rack.

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 5:** Privately owned vehicle parking, viewed from the north side of the Administration Building looking west. Also, the undeveloped lot to the west of the Site is visible.



**Photo 6:** Drill hall in the northeast corner of the Administration Building.

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 7:** Another view of the drill hall in the northeast corner of the Administration Building.



**Photo 8:** Storage cabinet with cleaning supplies in a janitor's closet in the Administration Building.

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 9:** Mechanical room in the southeast corner of the Administration Building.



**Photo 10:** Electrical transformers on a utility pole on the west side of the Administration Building. (Photo from the 2005 EBS report.)

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 11:** OMS maintenance bay, viewed looking to the southeast.



**Photo 12:** Storage inside the OMS maintenance bay.

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 13:** Vehicle wash rack and an oil/water separator in the south central portion of the property, viewed looking south.



**Photo 14:** Vehicle wash rack drain which connects to an oil/water separator.

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 15:** The top of the oil/water separator for the vehicle wash rack.



**Photo 16:** A parts washer was stored inside the OMS maintenance bay.

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 17:** Parts washer with spent solvents in the OMS maintenance bay.



**Photo 18:** Hazardous material flammable storage cabinets in the OMS maintenance building.

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 19:** Materials within the hazardous material flammable storage cabinets in OMS maintenance building.



**Photo 20:** Another view of materials within the hazardous material flammable storage cabinet in the OMS maintenance building.

**Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas**



**Photo 21:** Looking north from the privately owned vehicle parking area on the north end of the Site is a vacant lot and a restaurant on the northern adjacent property.



**Photo 22:** Looking west from the southeast corner of the Site, a grass covered drainage way borders the southern portion of the facility.

Jonesboro USAR Center  
1001 S. Caraway Road  
Jonesboro, Arkansas



**Photo 23:** Looking southeast from the east boundary of the Site are retail businesses on the adjoining property.



**Photo 24:** Looking northeast from the east boundary of the Site are retail businesses on the adjoining property.