



Photograph 1. POV area on southwest side of USARC administration building



Photograph 2. POV area on northeast side of administration building



Photograph 3. Asphalt MEP area with vehicles and administration building



Photograph 4. Asphalt MEP area with vehicles and administration building



Photograph 5. Asphalt MEP area with vehicles



Photograph 6. Fenced equipment entrance in northeast corner of property



Photograph 7. Landscaping on east side of administration building



Photograph 8. Southeast (front) view of administration building



Photograph 9. Southeast view of administration building and lawn



Photograph 10. Southwest corner of administration building



Photograph 11. Northeast side of administration building



Photograph 12. Northwest exterior of administration building



Photograph 13. Exterior of drill hall



Photograph 14. Front entry of administration building



Photograph 15. Typical hallway in administration building



Photograph 16. Typical classroom in administration building



Photograph 17. Typical office setup in administration building



Photograph 18. Former firing range, now weight room



Photograph 19. Interior of drill hall



Photograph 20. Mezzanine area behind drill hall with company equipment



Photograph 21. Company equipment cage near drill hall



Photograph 22. Kitchen area



Photograph 23. Boiler in mechanical room



Photograph 24. Sump in corner behind boiler piping



Photograph 25. Air conditioner units next to mechanical room door



Photograph 26. South side of OMS



Photograph 27. OMS exterior looking west



Photograph 28. OMS exterior looking south



Photograph 29. New part of OMS interior



Photograph 30. Old part of OMS interior



Photograph 31. Used oil AST



Photograph 32. Oil filter crusher adjacent and connected to used oil AST



Photograph 33. Electric air compressor in OMS



Photograph 34. Drum room on with exterior door on north side of OMS



Photograph 35. Hazmat sheds



Photograph 36. CONEX containers on northwest corner of property



Photograph 37. Empty 5 gallon fuel cans and portable generator in hazmat shed



Photograph 38. Cabinet in hazmat shed with aerosols and cleaners



Photograph 39. Empty drums, oxygen and acetylene gas, and empty fire extinguishers



Photograph 40. Oil/water separator adjacent to Chautauqua Boulevard



Photograph 41. Homes along Alaska St. north of USAR Center



Photograph 42. View north along Chautauqua Blvd. USAR Center (left), and homes (right)



Photograph 43. Mt. Olivet Baptist Church administration building southwest of Site



Photograph 44. University Park looking towards USAR Center