

Appendix E
Regulatory Database Search Reports



EDR® Environmental
Data Resources Inc

The EDR Radius Map with GeoCheck®

**Blucher S. Tharp Memorial USARC
2801 Duniven Circle
Amarillo, TX 79109**

Inquiry Number: 1715338.2s

July 14, 2006

The Standard in Environmental Risk Management Information

440 Wheelers Farms Road
Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Executive Summary	ES1
Overview Map	2
Detail Map	3
Map Findings Summary	4
Map Findings	6
Orphan Summary	139
Government Records Searched/Data Currency Tracking	GR-1
 <u>GEOCHECK ADDENDUM</u>	
Physical Setting Source Addendum	A-1
Physical Setting Source Summary	A-2
Physical Setting Source Map	A-7
Physical Setting Source Map Findings	A-8
Physical Setting Source Records Searched	A-30

Thank you for your business.
 Please contact EDR at 1-800-352-0050
 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2006 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

2801 DUNIVEN CIRCLE
AMARILLO, TX 79109

COORDINATES

Latitude (North): 35.190100 - 35° 11' 24.4"
Longitude (West): 101.870600 - 101° 52' 14.2"
Universal Transverse Mercator: Zone 14
UTM X (Meters): 238617.2
UTM Y (Meters): 3897702.0
Elevation: 3612 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 35101-B8 AMARILLO WEST, TX
Most Recent Revision: 1973

East Map: 35101-B7 AMARILLO EAST, TX
Most Recent Revision: 1973

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following government records. For more information on this property see page 6 of the attached EDR Radius Map report:

<u>Site</u>	<u>Database(s)</u>	<u>EPA ID</u>
THARP MEMORIAL US ARMY RESERVE CE 2801 DUNIVEN CIR AMARILLO, TX 79109	UST	N/A

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

FEDERAL RECORDS

NPL..... National Priority List

EXECUTIVE SUMMARY

Proposed NPL	Proposed National Priority List Sites
Delisted NPL	National Priority List Deletions
NPL RECOVERY	Federal Superfund Liens
CERCLIS	Comprehensive Environmental Response, Compensation, and Liability Information System
CERC-NFRAP	CERCLIS No Further Remedial Action Planned
CORRACTS	Corrective Action Report
RCRA-TSDF	Resource Conservation and Recovery Act Information
RCRA-LQG	Resource Conservation and Recovery Act Information
ERNS	Emergency Response Notification System
HMIRS	Hazardous Materials Information Reporting System
US ENG CONTROLS	Engineering Controls Sites List
US INST CONTROL	Sites with Institutional Controls
DOD	Department of Defense Sites
FUDS	Formerly Used Defense Sites
US BROWNFIELDS	A Listing of Brownfields Sites
CONSENT	Superfund (CERCLA) Consent Decrees
ROD	Records Of Decision
UMTRA	Uranium Mill Tailings Sites
ODI	Open Dump Inventory
TRIS	Toxic Chemical Release Inventory System
TSCA	Toxic Substances Control Act
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
SSTS	Section 7 Tracking Systems
ICIS	Integrated Compliance Information System
PADS	PCB Activity Database System
MLTS	Material Licensing Tracking System
MINES	Mines Master Index File
FINDS	Facility Index System/Facility Registry System
RAATS	RCRA Administrative Action Tracking System

STATE AND LOCAL RECORDS

SHWS	State Superfund Registry
IOP	Innocent Owner/Operator Program
SWF/LF	Permitted Solid Waste Facilities
CLI	Closed Landfill Inventory
WasteMgt	Commercial Hazardous & Solid Waste Management Facilities
AST	Petroleum Storage Tank Database
LIENS	Environmental Liens Listing
DEL SHWS	Deleted Superfund Registry Sites
TX Spills	Spills Database
AUL	Sites with Controls
TX VCP	Voluntary Cleanup Program Database
DRYCLEANERS	Drycleaner Registration Database Listing
BROWNFIELDS	Brownfields Site Assessments
ENF	Notice of Violations Listing
Ind. Haz Waste	Industrial & Hazardous Waste Database
ED AQUIF	Edwards Aquifer Permits
AIRS	Current Emission Inventory Data

TRIBAL RECORDS

INDIAN RESERV	Indian Reservations
----------------------	---------------------

EXECUTIVE SUMMARY

INDIAN UST..... USTs on Indian Land

EDR PROPRIETARY RECORDS

Manufactured Gas Plants... EDR Proprietary Manufactured Gas Plants

EDR Historical Auto StationsEDR Proprietary Historic Gas Stations

EDR Historical Cleaners..... EDR Proprietary Historic Dry Cleaners

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

FEDERAL RECORDS

RCRAInfo: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store , treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month Large quantity generators generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

A review of the RCRA-SQG list, as provided by EDR, and dated 03/09/2006 has revealed that there are 8 RCRA-SQG sites within approximately 0.25 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
<i>TUNEUP MASTERS INC</i>	<i>2314 S GEORGIA STREET</i>	<i>1/8 - 1/4E</i>	<i>C13</i>	<i>53</i>
<i>AUTOHAUS OF AMARILLO INC</i>	<i>2401 S GEORGIA</i>	<i>1/8 - 1/4ESE</i>	<i>D14</i>	<i>53</i>
<i>RUSSELL BUICK</i>	<i>2401 GEORGIA</i>	<i>1/8 - 1/4ESE</i>	<i>D16</i>	<i>59</i>
<i>AMARILLO IMPORTS INC</i>	<i>3019 WEST 26TH AVENUE</i>	<i>1/8 - 1/4SSE</i>	<i>E17</i>	<i>60</i>
<i>BILL FRANK AUTOMOTIVE</i>	<i>3006 W 26TH ST</i>	<i>1/8 - 1/4SSE</i>	<i>E20</i>	<i>79</i>
<i>MOSS BODY SHOP</i>	<i>3000 W 26TH ST</i>	<i>1/8 - 1/4SSE</i>	<i>E21</i>	<i>87</i>
<i>GEORGIA ST CLEANERS OF AMERICA</i>	<i>1800 S GEORGIA</i>	<i>1/8 - 1/4ENE</i>	<i>24</i>	<i>109</i>
<u>Lower Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
<i>DON JUDD CAD INC DBA</i>	<i>2501 PARAMOUNT</i>	<i>1/8 - 1/4SW</i>	<i>B8</i>	<i>33</i>

EXECUTIVE SUMMARY

STATE AND LOCAL RECORDS

LTANKS: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Texas Commission on Environmental Quality's Leaking Petroleum Storage Tank Database.

A review of the LTANKS list, as provided by EDR, and dated 05/04/2006 has revealed that there are 7 LTANKS sites within approximately 0.5 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
SMITHSON AUTOMOTIVE CENTER Status Code: PREASSESSMENT/RELEASE DETERMINATION	2821 WOLFLIN AVE	1/8 - 1/4NE	A6	25
TEXACO Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	2001 PARAMOUNT AVE	1/8 - 1/4NNW 7		26
WOLFIN SQUARE 66 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	1901 S GEORGIA	1/8 - 1/4ENE 22		93
TOOT N TOTUM FOOD STORES 81 Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	2601 PARAMOUNT	1/4 - 1/2SW 25		111
DUPRIEST ACURA Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	2525 S GEORGIA	1/4 - 1/2SE 26		119
WESTGATE CAR WASH & LUBE CENTE Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	2608 S GEORGIA	1/4 - 1/2SE 27		126
CULLIGAN WATER COND OF AMARILL Status Code: FINAL CONCURRENCE ISSUED, CASE CLOSED	3801 WOLFLIN AVE	1/4 - 1/2WNW 28		135

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Texas Commission on Environmental Quality's Petroleum Storage Tank Database.

A review of the UST list, as provided by EDR, and dated 04/26/2006 has revealed that there are 15 UST sites within approximately 0.25 miles of the target property.


<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
KMART 4023	2747 DUNIVEN CIR	0 - 1/8 NNW	2	7
PIT STOP	2413 PARAMOUNT	0 - 1/8 WSW	3	9
TASCOSA SHELL	3307 W IH 40	1/8 - 1/4W	4	13
SMITHSON AUTOMOTIVE CENTER	2821 WOLFLIN	1/8 - 1/4NE	A5	18
TEXACO	2001 PARAMOUNT AVE	1/8 - 1/4NNW 7		26
TUNEUP MASTERS STORE 823	2314 S GEORGIA ST	1/8 - 1/4E	C10	44
AFCO 010419	2333 S GEORGIA	1/8 - 1/4E	C11	46
KEY GUARD FUEL	GEORGIA & CIVIC	1/8 - 1/4E	12	49
MCBRAYER-DAY BALDWIN PIANO	2100 GEORGIA	1/8 - 1/4ENE	15	57
WALLY MCCARTHYS AMARILLO IMPOR	3019 W 26TH AVE	1/8 - 1/4SSE	E18	65
TOOT N TOTUM 17	2601 PATTERSON	1/8 - 1/4SSW	19	74
BILL FRANK AUTOMOTIVE	3006 W 26TH ST	1/8 - 1/4SSE E20		79
WOLFIN SQUARE 66	1901 S GEORGIA	1/8 - 1/4ENE 22		93
TASCOSA GULF	3400 W IH 40	1/8 - 1/4NW	23	102
<u>Lower Elevation</u>	<u>Address</u>	<u>Dist / Dir</u>	<u>Map ID</u>	<u>Page</u>
GEN MESSER CADILLAC	2501 PARAMOUNT	1/8 - 1/4SW	B9	38

EXECUTIVE SUMMARY

Due to poor or inadequate address information, the following sites were not mapped:

<u>Site Name</u>	<u>Database(s)</u>
CITY OF AMARILLO TRANSFER STATION	SWF/LF
HIGH PLAINS BAPTIST HOSPITAL SOLID WASTE	SWF/LF
SAFETY KLEEN AMARILLO LIQUID WASTE TRANS	SWF/LF
TEXAS STATE TECHNICAL INSTITUTE LANDFILL	SWF/LF
CUSTOMIZED SERVICE LANDFILL	SWF/LF
CITY OF AMARILLO LANDFILL	SWF/LF
DWAINE C WARNER LANDFILL	SWF/LF
SMOTHERMAN & SHARP LANDFILL	SWF/LF
FORMER ORDNANCE PLANT OF PANTEX	FINDS, RCRA-LQG
1901 S JOHNSON STREET (BNSF AM	HMIRS
34TH AND S MONROE	ERNS
1500 BLOCK OF BROAD ST., SOUTH SIDE OF S	TX Spills
U.S. DOE PANTEX PLANT	Ind. Haz Waste
U.S. DOE PANTEX PLANT	Ind. Haz Waste
U. S. DOE - PANTEX PLANT	ICIS

OVERVIEW MAP - 1715338.2s



-  Target Property
-  Sites at elevations higher than or equal to the target property
-  Sites at elevations lower than the target property
-  Manufactured Gas Plants
-  National Priority List Sites
-  Landfill Sites
-  Dept. Defense Sites


-  Indian Reservations BIA
-  County Boundary
-  Oil & Gas pipelines
-  100-year flood zone
-  500-year flood zone

This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

SITE NAME: Blucher S. Tharp Memorial USARC
 ADDRESS: 2801 Duniven Circle
 Amarillo TX 79109
 LAT/LONG: 35.1901 / 101.8706


CLIENT: ENSAFE
 CONTACT: Phil Hardy
 INQUIRY #: 1715338.2s
 DATE: July 14, 2006

DETAIL MAP - 1715338.2s



- Target Property
- Sites at elevations higher than or equal to the target property
- Sites at elevations lower than the target property
- Manufactured Gas Plants
- Sensitive Receptors
- National Priority List Sites
- Landfill Sites
- Dept. Defense Sites

- Indian Reservations BIA
- Oil & Gas pipelines
- 100-year flood zone
- 500-year flood zone



This report includes Interactive Map Layers to display and/or hide map information. The legend includes only those icons for the default map view.

<p>SITE NAME: Blucher S. Tharp Memorial USARC ADDRESS: 2801 Duniven Circle Amarillo TX 79109 LAT/LONG: 35.1901 / 101.8706</p>	<p>CLIENT: ENSAFE CONTACT: Phil Hardy INQUIRY #: 1715338.2s DATE: July 14, 2006</p>
---	--

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
<u>FEDERAL RECORDS</u>								
NPL		1.000	0	0	0	0	NR	0
Proposed NPL		1.000	0	0	0	0	NR	0
Delisted NPL		1.000	0	0	0	0	NR	0
NPL RECOVERY		TP	NR	NR	NR	NR	NR	0
CERCLIS		0.500	0	0	0	NR	NR	0
CERC-NFRAP		0.500	0	0	0	NR	NR	0
CORRACTS		1.000	0	0	0	0	NR	0
RCRA TSD		0.500	0	0	0	NR	NR	0
RCRA Lg. Quan. Gen.		0.250	0	0	NR	NR	NR	0
RCRA Sm. Quan. Gen.		0.250	0	8	NR	NR	NR	8
ERNS		TP	NR	NR	NR	NR	NR	0
HMIRS		TP	NR	NR	NR	NR	NR	0
US ENG CONTROLS		0.500	0	0	0	NR	NR	0
US INST CONTROL		0.500	0	0	0	NR	NR	0
DOD		1.000	0	0	0	0	NR	0
FUDS		1.000	0	0	0	0	NR	0
US BROWNFIELDS		0.500	0	0	0	NR	NR	0
CONSENT		1.000	0	0	0	0	NR	0
ROD		1.000	0	0	0	0	NR	0
UMTRA		0.500	0	0	0	NR	NR	0
ODI		0.500	0	0	0	NR	NR	0
TRIS		TP	NR	NR	NR	NR	NR	0
TSCA		TP	NR	NR	NR	NR	NR	0
FTTS		TP	NR	NR	NR	NR	NR	0
SSTS		TP	NR	NR	NR	NR	NR	0
ICIS		TP	NR	NR	NR	NR	NR	0
PADS		TP	NR	NR	NR	NR	NR	0
MLTS		TP	NR	NR	NR	NR	NR	0
MINES		0.250	0	0	NR	NR	NR	0
FINDS		TP	NR	NR	NR	NR	NR	0
RAATS		TP	NR	NR	NR	NR	NR	0
<u>STATE AND LOCAL RECORDS</u>								
State Haz. Waste		1.000	0	0	0	0	NR	0
IOP		TP	NR	NR	NR	NR	NR	0
State Landfill		0.500	0	0	0	NR	NR	0
CLI		0.500	0	0	0	NR	NR	0
WasteMgt		TP	NR	NR	NR	NR	NR	0
LTANKS		0.500	0	3	4	NR	NR	7
UST	X	0.250	2	13	NR	NR	NR	15
AST		0.250	0	0	NR	NR	NR	0
LIENS		TP	NR	NR	NR	NR	NR	0
DEL SHWS		1.000	0	0	0	0	NR	0
TX Spills		TP	NR	NR	NR	NR	NR	0
AUL		0.500	0	0	0	NR	NR	0
TX VCP		0.500	0	0	0	NR	NR	0
DRYCLEANERS		0.250	0	0	NR	NR	NR	0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
BROWNFIELDS		0.500	0	0	0	NR	NR	0
ENF	TP		NR	NR	NR	NR	NR	0
Ind. Haz Waste	TP		NR	NR	NR	NR	NR	0
ED AQUIF	TP		NR	NR	NR	NR	NR	0
AIRS	TP		NR	NR	NR	NR	NR	0
<u>TRIBAL RECORDS</u>								
INDIAN RESERV		1.000	0	0	0	0	NR	0
INDIAN UST		0.250	0	0	NR	NR	NR	0
<u>EDR PROPRIETARY RECORDS</u>								
Manufactured Gas Plants		1.000	0	0	0	0	NR	0
EDR Historical Auto Stations	TP		NR	NR	NR	NR	NR	0
EDR Historical Cleaners	TP		NR	NR	NR	NR	NR	0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
 EPA ID Number

1 **THARP MEMORIAL US ARMY RESERVE CENTER**
Target **2801 DUNIVEN CIR**
Property **AMARILLO, TX 79109**

UST **U003166205**
N/A

Actual:
3611 ft.

UST:

Facility ID:	0069229	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	08/31/1987
Tank Emptied:	No	Status Date:	Not reported
Capacity:	400	Unit ID:	00182353
Tank Material of Construction:	Concrete		
Pipe Material of Construction:	Concrete		
Other Materials of Construction:	Not reported		
Tank Status:	In Use		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Not reported		
Compartment Other Substance:	OIL WATER SEPARATOR		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Not reported		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Factory-Built Spill Container/Bucket/Sump		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	Not reported		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	01/21/1997		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		
Signature Title Name:	Not reported		
Signature Type Text:	Not reported		
Certification Submitted Type:	Not reported		
Registration Self-Certification Flag:	Not reported		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Not reported		
Technical standards Self-Certification flag:	Not reported		
UST Delivery Certificate Expiration Date:	Not reported		
Compartment letter:	Not reported		
Financial Responsibility Type:	Not reported		
Corrective Action Met Flag:	Not reported		
Third Party Met Flag:	Not reported		
Financial Assurance Beginning Date:	Not reported		
Piping Design & Ext. Containment 3 :	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

THARP MEMORIAL US ARMY RESERVE CENTER (Continued)

U003166205

Piping Design & Ext. Containment 4 : Not reported
 Type of Piping : Not reported
 Internal Tank Lining Date : 00/00/0000
 Pipe Connectors and Valves 1 : Not reported
 Pipe Connectors and Valves 2 : Not reported
 Pipe Connectors and Valves 3 : Not reported
 Other Tank Corrosion Protection Text: Not reported
 Tank Corrosion Protection Variance : No Variance
 Pipe Corrosion Protection 3 : Not reported
 Pipe Corrosion Protection Variance : No Variance
 Stage 2 Vapor Recy Equipment Status : Not reported
 Stage 1 Equipment Installed Date : Not reported
 Tank Tested : Not reported
 Compartment Capacity : 0000000
 Owner ID : 49607
 Owner Name : US DEPARTMENT OF THE ARMY
 Owner Address : 8000 CAMP ROBINSON RD AFRD-CAR-EN-E
 NORTH LITTLE ROCK, AR 72118
 Owner Contact Telephone : 501-771-7992
 Owner Type : Federal Government
 Owner Amendment Reason Code : Owner Billing Address Changed
 Owner Amendment Date : 16/05/06
 Owner Tax ID : Not reported
 Number of Facilities reported by Owner : 0036
 Mail Undeliverable : Not reported
 Bankruptcy In Effect : Not reported
 # Of Underground Storage Tanks : 0045
 # Of Aboveground Storage Tanks : 0000
 Operator Effective Date : Not reported
 Operator Type : Federal Government
 Owner Contact Name: James Wheeler
 Date Registration Form Received : 21/97/01
 Facility Type : None of the above, or unidentified
 Name of Facility Manager : Donny Rhynhart
 Title of Facility Manager : Not reported
 Facility Manager Phone : 806-352-8911
 Sign Name on Registration Form : Teddy B Baer, Col, USAR
 Title of Signer of Registration Form : Deputy Chief of Staf
 Date of Signature on Registration Form : 011797
 Number of USTs: 0001
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

2
NNW
< 1/8
351 ft.

KMART 4023
2747 DUNIVEN CIR
AMARILLO, TX 79109

UST U001250989
N/A

Relative:
Higher

UST:

Facility ID: 0015724
 Tank ID: 1
 Tank Emptied: No
 Capacity: 1000

Tank Installer: Not reported
 Installation Date: 01/01/1970
 Status Date: 09/28/1989
 Unit ID: 00040387

Actual:
3612 ft.

Tank Material of Construction: Steel
 Pipe Material of Construction: Steel
 Other Materials of Construction: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

KMART 4023 (Continued)

U001250989

Tank Status:	Removed from the Ground
Tank Construction & Containment:	Not reported
Pipe Construction & Containment:	Not reported
Other Construction & Containment:	Not reported
Compartment Substance Stored:	Used Oil
Compartment Other Substance:	Not reported
Tank Release Detection Method:	Not reported
Tank Release Method Detection II:	Not reported
Tank Release Method Detection III:	Not reported
Other Tank Release Method Detection:	None
Tank Release Detection Variance :	No Variance
Pipe Release Detection Method:	Not reported
Other Pipe Release Detection Method :	None
Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Corrosion Protection:	Not reported
Other Corrosion Protection:	None
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	05/08/1986
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

PIT STOP (Continued)

U001284716

Tank Release Detection Variance :	No Variance
Pipe Release Detection Method:	Not reported
Other Pipe Release Detection Method :	None
Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Corrosion Protection:	Not reported
Other Corrosion Protection:	None
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	06/28/1990
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Gravity
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	None
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Not reported
Compartment Capacity :	0000000
Owner ID :	28790
Owner Name :	DAMCOY INC
Owner Address :	AMARILLO, TX 79102
Owner Contact Telephone :	(806) 355-0521
Owner Type :	Private or Corporate
Owner Amendment Reason Code :	Owner Billing Address Changed

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

PIT STOP (Continued)

U001284716

Owner Amendment Date :	20/96/11		
Owner Tax ID :	17513297196		
Number of Facilities reported by Owner :	0001		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0002		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Private or Corporate		
Owner Contact Name:	JOHN FRISBY		
Date Registration Form Received :	28/90/06		
Facility Type :	Retail		
Name of Facility Manager :	JOHN FRISBY		
Title of Facility Manager :	PRESIDENT		
Facility Manager Phone :	8063528804		
Sign Name on Registration Form :	Not reported		
Title of Signer of Registration Form :	Not reported		
Date of Signature on Registration Form :	Not reported		
Number of USTs:	0002		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	PO BOX 30308		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0054376	Tank Installer:	Not reported
Tank ID:	2	Installation Date:	02/01/1979
Tank Emptied:	No	Status Date:	08/06/1990
Capacity:	500	Unit ID:	00133170
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Used Oil		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Inventory Control		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	06/28/1990		
Installer License Number:	Not reported		
Operator Name:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

PIT STOP (Continued)

U001284716

Operator Telephone number: Not reported
Operator Address:
Operator Address building: Not reported
Contact Operator Name:
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Gravity
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 28790
Owner Name : DAMCOY INC
Owner Address : AMARILLO, TX 79102
Owner Contact Telephone : (806) 355-0521
Owner Type : Private or Corporate
Owner Amendment Reason Code : Owner Billing Address Changed
Owner Amendment Date : 20/96/11
Owner Tax ID : 17513297196
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0002
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Private or Corporate
Owner Contact Name: JOHN FRISBY
Date Registration Form Received : 28/90/06
Facility Type : Retail
Name of Facility Manager : JOHN FRISBY
Title of Facility Manager : PRESIDENT
Facility Manager Phone : 8063528804

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

PIT STOP (Continued)

U001284716

Sign Name on Registration Form : Not reported
 Title of Signer of Registration Form : Not reported
 Date of Signature on Registration Form : Not reported
 Number of USTs: 0002
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : PO BOX 30308
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

4
West
1/8-1/4
786 ft.

TASCOSA SHELL
3307 W IH 40
AMARILLO, TX 79106

UST U001244560
N/A

Relative:
Higher

UST:
 Facility ID: 0008210 Tank Installer: Not reported
 Tank ID: 2 Installation Date: 01/01/1970
Actual: Tank Emptied: No Status Date: 05/30/1995
3618 ft. Capacity: 8000 Unit ID: 00021450
 Tank Material of Construction: Steel
 Pipe Material of Construction: Steel
 Other Materials of Construction: Not reported
 Tank Status: Removed from the Ground
 Tank Construction & Containment: Not reported
 Pipe Construction & Containment: Not reported
 Other Construction & Containment: Not reported
 Compartment Substance Stored: Gasoline
 Compartment Other Substance: Not reported
 Tank Release Detection Method: Not reported
 Tank Release Method Detection II: Not reported
 Tank Release Method Detection III: Not reported
 Other Tank Release Method Detection: None
 Tank Release Detection Variance : No Variance
 Pipe Release Detection Method: Not reported
 Other Pipe Release Detection Method : None
 Pipe Release Detection Variance : No Variance
 Spill and Overfill Protection: Not reported
 Tank Corrosion Protection: Not reported
 Pipe Corrosion Protection: Not reported
 Other Corrosion Protection: None
 Vapor Recovery Equipment Status: Not reported
 Equipment Installed Date: Not reported
 Equipment Installer: Not reported
 Contractor Registration Number: Not reported
 Tank Registration Date: 05/08/1986
 Installer License Number: Not reported
 Operator Name: Not reported
 Operator Telephone number: Not reported
 Operator Address: Not reported
 Operator Address building: Not reported
 Contact Operator Name: Not reported
 Contact Operator title: Not reported
 Contact Operator Phone: Not reported
 Self-Certification date: Not reported
 Signature Name: Not reported
 Signature Title Name: Not reported
 Signature Type Text: Not reported
 Certification Submitted Type: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TASCOSA SHELL (Continued)

U001244560

Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 24926
Owner Name : SCOTT NEIL B
Owner Address : AMARILLO, TX 79105
Owner Contact Telephone : 806-383-1985
Owner Type : Individual
Owner Amendment Reason Code : Owner Address Deliverable
Owner Amendment Date : 19/02/09
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0003
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Individual
Owner Contact Name: NEIL SCOTT
Date Registration Form Received : 08/86/05
Facility Type : None of the above, or unidentified
Name of Facility Manager : NEIL SCOTT
Title of Facility Manager : Not reported
Facility Manager Phone : 806-383-1985
Sign Name on Registration Form : E.H. FLOOD
Title of Signer of Registration Form : PRES
Date of Signature on Registration Form : 050186
Number of USTs: 0003
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : PO BOX 1948
Region Number : 01
Facility in Ozone non-attainment area : Not reported

Facility ID: 0008210

Tank Installer: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

TASCOSA SHELL (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U001244560

Tank ID:	1	Installation Date:	01/01/1970
Tank Emptied:	No	Status Date:	05/30/1995
Capacity:	8000	Unit ID:	00021451
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		
Signature Title Name:	Not reported		
Signature Type Text:	Not reported		
Certification Submitted Type:	Not reported		
Registration Self-Certification Flag:	Not reported		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Not reported		
Technical standards Self-Certification flag:	Not reported		
UST Delivery Certificate Expiration Date:	Not reported		
Compartment letter:	Not reported		
Financial Responsibility Type:	Not reported		
Corrective Action Met Flag:	Not reported		
Third Party Met Flag:	Not reported		
Financial Assurance Beginning Date:	Not reported		
Piping Design & Ext. Containment 3 :	Not reported		
Piping Design & Ext. Containment 4 :	Not reported		
Type of Piping :	Not reported		
Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TASCOSA SHELL (Continued)

U001244560

Pipe Connectors and Valves 2 :	Not reported		
Pipe Connectors and Valves 3 :	Not reported		
Other Tank Corrosion Protection Text:	Not reported		
Tank Corrosion Protection Variance :	No Variance		
Pipe Corrosion Protection 3 :	Not reported		
Pipe Corrosion Protection Variance :	No Variance		
Stage 2 Vapor Recry Equipment Status :	Not reported		
Stage 1 Equipment Installed Date :	Not reported		
Tank Tested :	Not reported		
Compartment Capacity :	0000000		
Owner ID :	24926		
Owner Name :	SCOTT NEIL B		
Owner Address :	AMARILLO, TX 79105		
Owner Contact Telephone :	806-383-1985		
Owner Type :	Individual		
Owner Amendment Reason Code :	Owner Address Deliverable		
Owner Amendment Date :	19/02/09		
Owner Tax ID :	Not reported		
Number of Facilities reported by Owner :	0001		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0003		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Individual		
Owner Contact Name:	NEIL SCOTT		
Date Registration Form Received :	08/86/05		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	NEIL SCOTT		
Title of Facility Manager :	Not reported		
Facility Manager Phone :	806-383-1985		
Sign Name on Registration Form :	E.H. FLOOD		
Title of Signer of Registration Form :	PRES		
Date of Signature on Registration Form :	050186		
Number of USTs:	0003		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	PO BOX 1948		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0008210	Tank Installer:	Not reported
Tank ID:	3	Installation Date:	01/01/1970
Tank Emptied:	No	Status Date:	05/30/1995
Capacity:	8000	Unit ID:	00021452
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TASCOSA SHELL (Continued)

U001244560

Other Tank Release Method Detection: None
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: Not reported
Other Pipe Release Detection Method : None
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Not reported
Tank Corrosion Protection: Not reported
Pipe Corrosion Protection: Not reported
Other Corrosion Protection: None
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 05/08/1986
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address: Not reported
Operator Address building: Not reported
Contact Operator Name: Not reported
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 24926
Owner Name : SCOTT NEIL B
Owner Address : AMARILLO, TX 79105
Owner Contact Telephone : 806-383-1985
Owner Type : Individual

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TASCOSA SHELL (Continued)

U001244560

Owner Amendment Reason Code : Owner Address Deliverable
 Owner Amendment Date : 19/02/09
 Owner Tax ID : Not reported
 Number of Facilities reported by Owner : 0001
 Mail Undeliverable : Not reported
 Bankruptcy In Effect : Not reported
 # Of Underground Storage Tanks : 0003
 # Of Aboveground Storage Tanks : 0000
 Operator Effective Date : Not reported
 Operator Type : Individual
 Owner Contact Name: NEIL SCOTT
 Date Registration Form Received : 08/86/05
 Facility Type : None of the above, or unidentified
 Name of Facility Manager : NEIL SCOTT
 Title of Facility Manager : Not reported
 Facility Manager Phone : 806-383-1985
 Sign Name on Registration Form : E.H. FLOOD
 Title of Signer of Registration Form : PRES
 Date of Signature on Registration Form : 050186
 Number of USTs: 0003
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : PO BOX 1948
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

**A5
 NE
 1/8-1/4
 867 ft.**

**SMITHSON AUTOMOTIVE CENTER
 2821 WOLFLIN
 AMARILLO, TX 79109**

**UST U001248351
 N/A**

Site 1 of 2 in cluster A

**Relative:
 Higher**

UST:

**Actual:
 3623 ft.**

Facility ID:	0012599	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1956
Tank Emptied:	No	Status Date:	03/09/2004
Capacity:	6000	Unit ID:	00032836
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	SCOTCH COAT		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Interstitial Monitoring within Secondary Wall/Jacket		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Tightness Testing		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Interstitial Monitoring within Secondary Wall/Jacket		
Other Pipe Release Detection Method :	Tightness Testing		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

SMITHSON AUTOMOTIVE CENTER (Continued)

U001248351

Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	05/08/1986
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Pressurized
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	None
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Tested
Compartment Capacity :	0000000
Owner ID :	06165
Owner Name :	SMITHSON JAMES D
Owner Address :	600 S TYLER 1300 BANK ONE CENTER AMARILLO, TX 79101
Owner Contact Telephone :	806-242-7437
Owner Type :	Private or Corporate
Owner Amendment Reason Code :	Owner Billing Address Changed
Owner Amendment Date :	14/04/04
Owner Tax ID :	17519937787
Number of Facilities reported by Owner :	0001
Mail Undeliverable :	Not reported
Bankruptcy In Effect :	Yes
# Of Underground Storage Tanks :	0004
# Of Aboveground Storage Tanks :	0000
Operator Effective Date :	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

SMITHSON AUTOMOTIVE CENTER (Continued)

U001248351

Operator Type : Private or Corporate
Owner Contact Name: KENT RIES
Date Registration Form Received : 08/86/05
Facility Type : None of the above, or unidentified
Name of Facility Manager : JAMES D SMITHSON
Title of Facility Manager : PARTNER
Facility Manager Phone : 806-355-6539
Sign Name on Registration Form : JAMES D SMITHSON
Title of Signer of Registration Form : PARTNER
Date of Signature on Registration Form : 042886
Number of USTs: 0004
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : PO BOX 12058
Region Number : 01
Facility in Ozone non-attainment area : Not reported

Facility ID: 0012599 Tank Installer: Not reported
Tank ID: 3 Installation Date: 01/01/1956
Tank Emptied: No Status Date: 03/09/2004
Capacity: 8000 Unit ID: 00032837

Tank Material of Construction: Steel
Pipe Material of Construction: Steel
Other Materials of Construction: Not reported
Tank Status: Removed from the Ground
Tank Construction & Containment: Single Wall
Pipe Construction & Containment: Single Wall
Other Construction & Containment: SCOTCH COAT
Compartment Substance Stored: Gasoline
Compartment Other Substance: Not reported
Tank Release Detection Method: Interstitial Monitoring within Secondary Wall/Jacket
Tank Release Method Detection II: Not reported
Tank Release Method Detection III: Not reported
Other Tank Release Method Detection: Tightness Testing
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: Interstitial Monitoring within Secondary Wall/Jacket
Other Pipe Release Detection Method : Tightness Testing
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Not reported
Tank Corrosion Protection: Not reported
Pipe Corrosion Protection: Not reported
Other Corrosion Protection: None
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 05/08/1986
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address: Not reported
Operator Address building: Not reported
Contact Operator Name: Not reported
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

SMITHSON AUTOMOTIVE CENTER (Continued)

U001248351

Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Pressurized
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Tested
Compartment Capacity : 0000000
Owner ID : 06165
Owner Name : SMITHSON JAMES D
Owner Address : 600 S TYLER 1300 BANK ONE CENTER
AMARILLO, TX 79101
Owner Contact Telephone : 806-242-7437
Owner Type : Private or Corporate
Owner Amendment Reason Code : Owner Billing Address Changed
Owner Amendment Date : 14/04/04
Owner Tax ID : 17519937787
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Yes
Of Underground Storage Tanks : 0004
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Private or Corporate
Owner Contact Name: KENT RIES
Date Registration Form Received : 08/86/05
Facility Type : None of the above, or unidentified
Name of Facility Manager : JAMES D SMITHSON
Title of Facility Manager : PARTNER
Facility Manager Phone : 806-355-6539
Sign Name on Registration Form : JAMES D SMITHSON
Title of Signer of Registration Form : PARTNER
Date of Signature on Registration Form : 042886
Number of USTs: 0004
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : PO BOX 12058

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

SMITHSON AUTOMOTIVE CENTER (Continued)

U001248351

Region Number :	01	Tank Installer:	Not reported
Facility in Ozone non-attainment area :	Not reported	Installation Date:	01/01/1956
Facility ID:	0012599	Status Date:	03/09/2004
Tank ID:	2	Unit ID:	00032838
Tank Emptied:	No		
Capacity:	6000		
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	SCOTCH COAT		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Interstitial Monitoring within Secondary Wall/Jacket		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Tightness Testing		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Interstitial Monitoring within Secondary Wall/Jacket		
Other Pipe Release Detection Method :	Tightness Testing		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		
Signature Title Name:	Not reported		
Signature Type Text:	Not reported		
Certification Submitted Type:	Not reported		
Registration Self-Certification Flag:	Not reported		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Not reported		
Technical standards Self-Certification flag:	Not reported		
UST Delivery Certificate Expiration Date:	Not reported		
Compartment letter:	Not reported		
Financial Responsibility Type:	Not reported		
Corrective Action Met Flag:	Not reported		
Third Party Met Flag:	Not reported		
Financial Assurance Beginning Date:	Not reported		
Piping Design & Ext. Containment 3 :	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

SMITHSON AUTOMOTIVE CENTER (Continued)

U001248351

Piping Design & Ext. Containment 4 :	Not reported		
Type of Piping :	Pressurized		
Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	Not reported		
Pipe Connectors and Valves 2 :	Not reported		
Pipe Connectors and Valves 3 :	Not reported		
Other Tank Corrosion Protection Text:	None		
Tank Corrosion Protection Variance :	No Variance		
Pipe Corrosion Protection 3 :	Not reported		
Pipe Corrosion Protection Variance :	No Variance		
Stage 2 Vapor Recry Equipment Status :	Not reported		
Stage 1 Equipment Installed Date :	Not reported		
Tank Tested :	Tested		
Compartment Capacity :	0000000		
Owner ID :	06165		
Owner Name :	SMITHSON JAMES D		
Owner Address :	600 S TYLER 1300 BANK ONE CENTER		
	AMARILLO, TX 79101		
Owner Contact Telephone :	806-242-7437		
Owner Type :	Private or Corporate		
Owner Amendment Reason Code :	Owner Billing Address Changed		
Owner Amendment Date :	14/04/04		
Owner Tax ID :	17519937787		
Number of Facilities reported by Owner :	0001		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Yes		
# Of Underground Storage Tanks :	0004		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Private or Corporate		
Owner Contact Name:	KENT RIES		
Date Registration Form Received :	08/86/05		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	JAMES D SMITHSON		
Title of Facility Manager :	PARTNER		
Facility Manager Phone :	806-355-6539		
Sign Name on Registration Form :	JAMES D SMITHSON		
Title of Signer of Registration Form :	PARTNER		
Date of Signature on Registration Form :	042886		
Number of USTs:	0004		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	PO BOX 12058		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0012599	Tank Installer:	Not reported
Tank ID:	4	Installation Date:	01/01/1956
Tank Emptied:	No	Status Date:	Not reported
Capacity:	300	Unit ID:	00032839
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	In Use		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

SMITHSON AUTOMOTIVE CENTER (Continued)

U001248351

Compartment Substance Stored:	Gasoline
Compartment Other Substance:	Not reported
Tank Release Detection Method:	Interstitial Monitoring within Secondary Wall/Jacket
Tank Release Method Detection II:	Not reported
Tank Release Method Detection III:	Not reported
Other Tank Release Method Detection:	Tightness Testing
Tank Release Detection Variance :	No Variance
Pipe Release Detection Method:	Interstitial Monitoring within Secondary Wall/Jacket
Other Pipe Release Detection Method :	Tightness Testing
Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Corrosion Protection:	Not reported
Other Corrosion Protection:	Not reported
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	05/08/1986
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Tested
Compartment Capacity :	0000000

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

SMITHSON AUTOMOTIVE CENTER (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U001248351

Owner ID : 06165
 Owner Name : SMITHSON JAMES D
 Owner Address : 600 S TYLER 1300 BANK ONE CENTER
 AMARILLO, TX 79101
 Owner Contact Telephone : 806-242-7437
 Owner Type : Private or Corporate
 Owner Amendment Reason Code : Owner Billing Address Changed
 Owner Amendment Date : 14/04/04
 Owner Tax ID : 17519937787
 Number of Facilities reported by Owner : 0001
 Mail Undeliverable : Not reported
 Bankruptcy In Effect : Yes
 # Of Underground Storage Tanks : 0004
 # Of Aboveground Storage Tanks : 0000
 Operator Effective Date : Not reported
 Operator Type : Private or Corporate
 Owner Contact Name: KENT RIES
 Date Registration Form Received : 08/86/05
 Facility Type : None of the above, or unidentified
 Name of Facility Manager : JAMES D SMITHSON
 Title of Facility Manager : PARTNER
 Facility Manager Phone : 806-355-6539
 Sign Name on Registration Form : JAMES D SMITHSON
 Title of Signer of Registration Form : PARTNER
 Date of Signature on Registration Form : 042886
 Number of USTs: 0004
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : PO BOX 12058
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

**A6
 NE
 1/8-1/4
 867 ft.**

**SMITHSON AUTOMOTIVE CENTER
 2821 WOLFLIN AVE
 AMARILLO, TX 79109**

**LTANKS S106953395
 N/A**

Site 2 of 2 in cluster A

**Relative:
 Higher**

LTANKS:

**Actual:
 3623 ft.**

Facility ID: 0012599
 Facility Location: 2821 WOLFLIN AVE
 Reported Date: 3/9/2004
 Entered Date: 10/19/2004
 RPR Coordinator: RD2
 Region: 01
 Region City ID: Amarillo
 LPST Id: 116186
 Responsible Party: SMITHSON JAMES ESTATE
 RP Contact: KENT RIES
 RP Telephone: 806/242-7437
 RP Address: 600 S TYLER STE 1300
 AMARILLO, TX 79101
 Priority: GW IMPACT, NON-PUBLIC/NON-DOMESTIC H2O SUPPLY WELL W/IN
 .25mi
Status: PREASSESSMENT/RELEASE DETERMINATION

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
 EPA ID Number

7
NNW
1/8-1/4
878 ft.

TEXACO
2001 PARAMOUNT AVE
AMARILLO, TX 79109

UST **U003565153**
LTANKS **N/A**

Relative:
Higher

LTANKS:

Actual:
3620 ft.

Facility ID: 0013494
 Facility Location: 2001 PARAMOUNT AVE
 Reported Date: 10/12/1990
 Entered Date: 12/4/1990
 RPR Coordinator: RPR
 Region: 01
 Region City ID: AMARILLO
 LPST Id: 097403
 Responsible Party: TEXACO REFINING MARKETING
 RP Contact: THOMAS CHANDLER
 RP Telephone: 918/560-7530
 RP Address: PO BOX 1650
 TULSA, OK 74102
 Priority: DRINKING WATER AQUIFER OR WATER WELL IMPACTED/THREATENED
 Status: **FINAL CONCURRENCE ISSUED, CASE CLOSED**

UST:

Facility ID:	0013494	Tank Installer:	Not reported
Tank ID:	4	Installation Date:	01/01/1972
Tank Emptied:	No	Status Date:	03/21/1988
Capacity:	550	Unit ID:	00034860
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Used Oil		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TEXACO (Continued)

U003565153

Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 03594
Owner Name : TEXACO REFINING & MARKETING INC
Owner Address : TULSA, OK 74101
Owner Contact Telephone : 214-258-7909
Owner Type : Corporation
Owner Amendment Reason Code : Owner Name Changed
Owner Amendment Date : 06/03/03
Owner Tax ID : 0049221035
Number of Facilities reported by Owner : 0030
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0121
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Corporation
Owner Contact Name:
Date Registration Form Received : 08/86/05
Facility Type : None of the above, or unidentified
Name of Facility Manager : F H VAN DYKE
Title of Facility Manager : DIV MGR
Facility Manager Phone : 2142587909
Sign Name on Registration Form : F H VAN DYKE
Title of Signer of Registration Form : DIV MGR
Date of Signature on Registration Form : 030786
Number of USTs: 0004
Number of ASTs: 0000

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TEXACO (Continued)

U003565153

Facility PO Box :	Not reported	Tank Installer:	Not reported
Owner PO Box :	PO BOX 1650	Installation Date:	01/01/1972
Region Number :	01	Status Date:	03/21/1988
Facility in Ozone non-attainment area :	Not reported	Unit ID:	00034861
Facility ID:	0013494		
Tank ID:	3		
Tank Emptied:	No		
Capacity:	10000		
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Used Oil		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		
Signature Title Name:	Not reported		
Signature Type Text:	Not reported		
Certification Submitted Type:	Not reported		
Registration Self-Certification Flag:	Not reported		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Not reported		
Technical standards Self-Certification flag:	Not reported		
UST Delivery Certificate Expiration Date:	Not reported		
Compartment letter:	Not reported		
Financial Responsibility Type:	Not reported		
Corrective Action Met Flag:	Not reported		
Third Party Met Flag:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TEXACO (Continued)

U003565153

Financial Assurance Beginning Date:	Not reported		
Piping Design & Ext. Containment 3 :	Not reported		
Piping Design & Ext. Containment 4 :	Not reported		
Type of Piping :	Not reported		
Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	Not reported		
Pipe Connectors and Valves 2 :	Not reported		
Pipe Connectors and Valves 3 :	Not reported		
Other Tank Corrosion Protection Text:	Not reported		
Tank Corrosion Protection Variance :	No Variance		
Pipe Corrosion Protection 3 :	Not reported		
Pipe Corrosion Protection Variance :	No Variance		
Stage 2 Vapor Recry Equipment Status :	Not reported		
Stage 1 Equipment Installed Date :	Not reported		
Tank Tested :	Not reported		
Compartment Capacity :	0000000		
Owner ID :	03594		
Owner Name :	TEXACO REFINING & MARKETING INC		
Owner Address :	TULSA, OK 74101		
Owner Contact Telephone :	214-258-7909		
Owner Type :	Corporation		
Owner Amendment Reason Code :	Owner Name Changed		
Owner Amendment Date :	06/03/03		
Owner Tax ID :	0049221035		
Number of Facilities reported by Owner :	0030		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0121		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Corporation		
Owner Contact Name:			
Date Registration Form Received :	08/86/05		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	F H VAN DYKE		
Title of Facility Manager :	DIV MGR		
Facility Manager Phone :	2142587909		
Sign Name on Registration Form :	F H VAN DYKE		
Title of Signer of Registration Form :	DIV MGR		
Date of Signature on Registration Form :	030786		
Number of USTs:	0004		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	PO BOX 1650		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0013494	Tank Installer:	Not reported
Tank ID:	2	Installation Date:	01/01/1972
Tank Emptied:	No	Status Date:	03/21/1988
Capacity:	10000	Unit ID:	00034862
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TEXACO (Continued)

U003565153

Other Construction & Containment:	Not reported
Compartment Substance Stored:	Used Oil
Compartment Other Substance:	Not reported
Tank Release Detection Method:	Not reported
Tank Release Method Detection II:	Not reported
Tank Release Method Detection III:	Not reported
Other Tank Release Method Detection:	None
Tank Release Detection Variance :	No Variance
Pipe Release Detection Method:	Not reported
Other Pipe Release Detection Method :	None
Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Corrosion Protection:	Not reported
Other Corrosion Protection:	None
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	05/08/1986
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TEXACO (Continued)

U003565153

Compartment Capacity :	0000000		
Owner ID :	03594		
Owner Name :	TEXACO REFINING & MARKETING INC		
Owner Address :	TULSA, OK 74101		
Owner Contact Telephone :	214-258-7909		
Owner Type :	Corporation		
Owner Amendment Reason Code :	Owner Name Changed		
Owner Amendment Date :	06/03/03		
Owner Tax ID :	0049221035		
Number of Facilities reported by Owner :	0030		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0121		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Corporation		
Owner Contact Name:			
Date Registration Form Received :	08/86/05		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	F H VAN DYKE		
Title of Facility Manager :	DIV MGR		
Facility Manager Phone :	2142587909		
Sign Name on Registration Form :	F H VAN DYKE		
Title of Signer of Registration Form :	DIV MGR		
Date of Signature on Registration Form :	030786		
Number of USTs:	0004		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	PO BOX 1650		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0013494	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1972
Tank Emptied:	No	Status Date:	03/21/1988
Capacity:	6000	Unit ID:	00034863
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Used Oil		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TEXACO (Continued)

U003565153

Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	05/08/1986
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Not reported
Compartment Capacity :	0000000
Owner ID :	03594
Owner Name :	TEXACO REFINING & MARKETING INC
Owner Address :	TULSA, OK 74101
Owner Contact Telephone :	214-258-7909
Owner Type :	Corporation
Owner Amendment Reason Code :	Owner Name Changed
Owner Amendment Date :	06/03/03
Owner Tax ID :	0049221035
Number of Facilities reported by Owner :	0030
Mail Undeliverable :	Not reported
Bankruptcy In Effect :	Not reported
# Of Underground Storage Tanks :	0121
# Of Aboveground Storage Tanks :	0000
Operator Effective Date :	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

TEXACO (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U003565153

Operator Type : Corporation
 Owner Contact Name:
 Date Registration Form Received : 08/86/05
 Facility Type : None of the above, or unidentified
 Name of Facility Manager : F H VAN DYKE
 Title of Facility Manager : DIV MGR
 Facility Manager Phone : 2142587909
 Sign Name on Registration Form : F H VAN DYKE
 Title of Signer of Registration Form : DIV MGR
 Date of Signature on Registration Form : 030786
 Number of USTs: 0004
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : PO BOX 1650
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

**B8
 SW
 1/8-1/4
 931 ft.**

**DON JUDD CAD INC DBA
 2501 PARAMOUNT
 AMARILLO, TX 79109**

**RCRA-SQG 1000121144
 FINDS TXD981594591
 Ind. Haz Waste**

Site 1 of 2 in cluster B

**Relative:
 Lower**

RCRAInfo:
 Owner: DON JUDD
 (000) 000-0000
 EPA ID: TXD981594591
 Contact: JOHNNY HARTSEL
 (806) 359-8541

**Actual:
 3609 ft.**

Classification: Small Quantity Generator
 TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated: Not reported
 Area of Violation: Texas Solid Waste Rule
 Date Violation Determined: 08/15/1990
 Actual Date Achieved Compliance: 08/23/1990
 Enforcement Action: VERBAL INFORMAL
 Enforcement Action Date: 08/23/1990
 Penalty Type: Not reported

There are 1 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Other Evaluation	Texas Solid Waste Rule	19900823

FINDS:

Other Pertinent Environmental Activity Identified at Site:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

TX IHW:

Registration Number: 72197
 Year: 1999
 Registration Initial Notification Date: 11/07/1986

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

DON JUDD CAD INC DBA (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000121144

Registration Last Amendment Date:	03/04/1993
EPA Identification:	TXD981594591
TNRCC Permit Number:	Not reported
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	00
	Not reported
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	SQG
Company Name:	Don Judd Cad Inc DBA
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	Not reported
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	Not reported
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	Not reported
Facility is STEERS Reporter :	Not reported
Fac Req to Submit Annual Waste Summary Rpt :	Not reported
Facility Involved In Recycling:	Not reported
Mailing Address:	2501 Paramount Amarillo, TX 79120
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Rex Brewer
Contact Telephone Number:	806-358-8888
Registration Number:	72197
Year:	2000
Registration Initial Notification Date:	11/07/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981594591
TNRCC Permit Number:	026640
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	99990
	Nonclassifiable Establishment Public Admin.
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	SQG
Company Name:	Don Judd Cad Inc DBA
Facility County:	Not reported
TNRCC Region:	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

DON JUDD CAD INC DBA (Continued)

1000121144

TNRCC Facility ID :	026640
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010824
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	2501 Paramount Amarillo, TX 79120
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Rex Brewer
Contact Telephone Number:	806-358-8888
Registration Number:	72197
Year:	2001
Registration Initial Notification Date:	11/07/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981594591
TNRCC Permit Number:	026640
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	99990 Nonclassifiable Establishments Nonclassifiable
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	SQG
Company Name:	Don Judd Cad Inc DBA
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	026640
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010824
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	2501 Paramount Amarillo, TX 79120
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Rex Brewer
Contact Telephone Number:	806-358-8888
Registration Number:	72197

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

DON JUDD CAD INC DBA (Continued)

1000121144

Year:	2002
Registration Initial Notification Date:	11/07/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981594591
TNRCC Permit Number:	026640
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	99990
	Nonclassifiable Establishments
	Nonclassifiable
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	SQG
Company Name:	Don Judd Cad Inc DBA
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	026640
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010824
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	2501 Paramount Amarillo, TX 79120
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Rex Brewer
Contact Telephone Number:	806-358-8888
Registration Number:	72197
Year:	2003
Registration Initial Notification Date:	11/07/1986
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD981594591
TNRCC Permit Number:	026640
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2501 Paramount, Amarillo, TX
Site Primary Standard Industrial Code:	99990
	Nonclassifiable Establishments
	Nonclassifiable
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	SQG

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

DON JUDD CAD INC DBA (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000121144

Contact Telephone Number:	806-358-8888
Registration Number:	72197
Year:	98-99
Registration Initial Notification Date:	11/07/1986
Registration Last Amendment Date:	03/04/1993
EPA Identification:	TXD981594591
TNRCC Permit Number:	Not reported
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	00
	Not reported
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	SQG
Company Name:	Don Judd Cad Inc DBA
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	Not reported
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	Not reported
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	Not reported
Facility is STEERS Reporter :	Not reported
Fac Req to Submit Annual Waste Summary Rpt :	Not reported
Facility Involved In Recycling:	Not reported
Mailing Address:	2501 Paramount Amarillo, TX 79120
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Rex Brewer
Contact Telephone Number:	806-358-8888

[Click this hyperlink](#) while viewing on your computer to access additional TX IHW detail in the EDR Site Report.

B9
SW
 1/8-1/4
 931 ft.

GEN MESSER CADILLAC
2501 PARAMOUNT
AMARILLO, TX 79109

UST U001261486
N/A

Site 2 of 2 in cluster B

Relative:
Lower

UST:			
Facility ID:	0027727	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1978
Tank Emptied:	No	Status Date:	06/15/1998
Capacity:	10000	Unit ID:	00072568
Tank Material of Construction:	Not reported		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		

Actual:
3609 ft.

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

GEN MESSER CADILLAC (Continued)

U001261486

Pipe Construction & Containment: Not reported
Other Construction & Containment: Not reported
Compartment Substance Stored: Gasoline
Compartment Other Substance: Not reported
Tank Release Detection Method: Not reported
Tank Release Method Detection II: Not reported
Tank Release Method Detection III: Not reported
Other Tank Release Method Detection: None
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: Not reported
Other Pipe Release Detection Method : None
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Not reported
Tank Corrosion Protection: Not reported
Pipe Corrosion Protection: Not reported
Other Corrosion Protection: None
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 05/08/1986
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address: Not reported
Operator Address building: Not reported
Contact Operator Name: Not reported
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

GEN MESSER CADILLAC (Continued)

U001261486

Tank Tested :	Tested		
Compartment Capacity :	0000000		
Owner ID :	52182		
Owner Name :	D & M PARTNERSHIP		
Owner Address :	ARLINGTON, TX 76004		
Owner Contact Telephone :	817-461-9144		
Owner Type :	Private or Corporate		
Owner Amendment Reason Code :	001		
Owner Amendment Date :	12/02/01		
Owner Tax ID :	Not reported		
Number of Facilities reported by Owner :	0001		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0003		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Private or Corporate		
Owner Contact Name:	Bill Snider		
Date Registration Form Received :	08/86/05		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	Larry Martin		
Title of Facility Manager :	Not reported		
Facility Manager Phone :	806-816-3845		
Sign Name on Registration Form :	J. A. MARTIN		
Title of Signer of Registration Form :	PART MGR.		
Date of Signature on Registration Form :	050286		
Number of USTs:	0003		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	P O BOX 490		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0027727	Tank Installer:	Not reported
Tank ID:	3	Installation Date:	01/01/1978
Tank Emptied:	No	Status Date:	06/15/1998
Capacity:	0	Unit ID:	00072569
Tank Material of Construction:	Not reported		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

GEN MESSER CADILLAC (Continued)

U001261486

Other Corrosion Protection: None
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 05/08/1986
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address:
Operator Address building: Not reported
Contact Operator Name:
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Tested
Compartment Capacity : 0000000
Owner ID : 52182
Owner Name : D & M PARTNERSHIP
Owner Address : ARLINGTON, TX 76004
Owner Contact Telephone : 817-461-9144
Owner Type : Private or Corporate
Owner Amendment Reason Code : 001
Owner Amendment Date : 12/02/01
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0003
Of Aboveground Storage Tanks : 0000

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

GEN MESSER CADILLAC (Continued)

U001261486

Operator Effective Date :	Not reported		
Operator Type :	Private or Corporate		
Owner Contact Name:	Bill Snider		
Date Registration Form Received :	08/86/05		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	Larry Martin		
Title of Facility Manager :	Not reported		
Facility Manager Phone :	806-816-3845		
Sign Name on Registration Form :	J. A. MARTIN		
Title of Signer of Registration Form :	PART MGR.		
Date of Signature on Registration Form :	050286		
Number of USTs:	0003		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	P O BOX 490		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0027727	Tank Installer:	Not reported
Tank ID:	2	Installation Date:	01/01/1978
Tank Emptied:	No	Status Date:	06/15/1998
Capacity:	4000	Unit ID:	00072570
Tank Material of Construction:	Not reported		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

GEN MESSER CADILLAC (Continued)

U001261486

Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Tested
Compartment Capacity : 0000000
Owner ID : 52182
Owner Name : D & M PARTNERSHIP
Owner Address : ARLINGTON, TX 76004
Owner Contact Telephone : 817-461-9144
Owner Type : Private or Corporate
Owner Amendment Reason Code : 001
Owner Amendment Date : 12/02/01
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0003
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Private or Corporate
Owner Contact Name: Bill Snider
Date Registration Form Received : 08/86/05
Facility Type : None of the above, or unidentified
Name of Facility Manager : Larry Martin
Title of Facility Manager : Not reported
Facility Manager Phone : 806-816-3845
Sign Name on Registration Form : J. A. MARTIN
Title of Signer of Registration Form : PART MGR.
Date of Signature on Registration Form : 050286
Number of USTs: 0003
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : P O BOX 490

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

GEN MESSER CADILLAC (Continued)

EDR ID Number
 EPA ID Number

U001261486

Region Number : 01
 Facility in Ozone non-attainment area : Not reported

C10 **TUNEUP MASTERS STORE 823**
East **2314 S GEORGIA ST**
1/8-1/4 **AMARILLO, TX 79109**
931 ft.

UST **U001258330**
N/A

Site 1 of 3 in cluster C

Relative:
Higher

Actual:
3621 ft.

UST:			
Facility ID:	0024073	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1983
Tank Emptied:	No	Status Date:	05/01/1991
Capacity:	500	Unit ID:	00061907
Tank Material of Construction:	Not reported		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Used Oil		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		
Signature Title Name:	Not reported		
Signature Type Text:	Not reported		
Certification Submitted Type:	Not reported		
Registration Self-Certification Flag:	Not reported		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Not reported		
Technical standards Self-Certification flag:	Not reported		
UST Delivery Certificate Expiration Date:	Not reported		
Compartment letter:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TUNEUP MASTERS STORE 823 (Continued)

U001258330

Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Tested
Compartment Capacity : 0000000
Owner ID : 00931
Owner Name : TUNEUP MASTERS INC
Owner Address : 750 W 5TH ST STE 300
 FT WORTH, TX 76102

Owner Contact Telephone : 805-375-1100
Owner Type : Corporation
Owner Amendment Reason Code : Owner Billing Address Changed
Owner Amendment Date : 21/05/06
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0061
Mail Undeliverable : Not reported
Bankruptcy In Effect : Yes
Of Underground Storage Tanks : 0070
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Corporation
Owner Contact Name: Not reported
Date Registration Form Received : 08/86/05
Facility Type : None of the above, or unidentified
Name of Facility Manager : GEORGE MAYER
Title of Facility Manager : OPER. MGR.
Facility Manager Phone : 8053751100
Sign Name on Registration Form : GEORGE MAYER
Title of Signer of Registration Form : OPER MGR
Date of Signature on Registration Form : 050286
Number of USTs: 0001
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : Not reported
Region Number : 01
Facility in Ozone non-attainment area : Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
 EPA ID Number

C11 **AFCO 010419**
East **2333 S GEORGIA**
1/8-1/4 **AMARILLO, TX 79106**
938 ft.

UST **U001246203**
N/A

Site 2 of 3 in cluster C

Relative:
Higher

UST:

Actual:
3620 ft.

Facility ID:	0010112	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1977
Tank Emptied:	Yes	Status Date:	06/28/1991
Capacity:	10000	Unit ID:	00026730
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		
Signature Title Name:	Not reported		
Signature Type Text:	Not reported		
Certification Submitted Type:	Not reported		
Registration Self-Certification Flag:	Not reported		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Not reported		
Technical standards Self-Certification flag:	Not reported		
UST Delivery Certificate Expiration Date:	Not reported		
Compartment letter:	Not reported		
Financial Responsibility Type:	Not reported		
Corrective Action Met Flag:	Not reported		
Third Party Met Flag:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AFCO 010419 (Continued)

U001246203

Financial Assurance Beginning Date:	Not reported		
Piping Design & Ext. Containment 3 :	Not reported		
Piping Design & Ext. Containment 4 :	Not reported		
Type of Piping :	Not reported		
Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	Not reported		
Pipe Connectors and Valves 2 :	Not reported		
Pipe Connectors and Valves 3 :	Not reported		
Other Tank Corrosion Protection Text:	Not reported		
Tank Corrosion Protection Variance :	No Variance		
Pipe Corrosion Protection 3 :	Not reported		
Pipe Corrosion Protection Variance :	No Variance		
Stage 2 Vapor Recry Equipment Status :	Not reported		
Stage 1 Equipment Installed Date :	Not reported		
Tank Tested :	Not reported		
Compartment Capacity :	0000000		
Owner ID :	23014		
Owner Name :	AUTOFUEL COMPANY AFCO		
Owner Address :	1234 W COWLES ST LONG BEACH, CA 90813		
Owner Contact Telephone :	915-695-5215		
Owner Type :	Private or Corporate		
Owner Amendment Reason Code :	Owner Address Undeliverable		
Owner Amendment Date :	29/03/08		
Owner Tax ID :	10049065230		
Number of Facilities reported by Owner :	0004		
Mail Undeliverable :	Yes		
Bankruptcy In Effect :	Yes		
# Of Underground Storage Tanks :	0013		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Private or Corporate		
Owner Contact Name:	JOHN MORAN		
Date Registration Form Received :	08/86/05		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	RAY P SIMPSON		
Title of Facility Manager :	GEN MGR		
Facility Manager Phone :	8063643368		
Sign Name on Registration Form :	RAY P SIMPSON		
Title of Signer of Registration Form :	GEN MGR		
Date of Signature on Registration Form :	041886		
Number of USTs:	0002		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0010112	Tank Installer:	Not reported
Tank ID:	2	Installation Date:	01/01/1977
Tank Emptied:	Yes	Status Date:	06/28/1991
Capacity:	10000	Unit ID:	00026731
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AFCO 010419 (Continued)

U001246203

Pipe Construction & Containment:	Not reported
Other Construction & Containment:	Not reported
Compartment Substance Stored:	Gasoline
Compartment Other Substance:	Not reported
Tank Release Detection Method:	Not reported
Tank Release Method Detection II:	Not reported
Tank Release Method Detection III:	Not reported
Other Tank Release Method Detection:	None
Tank Release Detection Variance :	No Variance
Pipe Release Detection Method:	Not reported
Other Pipe Release Detection Method :	None
Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Corrosion Protection:	Not reported
Other Corrosion Protection:	None
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	05/08/1986
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AFCO 010419 (Continued)

U001246203

Tank Tested : Not reported
 Compartment Capacity : 0000000
 Owner ID : 23014
 Owner Name : AUTOFUEL COMPANY AFCO
 Owner Address : 1234 W COWLES ST
 LONG BEACH, CA 90813
 Owner Contact Telephone : 915-695-5215
 Owner Type : Private or Corporate
 Owner Amendment Reason Code : Owner Address Undeliverable
 Owner Amendment Date : 29/03/08
 Owner Tax ID : 10049065230
 Number of Facilities reported by Owner : 0004
 Mail Undeliverable : Yes
 Bankruptcy In Effect : Yes
 # Of Underground Storage Tanks : 0013
 # Of Aboveground Storage Tanks : 0000
 Operator Effective Date : Not reported
 Operator Type : Private or Corporate
 Owner Contact Name: JOHN MORAN
 Date Registration Form Received : 08/86/05
 Facility Type : None of the above, or unidentified
 Name of Facility Manager : RAY P SIMPSON
 Title of Facility Manager : GEN MGR
 Facility Manager Phone : 8063643368
 Sign Name on Registration Form : RAY P SIMPSON
 Title of Signer of Registration Form : GEN MGR
 Date of Signature on Registration Form : 041886
 Number of USTs: 0002
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

**12
 East
 1/8-1/4
 943 ft.**

**KEY GUARD FUEL
 GEORGIA & CIVIC
 AMARILLO, TX 79109**

**UST U001257927
 N/A**

**Relative:
 Higher**

UST:
 Facility ID: 0023605 Tank Installer: Not reported
 Tank ID: 1 Installation Date: 01/01/1978
 Tank Emptied: No Status Date: 01/31/1989
 Capacity: 6000 Unit ID: 00060910
 Tank Material of Construction: Steel
 Pipe Material of Construction: Steel
 Other Materials of Construction: Not reported
 Tank Status: Removed from the Ground
 Tank Construction & Containment: Not reported
 Pipe Construction & Containment: Not reported
 Other Construction & Containment: Not reported
 Compartment Substance Stored: Gasoline
 Compartment Other Substance: Not reported
 Tank Release Detection Method: Not reported
 Tank Release Method Detection II: Not reported
 Tank Release Method Detection III: Not reported
 Other Tank Release Method Detection: None
 Tank Release Detection Variance : No Variance
 Pipe Release Detection Method: Not reported

**Actual:
 3623 ft.**

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

KEY GUARD FUEL (Continued)

U001257927

Other Pipe Release Detection Method : None
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Not reported
Tank Corrosion Protection: Not reported
Pipe Corrosion Protection: Not reported
Other Corrosion Protection: None
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 05/08/1986
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address:
Operator Address building: Not reported
Contact Operator Name:
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 11698
Owner Name : JONES JACK G
Owner Address : AMARILLO, TX 79114
Owner Contact Telephone : 806-353-4908
Owner Type : Private or Corporate
Owner Amendment Reason Code : 001
Owner Amendment Date : 12/02/01
Owner Tax ID : 0023606116

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

KEY GUARD FUEL (Continued)

U001257927

Number of Facilities reported by Owner : 0007
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0006
Of Aboveground Storage Tanks : 0013
Operator Effective Date : Not reported
Operator Type : Private or Corporate
Owner Contact Name: J. G. Jones
Date Registration Form Received : 08/86/05
Facility Type : None of the above, or unidentified
Name of Facility Manager : M. DELANO
Title of Facility Manager : SEC.
Facility Manager Phone : 8063745338
Sign Name on Registration Form : J.G. JONES
Title of Signer of Registration Form : OWNER
Date of Signature on Registration Form : 042586
Number of USTs: 0002
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : P O BOX 8145
Region Number : 01
Facility in Ozone non-attainment area : Not reported

Facility ID: 0023605 Tank Installer: Not reported
Tank ID: 2 Installation Date: 01/01/1978
Tank Emptied: No Status Date: 01/31/1989
Capacity: 6000 Unit ID: 00060911

Tank Material of Construction: Steel
Pipe Material of Construction: Steel
Other Materials of Construction: Not reported
Tank Status: Removed from the Ground
Tank Construction & Containment: Not reported
Pipe Construction & Containment: Not reported
Other Construction & Containment: Not reported
Compartment Substance Stored: Gasoline
Compartment Other Substance: Not reported
Tank Release Detection Method: Not reported
Tank Release Method Detection II: Not reported
Tank Release Method Detection III: Not reported
Other Tank Release Method Detection: None
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: Not reported
Other Pipe Release Detection Method : None
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Not reported
Tank Corrosion Protection: Not reported
Pipe Corrosion Protection: Not reported
Other Corrosion Protection: None
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 05/08/1986
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address:

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

KEY GUARD FUEL (Continued)

U001257927

Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Not reported
Compartment Capacity :	0000000
Owner ID :	11698
Owner Name :	JONES JACK G
Owner Address :	AMARILLO, TX 79114
Owner Contact Telephone :	806-353-4908
Owner Type :	Private or Corporate
Owner Amendment Reason Code :	001
Owner Amendment Date :	12/02/01
Owner Tax ID :	0023606116
Number of Facilities reported by Owner :	0007
Mail Undeliverable :	Not reported
Bankruptcy In Effect :	Not reported
# Of Underground Storage Tanks :	0006
# Of Aboveground Storage Tanks :	0013
Operator Effective Date :	Not reported
Operator Type :	Private or Corporate
Owner Contact Name:	J. G. Jones
Date Registration Form Received :	08/86/05
Facility Type :	None of the above, or unidentified
Name of Facility Manager :	M. DELANO
Title of Facility Manager :	SEC.
Facility Manager Phone :	8063745338
Sign Name on Registration Form :	J.G. JONES
Title of Signer of Registration Form :	OWNER

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

KEY GUARD FUEL (Continued)

EDR ID Number
 EPA ID Number

U001257927

Date of Signature on Registration Form : 042586
 Number of USTs: 0002
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : P O BOX 8145
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

**C13
 East
 1/8-1/4
 949 ft.**

**TUNEUP MASTERS INC
 2314 S GEORGIA STREET
 AMARILLO, TX 79109**

**RCRA-SQG 1000224552
 FINDS TXD982285967**

Site 3 of 3 in cluster C

**Relative:
 Higher**

RCRAInfo:
 Owner: TUNEUP MASTERS INC
 (000) 000-0000
 EPA ID: TXD982285967
 Contact: DON SALE
 (818) 999-5600

**Actual:
 3621 ft.**

Classification: Small Quantity Generator
 TSD Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

**D14
 ESE
 1/8-1/4
 978 ft.**

**AUTOHAUS OF AMARILLO INC
 2401 S GEORGIA
 AMARILLO, TX 79109**

**RCRA-SQG 1000696266
 FINDS TXD988070330
 Ind. Haz Waste**

Site 1 of 2 in cluster D

**Relative:
 Higher**

RCRAInfo:
 Owner: DWIGHT L BOGARD
 (806) 358-1110
 EPA ID: TXD988070330
 Contact: JIM TARR
 (806) 353-5555

**Actual:
 3618 ft.**

Classification: Small Quantity Generator
 TSD Activities: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

AUTOHAUS OF AMARILLO INC (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000696266

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

TX IHW:

Registration Number:	76812
Year:	2000
Registration Initial Notification Date:	06/19/1992
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD988070330
TNRCC Permit Number:	031119
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2401 S Georgia, Amarillo, TX
Site Primary Standard Industrial Code:	99990
	Nonclassifiable Establishment
	Public Admin.
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	AUTOHAUS OF AMARILLO INC
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	031119
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010727
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	Tucumcari, NM 88401 - 7008
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Jim Tarr
Contact Telephone Number:	806-353-5555
Registration Number:	76812
Year:	2001
Registration Initial Notification Date:	06/19/1992
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD988070330
TNRCC Permit Number:	031119
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2401 S Georgia, Amarillo, TX
Site Primary Standard Industrial Code:	99990

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AUTOHAUS OF AMARILLO INC (Continued)

1000696266

	Nonclassifiable Establishments
	Nonclassifiable
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	AUTOHAUS OF AMARILLO INC
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	031119
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010727
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	Tucumcari, NM 88401 - 7008
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Jim Tarr
Contact Telephone Number:	806-353-5555
Registration Number:	76812
Year:	2002
Registration Initial Notification Date:	06/19/1992
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD988070330
TNRCC Permit Number:	031119
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2401 S Georgia, Amarillo, TX
Site Primary Standard Industrial Code:	99990
	Nonclassifiable Establishments
	Nonclassifiable
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	AUTOHAUS OF AMARILLO INC
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	031119
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010727
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AUTOHAUS OF AMARILLO INC (Continued)

1000696266

Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	Tucumcari, NM 88401 - 7008
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Jim Tarr
Contact Telephone Number:	806-353-5555
Registration Number:	76812
Year:	2003
Registration Initial Notification Date:	06/19/1992
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD988070330
TNRCC Permit Number:	031119
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2401 S Georgia, Amarillo, TX
Site Primary Standard Industrial Code:	99990
	Nonclassifiable Establishments
	Nonclassifiable
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Autohaus of Amarillo Inc
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	031119
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20030922
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	Tucumcari, NM 88401 - 7008
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Jim Tarr
Contact Telephone Number:	806-353-5555
Registration Number:	76812
Year:	2004
Registration Initial Notification Date:	06/19/1992
Registration Last Amendment Date:	07/27/2001
EPA Identification:	TXD988070330
TNRCC Permit Number:	031119
Revr Has Monthly Reporting Requirement:	9
Description of Facility Site Location:	2401 S Georgia, Amarillo, TX
Site Primary Standard Industrial Code:	99990

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AUTOHAUS OF AMARILLO INC (Continued)

1000696266

Nonclassifiable Establishments
 Nonclassifiable
 Registration is a Generator of Waste: Yes
 Registration is a Receivers of Waste: No
 Registration is a Transporter of Waste: No
 Registration is a Transfer Facility: No
 Mexican Facility: Does not represent a Maquiladora (Mexican Facility)
 Facility Country: Not reported
 Facility Status: Inactive
 Type of Generator: Non-industrial and/or municipal, SQG
 Company Name: Autohaus of Amarillo Inc
 Facility County: Not reported
 TNRCC Region: Not reported
 TNRCC Facility ID : 031119
 Site Owner Tax ID : Not reported
 Site Location Lat/Long : Not reported
 Last Update to NOR Data : 20030922
 Ind. waste permit # : Not reported
 Mun waste permit # : Not reported
 Non Notifier : No
 Facility is STEERS Reporter : No
 Fac Req to Submit Annual Waste Summary Rpt : No
 Facility Involved In Recycling: No
 Mailing Address: PO Box H
 Tucumcari, NM 88401 - 7008
 Mailing County: USA
 Mailing Add 3: PO Box H
 Contact: Jim Tarr
 Contact Telephone Number: 806-353-5555

[Click this hyperlink](#) while viewing on your computer to access additional TX IHW detail in the EDR Site Report.

15
ENE
1/8-1/4
997 ft.

MCBRAYER-DAY BALDWIN PIANO
2100 GEORGIA
AMARILLO, TX 79109

UST U001272972
N/A

Relative:
Higher

UST:
 Facility ID: 0040478 Tank Installer: Not reported
 Tank ID: 1 Installation Date: 01/01/1981
 Tank Emptied: No Status Date: 09/18/1990
 Capacity: 2000 Unit ID: 00107280
 Tank Material of Construction: Steel
 Pipe Material of Construction: Steel
 Other Materials of Construction: Not reported
 Tank Status: Removed from the Ground
 Tank Construction & Containment: Not reported
 Pipe Construction & Containment: Not reported
 Other Construction & Containment: Not reported
 Compartment Substance Stored: Gasoline
 Compartment Other Substance: Not reported
 Tank Release Detection Method: Not reported
 Tank Release Method Detection II: Not reported
 Tank Release Method Detection III: Not reported
 Other Tank Release Method Detection: None
 Tank Release Detection Variance : No Variance
 Pipe Release Detection Method: Not reported
 Other Pipe Release Detection Method : None

Actual:
3625 ft.

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

MCBRAYER-DAY BALDWIN PIANO (Continued)

U001272972

Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Corrosion Protection:	Not reported
Other Corrosion Protection:	None
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	05/08/1986
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Cathodic Protection
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Tested
Compartment Capacity :	0000000
Owner ID :	18408
Owner Name :	MCBRAYER-DAY BALDWIN PIANO
Owner Address :	2100 GEORGIA AMARILLO, TX 79109
Owner Contact Telephone :	806-352-2739
Owner Type :	Private or Corporate
Owner Amendment Reason Code :	035
Owner Amendment Date :	28/01/08
Owner Tax ID :	17561192372

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

MCBRAYER-DAY BALDWIN PIANO (Continued)

U001272972

Number of Facilities reported by Owner : 0001
 Mail Undeliverable : Not reported
 Bankruptcy In Effect : Not reported
 # Of Underground Storage Tanks : 0001
 # Of Aboveground Storage Tanks : 0000
 Operator Effective Date : Not reported
 Operator Type : Private or Corporate
 Owner Contact Name:
 Date Registration Form Received : 08/86/05
 Facility Type : None of the above, or unidentified
 Name of Facility Manager : BILLY C. DAY
 Title of Facility Manager : PARTNER
 Facility Manager Phone : 8063522739
 Sign Name on Registration Form : BILLY C. DAY
 Title of Signer of Registration Form : PARTNER
 Date of Signature on Registration Form : 050586
 Number of USTs: 0001
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

**D16
 ESE
 1/8-1/4
 998 ft.**

**RUSSELL BUICK
 2401 GEORGIA
 AMARILLO, TX 79109**

**RCRA-SQG 1000379646
 FINDS TXD044272334**

Site 2 of 2 in cluster D

**Relative:
 Higher**

RCRAInfo:
 Owner: ERWIN RUSSELL
 (000) 000-0000
 EPA ID: TXD044272334
 Contact: TREY RUSSELL
 (806) 355-4461

**Actual:
 3618 ft.**

Classification: Small Quantity Generator
 TSD Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

Site

Database(s)

EDR ID Number
 EPA ID Number

E17
SSE
1/8-1/4
1104 ft.

AMARILLO IMPORTS INC
3019 WEST 26TH AVENUE
AMARILLO, TX 79109

RCRA-SQG
FINDS
Ind. Haz Waste

1000361970
TXD055290878

Site 1 of 4 in cluster E

Relative:
Higher

RCRAInfo:

Owner: BECKY DODSON
 (000) 000-0000

EPA ID: TXD055290878

Contact: REX BREWER
 (806) 353-1251

Classification: Small Quantity Generator
 TSDF Activities: Not reported

Violation Status: No violations found

Actual:
3613 ft.

FINDS:

Other Pertinent Environmental Activity Identified at Site:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

TX IHW:

Registration Number: 73854
 Year: 1999
 Registration Initial Notification Date: 10/11/1989
 Registration Last Amendment Date: 12/08/1989
 EPA Identification: TXD055290878
 TNRCC Permit Number: Not reported
 Revcr Has Monthly Reporting Requirement: Not reported
 Description of Facility Site Location: Not reported
 Site Primary Standard Industrial Code: 00
 Not reported
 Registration is a Generator of Waste: Yes
 Registration is a Receivers of Waste: No
 Registration is a Transporter of Waste: No
 Registration is a Transfer Facility: No
 Mexican Facility: Does not represent a Maquiladora (Mexican Facility)
 Facility Country: Not reported
 Facility Status: Inactive
 Type of Generator: Non-industrial and/or municipal, CESQG
 Company Name: AMARILLO IMPORTS
 Facility County: Not reported
 TNRCC Region: Not reported
 TNRCC Facility ID : Not reported
 Site Owner Tax ID : Not reported
 Site Location Lat/Long : Not reported
 Last Update to NOR Data : Not reported
 Ind. waste permit # : Not reported
 Mun waste permit # : Not reported
 Non Notifier : Not reported
 Facility is STEERS Reporter : Not reported
 Fac Req to Submit Annual Waste Summary Rpt : Not reported
 Facility Involved In Recycling: Not reported
 Mailing Address: 3019 W 26TH
 AMARILLO, TX 79109

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AMARILLO IMPORTS INC (Continued)

1000361970

Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	REX BREWER
Contact Telephone Number:	806-353-1251
Registration Number:	73854
Year:	2000
Registration Initial Notification Date:	10/11/1989
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD055290878
TNRCC Permit Number:	028263
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	99990
	Nonclassifiable Establishment Public Admin.
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	AMARILLO IMPORTS
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	028263
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20011022
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	3019 W 26TH AMARILLO, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	REX BREWER
Contact Telephone Number:	806-353-1251
Registration Number:	73854
Year:	2001
Registration Initial Notification Date:	10/11/1989
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD055290878
TNRCC Permit Number:	028263
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	99990
	Nonclassifiable Establishments Nonclassifiable
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AMARILLO IMPORTS INC (Continued)

1000361970

Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	AMARILLO IMPORTS
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	028263
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20011022
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	3019 W 26TH AMARILLO, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	REX BREWER
Contact Telephone Number:	806-353-1251
Registration Number:	73854
Year:	2002
Registration Initial Notification Date:	10/11/1989
Registration Last Amendment Date:	08/23/2001
EPA Identification:	TXD055290878
TNRCC Permit Number:	028263
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	99990
	Nonclassifiable Establishments
	Nonclassifiable
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	AMARILLO IMPORTS
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	028263
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20011022
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AMARILLO IMPORTS INC (Continued)

1000361970

Facility Involved In Recycling: Mailing Address: Mailing County: Mailing Add 3: Contact: Contact Telephone Number: Registration Number: Year: Registration Initial Notification Date: Registration Last Amendment Date: EPA Identification: TNRCC Permit Number: Revcr Has Monthly Reporting Requirement: Description of Facility Site Location: Site Primary Standard Industrial Code: Registration is a Generator of Waste: Registration is a Receivers of Waste: Registration is a Transporter of Waste: Registration is a Transfer Facility: Mexican Facility: Facility Country: Facility Status: Type of Generator: Company Name: Facility County: TNRCC Region: TNRCC Facility ID : Site Owner Tax ID : Site Location Lat/Long : Last Update to NOR Data : Ind. waste permit # : Mun waste permit # : Non Notifier : Facility is STEERS Reporter : Fac Req to Submit Annual Waste Summary Rpt : Facility Involved In Recycling: Mailing Address: Mailing County: Mailing Add 3: Contact: Contact Telephone Number: Registration Number: Year: Registration Initial Notification Date: Registration Last Amendment Date: EPA Identification: TNRCC Permit Number: Revcr Has Monthly Reporting Requirement: Description of Facility Site Location: Site Primary Standard Industrial Code:	No 3019 W 26TH AMARILLO, TX 79109 USA Not reported REX BREWER 806-353-1251 73854 2003 10/11/1989 08/23/2001 TXD055290878 028263 Not reported 3019 W 26th, Amarillo, TX 99990 Nonclassifiable Establishments Nonclassifiable Yes No No No Does not represent a Maquiladora (Mexican Facility) Not reported Inactive Non-industrial and/or municipal, CESQG Amarillo Imports Not reported Not reported 028263 Not reported Not reported 20040226 Not reported Not reported No No No No No 3019 W 26th Amarillo, TX 79109 USA Not reported Rex Brewer 806-353-1251 73854 2004 10/11/1989 08/23/2001 TXD055290878 028263 9 3019 W 26th, Amarillo, TX 99990 Nonclassifiable Establishments
--	--

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AMARILLO IMPORTS INC (Continued)

1000361970

	Nonclassifiable
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	USA
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	Amarillo Imports
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	028263
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20040226
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	3019 W 26th Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Rex Brewer
Contact Telephone Number:	806-353-1251
Registration Number:	73854
Year:	98-99
Registration Initial Notification Date:	10/11/1989
Registration Last Amendment Date:	12/08/1989
EPA Identification:	TXD055290878
TNRCC Permit Number:	Not reported
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	00
	Not reported
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	AMARILLO IMPORTS
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	Not reported
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	Not reported
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

AMARILLO IMPORTS INC (Continued)

1000361970

Facility is STEERS Reporter : Not reported
 Fac Req to Submit Annual Waste Summary Rpt : Not reported
 Facility Involved In Recycling: Not reported
 Mailing Address: 3019 W 26TH
 AMARILLO, TX 79109
 Mailing County: USA
 Mailing Add 3: Not reported
 Contact: REX BREWER
 Contact Telephone Number: 806-353-1251

[Click this hyperlink](#) while viewing on your computer to access additional TX IHW detail in the EDR Site Report.

E18
SSE
1/8-1/4
1104 ft.

WALLY MCCARTHYS AMARILLO IMPORT
3019 W 26TH AVE
AMARILLO, TX 79109

UST U001962063
N/A

Site 2 of 4 in cluster E

Relative:
Higher

UST:

Actual:
3613 ft.

Facility ID:	0044263	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1970
Tank Emptied:	No	Status Date:	Not reported
Capacity:	40	Unit ID:	00170863
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	In Use		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Not reported		
Compartment Other Substance:	HYDRAULIC LIFT OIL		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Not reported		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	Not reported		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	09/10/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WALLY MCCARTHYS AMARILLO IMPORT (Continued)

U001962063

Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 20728
Owner Name : WALLY MCCARTHYS AMARILLO IMPORT
Owner Address : 3019 W 26TH AVE
AMARILLO, TX 79109
Owner Contact Telephone : (806) 353-1251
Owner Type : Private or Corporate
Owner Amendment Reason Code : Owner Address Deliverable
Owner Amendment Date : 11/03/09
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0006
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Private or Corporate
Owner Contact Name:
Date Registration Form Received : 10/86/09
Facility Type : None of the above, or unidentified
Name of Facility Manager : PAT L LOCKWOOD
Title of Facility Manager : SERV MGR
Facility Manager Phone : 8063531251
Sign Name on Registration Form : THOMAS P. O'BRIEN
Title of Signer of Registration Form : V.P.,GEN. MGR.
Date of Signature on Registration Form : 090586
Number of USTs: 0006
Number of ASTs: 0000
Facility PO Box : Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

WALLY MCCARTHYS AMARILLO IMPORT (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001962063

Owner PO Box : Not reported
Region Number : 01
Facility in Ozone non-attainment area : Not reported

Facility ID: 0044263
Tank ID: 3
Tank Emptied: No
Capacity: 40

Tank Installer: Not reported
Installation Date: 01/01/1974
Status Date: Not reported
Unit ID: 00170864

Tank Material of Construction: Steel
Pipe Material of Construction: Not reported
Other Materials of Construction: Not reported
Tank Status: In Use
Tank Construction & Containment: Not reported
Pipe Construction & Containment: Not reported
Other Construction & Containment: Not reported
Compartment Substance Stored: Not reported
Compartment Other Substance: HYDRAULIC LIFT OIL
Tank Release Detection Method: Not reported
Tank Release Method Detection II: Not reported
Tank Release Method Detection III: Not reported
Other Tank Release Method Detection: Not reported
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: Not reported
Other Pipe Release Detection Method : Not reported
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Not reported
Tank Corrosion Protection: Not reported
Pipe Corrosion Protection: Not reported
Other Corrosion Protection: Not reported
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 09/10/1986
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address:
Operator Address building: Not reported
Contact Operator Name:
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WALLY MCCARTHYS AMARILLO IMPORT (Continued)

U001962063

Piping Design & Ext. Containment 3 :	Not reported		
Piping Design & Ext. Containment 4 :	Not reported		
Type of Piping :	Not reported		
Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	Not reported		
Pipe Connectors and Valves 2 :	Not reported		
Pipe Connectors and Valves 3 :	Not reported		
Other Tank Corrosion Protection Text:	Not reported		
Tank Corrosion Protection Variance :	No Variance		
Pipe Corrosion Protection 3 :	Not reported		
Pipe Corrosion Protection Variance :	No Variance		
Stage 2 Vapor Recry Equipment Status :	Not reported		
Stage 1 Equipment Installed Date :	Not reported		
Tank Tested :	Not reported		
Compartment Capacity :	0000000		
Owner ID :	20728		
Owner Name :	WALLY MCCARTHYS AMARILLO IMPORT		
Owner Address :	3019 W 26TH AVE AMARILLO, TX 79109		
Owner Contact Telephone :	(806) 353-1251		
Owner Type :	Private or Corporate		
Owner Amendment Reason Code :	Owner Address Deliverable		
Owner Amendment Date :	11/03/09		
Owner Tax ID :	Not reported		
Number of Facilities reported by Owner :	0001		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0006		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Private or Corporate		
Owner Contact Name:			
Date Registration Form Received :	10/86/09		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	PAT L LOCKWOOD		
Title of Facility Manager :	SERV MGR		
Facility Manager Phone :	8063531251		
Sign Name on Registration Form :	THOMAS P. O'BRIEN		
Title of Signer of Registration Form :	V.P., GEN. MGR.		
Date of Signature on Registration Form :	090586		
Number of USTs:	0006		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0044263	Tank Installer:	Not reported
Tank ID:	2	Installation Date:	01/01/1970
Tank Emptied:	No	Status Date:	Not reported
Capacity:	40	Unit ID:	00170865
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	In Use		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WALLY MCCARTHYS AMARILLO IMPORT (Continued)

U001962063

Other Construction & Containment:	Not reported
Compartment Substance Stored:	Not reported
Compartment Other Substance:	HYDRAULIC LIFT OIL
Tank Release Detection Method:	Not reported
Tank Release Method Detection II:	Not reported
Tank Release Method Detection III:	Not reported
Other Tank Release Method Detection:	Not reported
Tank Release Detection Variance :	No Variance
Pipe Release Detection Method:	Not reported
Other Pipe Release Detection Method :	Not reported
Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Corrosion Protection:	Not reported
Other Corrosion Protection:	Not reported
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	09/10/1986
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

WALLY MCCARTHYS AMARILLO IMPORT (Continued)

EDR ID Number
EPA ID Number

Database(s)

U001962063

Compartment Capacity :	0000000		
Owner ID :	20728		
Owner Name :	WALLY MCCARTHYS AMARILLO IMPORT		
Owner Address :	3019 W 26TH AVE AMARILLO, TX 79109		
Owner Contact Telephone :	(806) 353-1251		
Owner Type :	Private or Corporate		
Owner Amendment Reason Code :	Owner Address Deliverable		
Owner Amendment Date :	11/03/09		
Owner Tax ID :	Not reported		
Number of Facilities reported by Owner :	0001		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0006		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Private or Corporate		
Owner Contact Name:			
Date Registration Form Received :	10/86/09		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	PAT L LOCKWOOD		
Title of Facility Manager :	SERV MGR		
Facility Manager Phone :	8063531251		
Sign Name on Registration Form :	THOMAS P. O'BRIEN		
Title of Signer of Registration Form :	V.P.,GEN. MGR.		
Date of Signature on Registration Form :	090586		
Number of USTs:	0006		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0044263	Tank Installer:	Not reported
Tank ID:	6	Installation Date:	01/01/1984
Tank Emptied:	No	Status Date:	Not reported
Capacity:	40	Unit ID:	00170866
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	In Use		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Not reported		
Compartment Other Substance:	HYDRAULIC LIFT OIL		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Not reported		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WALLY MCCARTHYS AMARILLO IMPORT (Continued)

U001962063

Other Corrosion Protection:	Not reported
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	09/10/1986
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Not reported
Compartment Capacity :	0000000
Owner ID :	20728
Owner Name :	WALLY MCCARTHYS AMARILLO IMPORT
Owner Address :	3019 W 26TH AVE AMARILLO, TX 79109
Owner Contact Telephone :	(806) 353-1251
Owner Type :	Private or Corporate
Owner Amendment Reason Code :	Owner Address Deliverable
Owner Amendment Date :	11/03/09
Owner Tax ID :	Not reported
Number of Facilities reported by Owner :	0001
Mail Undeliverable :	Not reported
Bankruptcy In Effect :	Not reported
# Of Underground Storage Tanks :	0006

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WALLY MCCARTHYS AMARILLO IMPORT (Continued)

U001962063

# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Private or Corporate		
Owner Contact Name:			
Date Registration Form Received :	10/86/09		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	PAT L LOCKWOOD		
Title of Facility Manager :	SERV MGR		
Facility Manager Phone :	8063531251		
Sign Name on Registration Form :	THOMAS P. O'BRIEN		
Title of Signer of Registration Form :	V.P.,GEN. MGR.		
Date of Signature on Registration Form :	090586		
Number of USTs:	0006		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0044263	Tank Installer:	Not reported
Tank ID:	5	Installation Date:	01/01/1970
Tank Emptied:	No	Status Date:	Not reported
Capacity:	40	Unit ID:	00170867
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	In Use		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Not reported		
Compartment Other Substance:	HYDRAULIC LIFT OIL		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Not reported		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	Not reported		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	09/10/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WALLY MCCARTHYS AMARILLO IMPORT (Continued)

U001962063

Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Not reported
Compartment Capacity :	0000000
Owner ID :	20728
Owner Name :	WALLY MCCARTHYS AMARILLO IMPORT
Owner Address :	3019 W 26TH AVE AMARILLO, TX 79109
Owner Contact Telephone :	(806) 353-1251
Owner Type :	Private or Corporate
Owner Amendment Reason Code :	Owner Address Deliverable
Owner Amendment Date :	11/03/09
Owner Tax ID :	Not reported
Number of Facilities reported by Owner :	0001
Mail Undeliverable :	Not reported
Bankruptcy In Effect :	Not reported
# Of Underground Storage Tanks :	0006
# Of Aboveground Storage Tanks :	0000
Operator Effective Date :	Not reported
Operator Type :	Private or Corporate
Owner Contact Name:	
Date Registration Form Received :	10/86/09
Facility Type :	None of the above, or unidentified
Name of Facility Manager :	PAT L LOCKWOOD
Title of Facility Manager :	SERV MGR
Facility Manager Phone :	8063531251
Sign Name on Registration Form :	THOMAS P. O'BRIEN
Title of Signer of Registration Form :	V.P.,GEN. MGR.
Date of Signature on Registration Form :	090586
Number of USTs:	0006
Number of ASTs:	0000

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WALLY MCCARTHY'S AMARILLO IMPORT (Continued)

U001962063

Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

[Click this hyperlink](#) while viewing on your computer to access
 1 additional TX UST record(s) in the EDR Site Report.

19
SSW
1/8-1/4
1128 ft.

TOOT N TOTUM 17
2601 PATTERSON
AMARILLO, TX 79109

UST U001276473
N/A

Relative:
Higher

UST:

Actual:
3612 ft.

Facility ID:	0044775	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1987
Tank Emptied:	No	Status Date:	01/03/1997
Capacity:	10000	Unit ID:	00117272
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Vapor Monitoring		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Inventory Control		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Auto. Line Leak Detector(3.0gph for pressure piping)		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Auto. Flow Restrictor Valve		
Spill and Overfill Protection II:	Automatic Delivery Shut-off Valve		
Spill and Overfill Protection III:	Tight-Fill Fitting		
Tank Corrosion Protection:	9		
Tank Corrosion Protection II:	External Coatings - Laminate/Tape/Wrap		
Tank Corrosion Protection III:	Composite Tank (steel w/FRP laminate)		
Pipe Corrosion Protection:	Composite Tank (steel w/FRP laminate)		
Pipe Corrosion Protection II:	None		
Other Corrosion Protection:	Non Corrodible Material		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	04/10/1987		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TOOT N TOTUM 17 (Continued)

U001276473

Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Ext Dielectric Coat/Laminate/T
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 21385
Owner Name : TOOT N TOTUM FOOD STORES LP
Owner Address : 1201 S TAYLOR ST
AMARILLO, TX 79101
Owner Contact Telephone : 806-373-4351
Owner Type : Corporation
Owner Amendment Reason Code : 035
Owner Amendment Date : 17/04/03
Owner Tax ID : 10046393213
Number of Facilities reported by Owner : 0092
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0323
Of Aboveground Storage Tanks : 0002
Operator Effective Date : Not reported
Operator Type : Corporation
Owner Contact Name: DAVID HUDSON
Date Registration Form Received : 10/87/04
Facility Type : None of the above, or unidentified
Name of Facility Manager : Craig Owen
Title of Facility Manager : Pet. Market. Mgr.
Facility Manager Phone : 806-373-4351
Sign Name on Registration Form : GREG MITCHELL
Title of Signer of Registration Form : VP
Date of Signature on Registration Form : 030987
Number of USTs: 0003
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

TOOT N TOTUM 17 (Continued)

EDR ID Number
 EPA ID Number

Database(s)

Region Number :	01	Tank Installer:	Not reported
Facility in Ozone non-attainment area :	Not reported	Installation Date:	01/01/1987
Facility ID:	0044775	Status Date:	01/03/1997
Tank ID:	2	Unit ID:	00117273
Tank Emptied:	No		
Capacity:	10000		
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Vapor Monitoring		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Inventory Control		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Auto. Line Leak Detector(3.0gph for pressure piping)		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Auto. Flow Restrictor Valve		
Spill and Overfill Protection II:	Automatic Delivery Shut-off Valve		
Spill and Overfill Protection III:	Tight-Fill Fitting		
Tank Corrosion Protection:	External Coatings - Laminate/Tape/Wrap		
Tank Corrosion Protection II:	9		
Tank Corrosion Protection III:	External Coatings - Laminate/Tape/Wrap		
Pipe Corrosion Protection:	Composite Tank (steel w/FRP laminate)		
Pipe Corrosion Protection II:	None		
Other Corrosion Protection:	Non Corrodible Material		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	04/10/1987		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		
Signature Title Name:	Not reported		
Signature Type Text:	Not reported		
Certification Submitted Type:	Not reported		
Registration Self-Certification Flag:	Not reported		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Not reported		
Technical standards Self-Certification flag:	Not reported		
UST Delivery Certificate Expiration Date:	Not reported		
Compartment letter:	Not reported		

U001276473

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

TOOT N TOTUM 17 (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U001276473

Financial Responsibility Type:	Not reported	Tank Installer:	Not reported
Corrective Action Met Flag:	Not reported	Installation Date:	01/01/1987
Third Party Met Flag:	Not reported	Status Date:	01/03/1997
Financial Assurance Beginning Date:	Not reported	Unit ID:	00117274
Piping Design & Ext. Containment 3 :	Not reported	Tank Material of Construction:	Steel
Piping Design & Ext. Containment 4 :	Not reported	Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)
Type of Piping :	Not reported		
Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	Not reported		
Pipe Connectors and Valves 2 :	Not reported		
Pipe Connectors and Valves 3 :	Not reported		
Other Tank Corrosion Protection Text:	Cath Protect - Field Instal		
Tank Corrosion Protection Variance :	No Variance		
Pipe Corrosion Protection 3 :	Not reported		
Pipe Corrosion Protection Variance :	No Variance		
Stage 2 Vapor Recry Equipment Status :	Not reported		
Stage 1 Equipment Installed Date :	Not reported		
Tank Tested :	Not reported		
Compartment Capacity :	0000000		
Owner ID :	21385		
Owner Name :	TOOT N TOTUM FOOD STORES LP		
Owner Address :	1201 S TAYLOR ST AMARILLO, TX 79101		
Owner Contact Telephone :	806-373-4351		
Owner Type :	Corporation		
Owner Amendment Reason Code :	035		
Owner Amendment Date :	17/04/03		
Owner Tax ID :	10046393213		
Number of Facilities reported by Owner :	0092		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0323		
# Of Aboveground Storage Tanks :	0002		
Operator Effective Date :	Not reported		
Operator Type :	Corporation		
Owner Contact Name:	DAVID HUDSON		
Date Registration Form Received :	10/87/04		
Facility Type :	None of the above, or unidentified		
Name of Facility Manager :	Craig Owen		
Title of Facility Manager :	Pet. Market. Mgr.		
Facility Manager Phone :	806-373-4351		
Sign Name on Registration Form :	GREG MITCHELL		
Title of Signer of Registration Form :	VP		
Date of Signature on Registration Form :	030987		
Number of USTs:	0003		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0044775		
Tank ID:	3		
Tank Emptied:	No		
Capacity:	10000		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TOOT N TOTUM 17 (Continued)

U001276473

Other Materials of Construction:	Not reported
Tank Status:	Removed from the Ground
Tank Construction & Containment:	Single Wall
Pipe Construction & Containment:	Single Wall
Other Construction & Containment:	Not reported
Compartment Substance Stored:	Gasoline
Compartment Other Substance:	Not reported
Tank Release Detection Method:	Vapor Monitoring
Tank Release Method Detection II:	Not reported
Tank Release Method Detection III:	Not reported
Other Tank Release Method Detection:	Inventory Control
Tank Release Detection Variance :	No Variance
Pipe Release Detection Method:	Auto. Line Leak Detector(3.0gph for pressure piping)
Other Pipe Release Detection Method :	Not reported
Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Auto. Flow Restrictor Valve
Spill and Overfill Protection II:	Automatic Delivery Shut-off Valve
Spill and Overfill Protection III:	Tight-Fill Fitting
Tank Corrosion Protection:	External Coatings - Laminate/Tape/Wrap
Tank Corrosion Protection II:	9
Tank Corrosion Protection III:	External Coatings - Laminate/Tape/Wrap
Pipe Corrosion Protection:	None
Pipe Corrosion Protection II:	Composite Tank (steel w/FRP laminate)
Other Corrosion Protection:	Non Corrodible Material
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	04/10/1987
Installer License Number:	Not reported
Operator Name:	Not reported
Operator Telephone number:	Not reported
Operator Address:	
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	Not reported
Self-Certification date:	Not reported
Signature Name:	Not reported
Signature Title Name:	Not reported
Signature Type Text:	Not reported
Certification Submitted Type:	Not reported
Registration Self-Certification Flag:	Not reported
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Not reported
Technical standards Self-Certification flag:	Not reported
UST Delivery Certificate Expiration Date:	Not reported
Compartment letter:	Not reported
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

TOOT N TOTUM 17 (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U001276473

Pipe Connectors and Valves 2 : Not reported
 Pipe Connectors and Valves 3 : Not reported
 Other Tank Corrosion Protection Text: Cath Protect - Field Instal
 Tank Corrosion Protection Variance : No Variance
 Pipe Corrosion Protection 3 : Not reported
 Pipe Corrosion Protection Variance : No Variance
 Stage 2 Vapor Recry Equipment Status : Not reported
 Stage 1 Equipment Installed Date : Not reported
 Tank Tested : Not reported
 Compartment Capacity : 0000000
 Owner ID : 21385
 Owner Name : TOOT N TOTUM FOOD STORES LP
 Owner Address : 1201 S TAYLOR ST
 AMARILLO, TX 79101
 Owner Contact Telephone : 806-373-4351
 Owner Type : Corporation
 Owner Amendment Reason Code : 035
 Owner Amendment Date : 17/04/03
 Owner Tax ID : 10046393213
 Number of Facilities reported by Owner : 0092
 Mail Undeliverable : Not reported
 Bankruptcy In Effect : Not reported
 # Of Underground Storage Tanks : 0323
 # Of Aboveground Storage Tanks : 0002
 Operator Effective Date : Not reported
 Operator Type : Corporation
 Owner Contact Name: DAVID HUDSON
 Date Registration Form Received : 10/87/04
 Facility Type : None of the above, or unidentified
 Name of Facility Manager : Craig Owen
 Title of Facility Manager : Pet. Market. Mgr.
 Facility Manager Phone : 806-373-4351
 Sign Name on Registration Form : GREG MITCHELL
 Title of Signer of Registration Form : VP
 Date of Signature on Registration Form : 030987
 Number of USTs: 0003
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

E20 **BILL FRANK AUTOMOTIVE**
SSE **3006 W 26TH ST**
1/8-1/4 **AMARILLO, TX 79109**
1128 ft.

RCRA-SQG **1000274222**
FINDS **TXD987987500**
UST
Ind. Haz Waste

Relative:
Higher

Site 3 of 4 in cluster E

Actual:
3612 ft.

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

BILL FRANK AUTOMOTIVE (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000274222

RCRAInfo:
 Owner: WILLIAM M FRANK INC
 (000) 000-0000
 EPA ID: TXD987987500
 Contact: BILL FRANK
 (806) 355-8929
 Classification: Small Quantity Generator
 TSD Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

TX IHW:

Registration Number: 76105
 Year: 1999
 Registration Initial Notification Date: 02/05/1990
 Registration Last Amendment Date: 10/24/1997
 EPA Identification: TXD987987500
 TNRCC Permit Number: Not reported
 Revcr Has Monthly Reporting Requirement: Not reported
 Description of Facility Site Location: 3006 W 26th St., Amarillo, TX
 Site Primary Standard Industrial Code: 00
 Not reported
 Registration is a Generator of Waste: Yes
 Registration is a Receivers of Waste: No
 Registration is a Transporter of Waste: No
 Registration is a Transfer Facility: No
 Mexican Facility: Does not represent a Maquiladora (Mexican Facility)
 Facility Country: Not reported
 Facility Status: Active
 Type of Generator: Non-industrial and/or municipal, SQG
 Company Name: Bill Frank Automotive
 Facility County: Not reported
 TNRCC Region: Not reported
 TNRCC Facility ID : Not reported
 Site Owner Tax ID : Not reported
 Site Location Lat/Long : Not reported
 Last Update to NOR Data : Not reported
 Ind. waste permit # : Not reported
 Mun waste permit # : Not reported
 Non Notifier : Not reported
 Facility is STEERS Reporter : Not reported
 Fac Req to Submit Annual Waste Summary Rpt : Not reported
 Facility Involved In Recycling: Not reported
 Mailing Address: 3006 W 26th St.
 Amarillo, TX 79109
 Mailing County: USA
 Mailing Add 3: Not reported
 Contact: BILL FRANK
 Contact Telephone Number: 806-355-8929

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

BILL FRANK AUTOMOTIVE (Continued)

EDR ID Number
EPA ID Number

Database(s)

1000274222

Registration Number: 76105
Year: 2000
Registration Initial Notification Date: 02/05/1990
Registration Last Amendment Date: 01/27/2001
EPA Identification: TXD987987500
TNRCC Permit Number: 030435
Revcr Has Monthly Reporting Requirement: Not reported
Description of Facility Site Location: 3006 W 26th St., Amarillo, TX
Site Primary Standard Industrial Code: 75380
General Automotive Repair Shops
Services
Registration is a Generator of Waste: Yes
Registration is a Receivers of Waste: No
Registration is a Transporter of Waste: No
Registration is a Transfer Facility: No
Mexican Facility: Does not represent a Maquiladora (Mexican Facility)
Facility Country: Not reported
Facility Status: Active
Type of Generator: Non-industrial and/or municipal, SQG
Company Name: Bill Frank Automotive
Facility County: Not reported
TNRCC Region: Not reported
TNRCC Facility ID : 030435
Site Owner Tax ID : Not reported
Site Location Lat/Long : Not reported
Last Update to NOR Data : 20010222
Ind. waste permit # : Not reported
Mun waste permit # : Not reported
Non Notifier : No
Facility is STEERS Reporter : No
Fac Req to Submit Annual Waste Summary Rpt : Yes
Facility Involved In Recycling: No
Mailing Address: 3006 W 26th St.
Amarillo, TX 79109
Mailing County: USA
Mailing Add 3: Not reported
Contact: BILL FRANK
Contact Telephone Number: 806-355-8929

Registration Number: 76105
Year: 2001
Registration Initial Notification Date: 02/05/1990
Registration Last Amendment Date: 01/27/2001
EPA Identification: TXD987987500
TNRCC Permit Number: 030435
Revcr Has Monthly Reporting Requirement: Not reported
Description of Facility Site Location: 3006 W 26th St Amarillo, TX
Site Primary Standard Industrial Code: 75380
General Automotive Repair Shops
Services
Registration is a Generator of Waste: Yes
Registration is a Receivers of Waste: No
Registration is a Transporter of Waste: No
Registration is a Transfer Facility: No
Mexican Facility: Does not represent a Maquiladora (Mexican Facility)
Facility Country: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

BILL FRANK AUTOMOTIVE (Continued)

1000274222

Facility Status:	Active
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Bill Frank Automotive
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	030435
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20020710
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	Yes
Facility Involved In Recycling:	No
Mailing Address:	3006 W 26th St Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Bill Frank
Contact Telephone Number:	806-355-8929
Registration Number:	76105
Year:	2001
Registration Initial Notification Date:	02/05/1990
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD987987500
TNRCC Permit Number:	030435
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3006 W 26th St., Amarillo, TX
Site Primary Standard Industrial Code:	75380 General Automotive Repair Shops Services
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Active
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Bill Frank Automotive
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	030435
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010222
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	Yes
Facility Involved In Recycling:	No
Mailing Address:	3006 W 26th St. Amarillo, TX 79109
Mailing County:	USA

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

BILL FRANK AUTOMOTIVE (Continued)

1000274222

Mailing Add 3:	Not reported
Contact:	BILL FRANK
Contact Telephone Number:	806-355-8929
Registration Number:	76105
Year:	2002
Registration Initial Notification Date:	02/05/1990
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD987987500
TNRCC Permit Number:	030435
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3006 W 26th St Amarillo, TX
Site Primary Standard Industrial Code:	75380 General Automotive Repair Shops Services
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Active
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Bill Frank Automotive
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	030435
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20020710
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	Yes
Facility Involved In Recycling:	No
Mailing Address:	3006 W 26th St Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Bill Frank
Contact Telephone Number:	806-355-8929
Registration Number:	76105
Year:	2003
Registration Initial Notification Date:	02/05/1990
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD987987500
TNRCC Permit Number:	030435
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3006 W 26th St Amarillo, TX
Site Primary Standard Industrial Code:	75380 General Automotive Repair Shops Services
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

BILL FRANK AUTOMOTIVE (Continued)

1000274222

Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Active
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Bill Frank Automotive
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	030435
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20020710
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	Yes
Facility Involved In Recycling:	No
Mailing Address:	3006 W 26th St Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Bill Frank
Contact Telephone Number:	806-355-8929
Registration Number:	76105
Year:	2004
Registration Initial Notification Date:	02/05/1990
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD987987500
TNRCC Permit Number:	030435
Revcr Has Monthly Reporting Requirement:	8
Description of Facility Site Location:	3006 W 26th St Amarillo, TX
Site Primary Standard Industrial Code:	75380 General Automotive Repair Shops Services
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Active
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Bill Frank Automotive
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	030435
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20020710
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	Yes
Facility Involved In Recycling:	No

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

BILL FRANK AUTOMOTIVE (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000274222

Mailing Address:	3006 W 26th St Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Bill Frank
Contact Telephone Number:	806-355-8929
Registration Number:	76105
Year:	98-99
Registration Initial Notification Date:	02/05/1990
Registration Last Amendment Date:	10/24/1997
EPA Identification:	TXD987987500
TNRCC Permit Number:	Not reported
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3006 W 26th St., Amarillo, TX
Site Primary Standard Industrial Code:	00
	Not reported
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Active
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Bill Frank Automotive
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	Not reported
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	Not reported
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	Not reported
Facility is STEERS Reporter :	Not reported
Fac Req to Submit Annual Waste Summary Rpt :	Not reported
Facility Involved In Recycling:	Not reported
Mailing Address:	3006 W 26th St. Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	BILL FRANK
Contact Telephone Number:	806-355-8929

[Click this hyperlink](#) while viewing on your computer to access additional TX IHW detail in the EDR Site Report.

UST:

Facility ID:	0048161	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1984
Tank Emptied:	No	Status Date:	08/05/1999
Capacity:	500	Unit ID:	00125446
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

BILL FRANK AUTOMOTIVE (Continued)

1000274222

Pipe Construction & Containment: Single Wall
Other Construction & Containment: Not reported
Compartment Substance Stored: Used Oil
Compartment Other Substance: Not reported
Tank Release Detection Method: Not reported
Tank Release Method Detection II: Not reported
Tank Release Method Detection III: Not reported
Other Tank Release Method Detection: Inventory Control
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: Not reported
Other Pipe Release Detection Method : None
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Not reported
Tank Corrosion Protection: Not reported
Pipe Corrosion Protection: Not reported
Other Corrosion Protection: None
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 03/30/1989
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address: Not reported
Operator Address building: Not reported
Contact Operator Name: Not reported
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

BILL FRANK AUTOMOTIVE (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000274222

Tank Tested : Not reported
 Compartment Capacity : 0000000
 Owner ID : 24710
 Owner Name : BILL FRANK AUTOMOTIVE CTR
 Owner Address : 3006 W 26TH ST
 AMARILLO, TX 79109
 Owner Contact Telephone : 806-355-8929
 Owner Type : Private or Corporate
 Owner Amendment Reason Code : 001
 Owner Amendment Date : 12/02/01
 Owner Tax ID : Not reported
 Number of Facilities reported by Owner : 0001
 Mail Undeliverable : Not reported
 Bankruptcy In Effect : Not reported
 # Of Underground Storage Tanks : 0001
 # Of Aboveground Storage Tanks : 0000
 Operator Effective Date : Not reported
 Operator Type : Private or Corporate
 Owner Contact Name: Bill Frank
 Date Registration Form Received : 30/89/03
 Facility Type : Retail
 Name of Facility Manager : FRANK, BILL
 Title of Facility Manager : PRESIDENT
 Facility Manager Phone : 806-355-8929
 Sign Name on Registration Form : SAME
 Title of Signer of Registration Form : SAME
 Date of Signature on Registration Form : 032889
 Number of USTs: 0001
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

E21
SSE
 1/8-1/4
 1142 ft.

MOSS BODY SHOP
3000 W 26TH ST
AMARILLO, TX 79109

RCRA-SQG 1000374074
FINDS TXD981905284
Ind. Haz Waste

Site 4 of 4 in cluster E

Relative:
Higher

RCRAInfo:
 Owner: MOSS BODY SHOP INC
 (806) 355-9208
 EPA ID: TXD981905284
 Contact: DON MOSS
 (806) 355-9208

Actual:
3612 ft.

Classification: Small Quantity Generator
 TSDF Activities: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

MOSS BODY SHOP (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000374074

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

TX IHW:

Registration Number:	73207
Year:	1999
Registration Initial Notification Date:	02/13/1987
Registration Last Amendment Date:	08/20/1998
EPA Identification:	TXD981905284
TNRCC Permit Number:	Not reported
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3000 W 26th ST, Amarillo, TX
Site Primary Standard Industrial Code:	00
	Not reported
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	Moss Body Shop
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	Not reported
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	Not reported
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	Not reported
Facility is STEERS Reporter :	Not reported
Fac Req to Submit Annual Waste Summary Rpt :	Not reported
Facility Involved In Recycling:	Not reported
Mailing Address:	3000 W 26th St. Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	DON MOSS
Contact Telephone Number:	806-355-9208
Registration Number:	73207
Year:	2000
Registration Initial Notification Date:	02/13/1987
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981905284
TNRCC Permit Number:	027635
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3000 W 26th ST, Amarillo, TX
Site Primary Standard Industrial Code:	75320

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

MOSS BODY SHOP (Continued)

1000374074

	Top And Body Repair And Paint Shops Services
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	Moss Body Shop
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	027635
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20011022
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	3000 W 26th St. Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	DON MOSS
Contact Telephone Number:	806-355-9208
Registration Number:	73207
Year:	2001
Registration Initial Notification Date:	02/13/1987
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981905284
TNRCC Permit Number:	027635
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3000 W 26th ST, Amarillo, TX
Site Primary Standard Industrial Code:	75320 Top & Body Repair & Paint Shops Services
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	Moss Body Shop
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	027635
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20011022
Ind. waste permit # :	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

MOSS BODY SHOP (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000374074

Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	3000 W 26th St. Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	DON MOSS
Contact Telephone Number:	806-355-9208
Registration Number:	73207
Year:	2002
Registration Initial Notification Date:	02/13/1987
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981905284
TNRCC Permit Number:	027635
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3000 W 26th ST, Amarillo, TX
Site Primary Standard Industrial Code:	75320 Top & Body Repair & Paint Shops Services
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	Moss Body Shop
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	027635
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20011022
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	3000 W 26th St. Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	DON MOSS
Contact Telephone Number:	806-355-9208
Registration Number:	73207
Year:	2003
Registration Initial Notification Date:	02/13/1987
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981905284
TNRCC Permit Number:	027635

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

MOSS BODY SHOP (Continued)

1000374074

Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3000 W 26th ST, Amarillo, TX
Site Primary Standard Industrial Code:	75320 Top & Body Repair & Paint Shops Services
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	Moss Body Shop
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	027635
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20031029
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	3000 W 26th St Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Don Moss
Contact Telephone Number:	806-355-9208
Registration Number:	73207
Year:	2004
Registration Initial Notification Date:	02/13/1987
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981905284
TNRCC Permit Number:	027635
Revcr Has Monthly Reporting Requirement:	8
Description of Facility Site Location:	3000 W 26th ST, Amarillo, TX
Site Primary Standard Industrial Code:	75320 Top & Body Repair & Paint Shops Services
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	Moss Body Shop
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	027635
Site Owner Tax ID :	Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

MOSS BODY SHOP (Continued)

1000374074

Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20031029
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	3000 W 26th St Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Don Moss
Contact Telephone Number:	806-355-9208
Registration Number:	73207
Year:	98-99
Registration Initial Notification Date:	02/13/1987
Registration Last Amendment Date:	08/20/1998
EPA Identification:	TXD981905284
TNRCC Permit Number:	Not reported
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	3000 W 26th ST, Amarillo, TX
Site Primary Standard Industrial Code:	00
	Not reported
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, CESQG
Company Name:	Moss Body Shop
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	Not reported
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	Not reported
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	Not reported
Facility is STEERS Reporter :	Not reported
Fac Req to Submit Annual Waste Summary Rpt :	Not reported
Facility Involved In Recycling:	Not reported
Mailing Address:	3000 W 26th St. Amarillo, TX 79109
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	DON MOSS
Contact Telephone Number:	806-355-9208

[Click this hyperlink](#) while viewing on your computer to access additional TX IHW detail in the EDR Site Report.

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
 EPA ID Number

22
ENE
1/8-1/4
1172 ft.

WOLFIN SQUARE 66
1901 S GEORGIA
AMARILLO, TX 79109

UST
LTANKS **U001275634**
N/A

Relative:
Higher

LTANKS:

Actual:
3629 ft.

Facility ID: 0043630
 Facility Location: 1901 S GEORGIA
 Reported Date: 9/7/1990
 Entered Date: 12/11/1990
 RPR Coordinator: RPR
 Region: 01
 Region City ID: AMARILLO
 LPST Id: 097486
 Responsible Party: FRED FLOWERS TEXACO STATION
 RP Contact: FRED FLOWERS
 RP Telephone: 806/355-6131
 RP Address: 1901 S GEORGIA
 AMARILLO, TX 79109
 Priority: NO GW IMPACT, NO APPARENT THREATS OR IMPACTS TO RECEPTORS
 Status: **FINAL CONCURRENCE ISSUED, CASE CLOSED**

UST:

Facility ID:	0043630	Tank Installer:	Not reported
Tank ID:	5	Installation Date:	01/01/1984
Tank Emptied:	No	Status Date:	07/18/2005
Capacity:	500	Unit ID:	00115031
Tank Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Used Oil		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Auto Tank Gauging & inv. contr		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Auto. Line Leak Detector(3.0gph for pressure piping)		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Automatic Delivery Shut-off Valve		
Spill and Overfill Protection II:	Factory-Built Spill Container/Bucket/Sump		
Spill and Overfill Protection III:	Tight-Fill Fitting		
Tank Corrosion Protection:	None		
Pipe Corrosion Protection:	None		
Other Corrosion Protection:	Not reported		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/30/1986		
Installer License Number:	Not reported		
Operator Name:	FLOWERS LYNDALL		
Operator Telephone number:	Not reported		
Operator Address:	1901 S GEORGIA		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WOLFIN SQUARE 66 (Continued)

U001275634

AMARILLO, TX 79109
Operator Address building: Not reported
Contact Operator Name:
Contact Operator title: Not reported
Contact Operator Phone: 806-355-2517
Self-Certification date: 040205
Signature Name: LYNDALL F FLOWERS
Signature Title Name: OWNER
Signature Type Text: Owner
Certification Submitted Type: Annual
Registration Self-Certification Flag: Yes
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Yes
Technical standards Self-Certification flag: Yes
UST Delivery Certificate Expiration Date: 20/06/04
Compartment letter: A
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Pressurized
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 41734
Owner Name : FLOWERS LYNDALL
Owner Address : 1901 S GEORGIA
AMARILLO, TX 79109
Owner Contact Telephone : 806-355-2517
Owner Type : Individual
Owner Amendment Reason Code : 035
Owner Amendment Date : 05/04/05
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0005
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Individual
Owner Contact Name: LYNDALL FLOWERS
Date Registration Form Received : 30/86/05
Facility Type : Retail
Name of Facility Manager : LYNDALL FLOWERS
Title of Facility Manager : Not reported
Facility Manager Phone : 806-355-6131

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WOLFIN SQUARE 66 (Continued)

U001275634

Sign Name on Registration Form : LYNDALL FLOWERS
Title of Signer of Registration Form : MGR.
Date of Signature on Registration Form : 052186
Number of USTs: 0005
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : Not reported
Region Number : 01
Facility in Ozone non-attainment area : Not reported

Facility ID: 0043630 Tank Installer: Not reported
Tank ID: 4 Installation Date: 01/01/1984
Tank Emptied: No Status Date: 07/12/2005
Capacity: 8000 Unit ID: 00115032

Tank Material of Construction: Fiberglass-Reinforced Plastic (FRP)
Pipe Material of Construction: Fiberglass-Reinforced Plastic (FRP)
Other Materials of Construction: Not reported
Tank Status: Removed from the Ground
Tank Construction & Containment: Double Wall
Pipe Construction & Containment: Single Wall
Other Construction & Containment: Not reported
Compartment Substance Stored: Used Oil
Compartment Other Substance: Not reported
Tank Release Detection Method: Not reported
Tank Release Method Detection II: Not reported
Tank Release Method Detection III: Not reported
Other Tank Release Method Detection: Auto Tank Gauging & inv. contr
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: Auto. Line Leak Detector(3.0gph for pressure piping)
Other Pipe Release Detection Method : Not reported
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Automatic Delivery Shut-off Valve
Spill and Overfill Protection II: Factory-Built Spill Container/Bucket/Sump
Spill and Overfill Protection III: Tight-Fill Fitting
Tank Corrosion Protection: Cathodic Protection System
Tank Corrosion Protection II: None
Pipe Corrosion Protection: None
Other Corrosion Protection: Not reported
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 05/30/1986
Installer License Number: Not reported
Operator Name: FLOWERS LYNDALL
Operator Telephone number: Not reported
Operator Address: 1901 S GEORGIA

Operator Address building: AMARILLO, TX 79109
Contact Operator Name: Not reported
Contact Operator title: Not reported
Contact Operator Phone: 806-355-2517
Self-Certification date: 040205
Signature Name: LYNDALL F FLOWERS
Signature Title Name: OWNER
Signature Type Text: Owner

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

WOLFIN SQUARE 66 (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U001275634

Facility ID:	0043630	Tank Installer:	Not reported
Tank ID:	2	Installation Date:	01/01/1984
Tank Emptied:	No	Status Date:	07/12/2005
Capacity:	10000	Unit ID:	00115033
Tank Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Double Wall		
Tank Construction & Containment II:	External Jacket System		
Pipe Construction & Containment:	External Jacket System		
Pipe Construction & Containment II:	Double Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Used Oil		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Auto Tank Gauging & inv. contr		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Auto. Line Leak Detector(3.0gph for pressure piping)		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Automatic Delivery Shut-off Valve		
Spill and Overfill Protection II:	Factory-Built Spill Container/Bucket/Sump		
Spill and Overfill Protection III:	Tight-Fill Fitting		
Tank Corrosion Protection:	None		
Tank Corrosion Protection II:	Cathodic Protection System		
Pipe Corrosion Protection:	None		
Other Corrosion Protection:	Not reported		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/30/1986		
Installer License Number:	Not reported		
Operator Name:	FLOWERS LYNDALL		
Operator Telephone number:	Not reported		
Operator Address:	1901 S GEORGIA		
	AMARILLO, TX 79109		
Operator Address building:	Not reported		
Contact Operator Name:	Not reported		
Contact Operator title:	Not reported		
Contact Operator Phone:	806-355-2517		
Self-Certification date:	040205		
Signature Name:	LYNDALL F FLOWERS		
Signature Title Name:	OWNER		
Signature Type Text:	Owner		
Certification Submitted Type:	Annual		
Registration Self-Certification Flag:	Yes		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Yes		
Technical standards Self-Certification flag:	Yes		
UST Delivery Certificate Expiration Date:	20/06/04		
Compartment letter:	A		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

WOLFIN SQUARE 66 (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U001275634

Financial Responsibility Type:	Not reported		
Corrective Action Met Flag:	Not reported		
Third Party Met Flag:	Not reported		
Financial Assurance Beginning Date:	Not reported		
Piping Design & Ext. Containment 3 :	Not reported		
Piping Design & Ext. Containment 4 :	Not reported		
Type of Piping :	Pressurized		
Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	3		
Pipe Connectors and Valves 2 :	1		
Pipe Connectors and Valves 3 :	Not reported		
Other Tank Corrosion Protection Text:	Not reported		
Tank Corrosion Protection Variance :	No Variance		
Pipe Corrosion Protection 3 :	Not reported		
Pipe Corrosion Protection Variance :	No Variance		
Stage 2 Vapor Recry Equipment Status :	Not reported		
Stage 1 Equipment Installed Date :	Not reported		
Tank Tested :	Not reported		
Compartment Capacity :	0000000		
Owner ID :	41734		
Owner Name :	FLOWERS LYNDALL		
Owner Address :	1901 S GEORGIA AMARILLO, TX 79109		
Owner Contact Telephone :	806-355-2517		
Owner Type :	Individual		
Owner Amendment Reason Code :	035		
Owner Amendment Date :	05/04/05		
Owner Tax ID :	Not reported		
Number of Facilities reported by Owner :	0001		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0005		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Individual		
Owner Contact Name:	LYNDALL FLOWERS		
Date Registration Form Received :	30/86/05		
Facility Type :	Retail		
Name of Facility Manager :	LYNDALL FLOWERS		
Title of Facility Manager :	Not reported		
Facility Manager Phone :	806-355-6131		
Sign Name on Registration Form :	LYNDALL FLOWERS		
Title of Signer of Registration Form :	MGR.		
Date of Signature on Registration Form :	052186		
Number of USTs:	0005		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0043630	Tank Installer:	Not reported
Tank ID:	3	Installation Date:	01/01/1984
Tank Emptied:	No	Status Date:	07/12/2005
Capacity:	10000	Unit ID:	00115034
Tank Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WOLFIN SQUARE 66 (Continued)

U001275634

<p>Other Materials of Construction: Tank Status: Tank Construction & Containment: Tank Construction & Containment II: Pipe Construction & Containment: Pipe Construction & Containment II: Other Construction & Containment: Compartment Substance Stored: Compartment Other Substance: Tank Release Detection Method: Tank Release Method Detection II: Tank Release Method Detection III: Other Tank Release Method Detection: Tank Release Detection Variance : Pipe Release Detection Method: Other Pipe Release Detection Method : Pipe Release Detection Variance : Spill and Overfill Protection: Spill and Overfill Protection II: Spill and Overfill Protection III: Tank Corrosion Protection: Tank Corrosion Protection II: Pipe Corrosion Protection: Other Corrosion Protection: Vapor Recovery Equipment Status: Equipment Installed Date: Equipment Installer: Contractor Registration Number: Tank Registration Date: Installer License Number: Operator Name: Operator Telephone number: Operator Address:</p>	<p>Not reported Removed from the Ground Double Wall External Jacket System Double Wall External Jacket System Not reported Used Oil Not reported Not reported Not reported Not reported Auto Tank Gauging & inv. contr No Variance Auto. Line Leak Detector(3.0gph for pressure piping) Not reported No Variance Automatic Delivery Shut-off Valve Factory-Built Spill Container/Bucket/Sump Tight-Fill Fitting Cathodic Protection System None None Not reported Not reported Not reported Not reported 05/30/1986 Not reported FLOWERS LYNDALL Not reported 1901 S GEORGIA</p>
<p>Operator Address building: Contact Operator Name: Contact Operator title: Contact Operator Phone: Self-Certification date: Signature Name: Signature Title Name: Signature Type Text: Certification Submitted Type: Registration Self-Certification Flag: Fees Self-Certification Flag: Financial Assurance Self-Certification flag: Technical standards Self-Certification flag: UST Delivery Certificate Expiration Date: Compartment letter: Financial Responsibility Type: Corrective Action Met Flag: Third Party Met Flag: Financial Assurance Beginning Date: Piping Design & Ext. Containment 3 : Piping Design & Ext. Containment 4 : Type of Piping :</p>	<p>AMARILLO, TX 79109 Not reported Not reported 806-355-2517 040205 LYNDALL F FLOWERS OWNER Owner Annual Yes Not reported Yes Yes 20/06/04 A Not reported Not reported Not reported Not reported Not reported Pressurized</p>

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WOLFIN SQUARE 66 (Continued)

U001275634

Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	3		
Pipe Connectors and Valves 2 :	1		
Pipe Connectors and Valves 3 :	Not reported		
Other Tank Corrosion Protection Text:	Not reported		
Tank Corrosion Protection Variance :	No Variance		
Pipe Corrosion Protection 3 :	Not reported		
Pipe Corrosion Protection Variance :	No Variance		
Stage 2 Vapor Recry Equipment Status :	Not reported		
Stage 1 Equipment Installed Date :	Not reported		
Tank Tested :	Not reported		
Compartment Capacity :	0000000		
Owner ID :	41734		
Owner Name :	FLOWERS LYNDALL		
Owner Address :	1901 S GEORGIA AMARILLO, TX 79109		
Owner Contact Telephone :	806-355-2517		
Owner Type :	Individual		
Owner Amendment Reason Code :	035		
Owner Amendment Date :	05/04/05		
Owner Tax ID :	Not reported		
Number of Facilities reported by Owner :	0001		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0005		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Individual		
Owner Contact Name:	LYNDALL FLOWERS		
Date Registration Form Received :	30/86/05		
Facility Type :	Retail		
Name of Facility Manager :	LYNDALL FLOWERS		
Title of Facility Manager :	Not reported		
Facility Manager Phone :	806-355-6131		
Sign Name on Registration Form :	LYNDALL FLOWERS		
Title of Signer of Registration Form :	MGR.		
Date of Signature on Registration Form :	052186		
Number of USTs:	0005		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0043630	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1984
Tank Emptied:	No	Status Date:	07/12/2005
Capacity:	12000	Unit ID:	00115035
Tank Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Double Wall		
Tank Construction & Containment II:	External Jacket System		
Pipe Construction & Containment:	External Jacket System		
Pipe Construction & Containment II:	Double Wall		
Other Construction & Containment:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WOLFIN SQUARE 66 (Continued)

U001275634

Compartment Substance Stored:	Used Oil
Compartment Other Substance:	Not reported
Tank Release Detection Method:	Not reported
Tank Release Method Detection II:	Not reported
Tank Release Method Detection III:	Not reported
Other Tank Release Method Detection:	Auto Tank Gauging & inv. contr
Tank Release Detection Variance :	No Variance
Pipe Release Detection Method:	Auto. Line Leak Detector(3.0gph for pressure piping)
Other Pipe Release Detection Method :	Not reported
Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Automatic Delivery Shut-off Valve
Spill and Overfill Protection II:	Factory-Built Spill Container/Bucket/Sump
Spill and Overfill Protection III:	Tight-Fill Fitting
Tank Corrosion Protection:	Cathodic Protection System
Tank Corrosion Protection II:	None
Pipe Corrosion Protection:	None
Other Corrosion Protection:	Not reported
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	05/30/1986
Installer License Number:	Not reported
Operator Name:	FLOWERS LYNDALL
Operator Telephone number:	Not reported
Operator Address:	1901 S GEORGIA
	AMARILLO, TX 79109
Operator Address building:	Not reported
Contact Operator Name:	
Contact Operator title:	Not reported
Contact Operator Phone:	806-355-2517
Self-Certification date:	040205
Signature Name:	LYNDALL F FLOWERS
Signature Title Name:	OWNER
Signature Type Text:	Owner
Certification Submitted Type:	Annual
Registration Self-Certification Flag:	Yes
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Yes
Technical standards Self-Certification flag:	Yes
UST Delivery Certificate Expiration Date:	20/06/04
Compartment letter:	A
Financial Responsibility Type:	Not reported
Corrective Action Met Flag:	Not reported
Third Party Met Flag:	Not reported
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Pressurized
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	3
Pipe Connectors and Valves 2 :	1
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WOLFIN SQUARE 66 (Continued)

U001275634

Pipe Corrosion Protection Variance : No Variance
 Stage 2 Vapor Recry Equipment Status : Not reported
 Stage 1 Equipment Installed Date : Not reported
 Tank Tested : Not reported
 Compartment Capacity : 0000000
 Owner ID : 41734
 Owner Name : FLOWERS LYNDALL
 Owner Address : 1901 S GEORGIA
 AMARILLO, TX 79109
 Owner Contact Telephone : 806-355-2517
 Owner Type : Individual
 Owner Amendment Reason Code : 035
 Owner Amendment Date : 05/04/05
 Owner Tax ID : Not reported
 Number of Facilities reported by Owner : 0001
 Mail Undeliverable : Not reported
 Bankruptcy In Effect : Not reported
 # Of Underground Storage Tanks : 0005
 # Of Aboveground Storage Tanks : 0000
 Operator Effective Date : Not reported
 Operator Type : Individual
 Owner Contact Name: LYNDALL FLOWERS
 Date Registration Form Received : 30/86/05
 Facility Type : Retail
 Name of Facility Manager : LYNDALL FLOWERS
 Title of Facility Manager : Not reported
 Facility Manager Phone : 806-355-6131
 Sign Name on Registration Form : LYNDALL FLOWERS
 Title of Signer of Registration Form : MGR.
 Date of Signature on Registration Form : 052186
 Number of USTs: 0005
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

23 TASCOSA GULF
NW 3400 W IH 40
1/8-1/4 AMARILLO, TX 79102
1282 ft.

UST U001244883
N/A

Relative:
Higher

UST:
 Facility ID: 0008561 Tank Installer: Not reported
 Tank ID: 1 Installation Date: 01/01/1966
Actual: Tank Emptied: No Status Date: 01/15/1996
3621 ft. Capacity: 6000 Unit ID: 00022504
 Tank Material of Construction: Steel
 Pipe Material of Construction: Steel
 Other Materials of Construction: Not reported
 Tank Status: Removed from the Ground
 Tank Construction & Containment: Single Wall
 Pipe Construction & Containment: Single Wall
 Other Construction & Containment: Not reported
 Compartment Substance Stored: Gasoline
 Compartment Other Substance: Not reported
 Tank Release Detection Method: Not reported
 Tank Release Method Detection II: Not reported
 Tank Release Method Detection III: Not reported

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TASCOSA GULF (Continued)

U001244883

Other Tank Release Method Detection: None
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: Not reported
Other Pipe Release Detection Method : None
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Not reported
Tank Corrosion Protection: Not reported
Pipe Corrosion Protection: Not reported
Other Corrosion Protection: None
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 05/08/1986
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address:
Operator Address building: Not reported
Contact Operator Name:
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 30265
Owner Name : STEVENS JERRY
Owner Address : 3533 GOODFELLOW LN
AMARILLO, TX 79121
Owner Contact Telephone : (806) 353-6512

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TASCOSA GULF (Continued)

U001244883

Owner Type :	Private or Corporate		
Owner Amendment Reason Code :	001		
Owner Amendment Date :	12/02/01		
Owner Tax ID :	Not reported		
Number of Facilities reported by Owner :	0001		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0004		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Private or Corporate		
Owner Contact Name:	JERRY STEVENS		
Date Registration Form Received :	08/86/05		
Facility Type :	Retail		
Name of Facility Manager :	JERRY STEVENS		
Title of Facility Manager :	Not reported		
Facility Manager Phone :	8063536512		
Sign Name on Registration Form :	ROBERT TIGRETT		
Title of Signer of Registration Form :	MANAGER		
Date of Signature on Registration Form :	042586		
Number of USTs:	0004		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0008561	Tank Installer:	Not reported
Tank ID:	3	Installation Date:	01/01/1966
Tank Emptied:	No	Status Date:	01/15/1996
Capacity:	6000	Unit ID:	00022505
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TASCOSA GULF (Continued)

U001244883

Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address:
Operator Address building: Not reported
Contact Operator Name:
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recy Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 30265
Owner Name : STEVENS JERRY
Owner Address : 3533 GOODFELLOW LN
 AMARILLO, TX 79121
Owner Contact Telephone : (806) 353-6512
Owner Type : Private or Corporate
Owner Amendment Reason Code : 001
Owner Amendment Date : 12/02/01
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0004
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Private or Corporate
Owner Contact Name: JERRY STEVENS
Date Registration Form Received : 08/86/05
Facility Type : Retail

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

TASCOSA GULF (Continued)

EDR ID Number
EPA ID Number

Database(s)

Site _____ U001244883

Name of Facility Manager :	JERRY STEVENS	Tank Installer:	Not reported
Title of Facility Manager :	Not reported	Installation Date:	01/01/1966
Facility Manager Phone :	8063536512	Status Date:	01/15/1996
Sign Name on Registration Form :	ROBERT TIGRETT	Unit ID:	00022506
Title of Signer of Registration Form :	MANAGER		
Date of Signature on Registration Form :	042586		
Number of USTs:	0004		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0008561		
Tank ID:	2		
Tank Emptied:	No		
Capacity:	6000		
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		
Signature Title Name:	Not reported		
Signature Type Text:	Not reported		
Certification Submitted Type:	Not reported		
Registration Self-Certification Flag:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

TASCOSA GULF (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U001244883

Tank ID:	4	Installation Date:	08/31/1987
Tank Emptied:	No	Status Date:	01/15/1996
Capacity:	500	Unit ID:	00022507
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	Not reported		
Operator Telephone number:	Not reported		
Operator Address:			
Operator Address building:	Not reported		
Contact Operator Name:			
Contact Operator title:	Not reported		
Contact Operator Phone:	Not reported		
Self-Certification date:	Not reported		
Signature Name:	Not reported		
Signature Title Name:	Not reported		
Signature Type Text:	Not reported		
Certification Submitted Type:	Not reported		
Registration Self-Certification Flag:	Not reported		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Not reported		
Technical standards Self-Certification flag:	Not reported		
UST Delivery Certificate Expiration Date:	Not reported		
Compartment letter:	Not reported		
Financial Responsibility Type:	Not reported		
Corrective Action Met Flag:	Not reported		
Third Party Met Flag:	Not reported		
Financial Assurance Beginning Date:	Not reported		
Piping Design & Ext. Containment 3 :	Not reported		
Piping Design & Ext. Containment 4 :	Not reported		
Type of Piping :	Not reported		
Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

TASCOSA GULF (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U001244883

Pipe Connectors and Valves 2 : Not reported
 Pipe Connectors and Valves 3 : Not reported
 Other Tank Corrosion Protection Text: None
 Tank Corrosion Protection Variance : No Variance
 Pipe Corrosion Protection 3 : Not reported
 Pipe Corrosion Protection Variance : No Variance
 Stage 2 Vapor Recry Equipment Status : Not reported
 Stage 1 Equipment Installed Date : Not reported
 Tank Tested : Not reported
 Compartment Capacity : 0000000
 Owner ID : 30265
 Owner Name : STEVENS JERRY
 Owner Address : 3533 GOODFELLOW LN
 AMARILLO, TX 79121
 Owner Contact Telephone : (806) 353-6512
 Owner Type : Private or Corporate
 Owner Amendment Reason Code : 001
 Owner Amendment Date : 12/02/01
 Owner Tax ID : Not reported
 Number of Facilities reported by Owner : 0001
 Mail Undeliverable : Not reported
 Bankruptcy In Effect : Not reported
 # Of Underground Storage Tanks : 0004
 # Of Aboveground Storage Tanks : 0000
 Operator Effective Date : Not reported
 Operator Type : Private or Corporate
 Owner Contact Name: JERRY STEVENS
 Date Registration Form Received : 08/86/05
 Facility Type : Retail
 Name of Facility Manager : JERRY STEVENS
 Title of Facility Manager : Not reported
 Facility Manager Phone : 8063536512
 Sign Name on Registration Form : ROBERT TIGRETT
 Title of Signer of Registration Form : MANAGER
 Date of Signature on Registration Form : 042586
 Number of USTs: 0004
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

24
ENE
1/8-1/4
1286 ft.

GEORGIA ST CLEANERS OF AMERICA
1800 S GEORGIA
AMARILLO, TX 79109

RCRA-SQG **1000223382**
FINDS **TXD981060049**
Ind. Haz Waste

Relative:
Higher

Actual:
3631 ft.

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

GEORGIA ST CLEANERS OF AMERICA (Continued)

EDR ID Number
 EPA ID Number

Database(s)

1000223382

RCRAInfo:

Owner: LHF INC
 (000) 000-0000
 EPA ID: TXD981060049
 Contact: JAMES FRAZIER
 (806) 353-3971
 Classification: Small Quantity Generator
 TSD Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

TX IHW:

Registration Number: 69859
 Year: 2004
 Registration Initial Notification Date: 10/10/1986
 Registration Last Amendment Date: 08/23/2001
 EPA Identification: TXD981060049
 TNRCC Permit Number: 024730
 Revcr Has Monthly Reporting Requirement: 9
 Description of Facility Site Location: 1800 S Georgia, Amarillo, TX
 Site Primary Standard Industrial Code: 99990
 Nonclassifiable Establishments
 Nonclassifiable
 Registration is a Generator of Waste: Yes
 Registration is a Receivers of Waste: No
 Registration is a Transporter of Waste: No
 Registration is a Transfer Facility: No
 Mexican Facility: Does not represent a Maquiladora (Mexican Facility)
 Facility Country: Not reported
 Facility Status: Inactive
 Type of Generator: Non-industrial and/or municipal, SQG
 Company Name: Georgia St Cleaners of America
 Facility County: Not reported
 TNRCC Region: Not reported
 TNRCC Facility ID : 024730
 Site Owner Tax ID : Not reported
 Site Location Lat/Long : Not reported
 Last Update to NOR Data : 20030929
 Ind. waste permit # : Not reported
 Mun waste permit # : Not reported
 Non Notifier : No
 Facility is STEERS Reporter : No
 Fac Req to Submit Annual Waste Summary Rpt : No
 Facility Involved In Recycling: No
 Mailing Address: 1800 S Georgia
 Amarillo, TX 79109
 Mailing County: USA
 Mailing Add 3: Not reported
 Contact: Richard Holloway

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

GEORGIA ST CLEANERS OF AMERICA (Continued)

1000223382

Contact Telephone Number: 806-353-4242

[Click this hyperlink](#) while viewing on your computer to access additional TX IHW detail in the EDR Site Report.

25
SW
1/4-1/2
1346 ft.

TOOT N TOTUM FOOD STORES 81
2601 PARAMOUNT
AMARILLO, TX 79109

UST U003038724
LTANKS N/A

Relative:
Higher

LTANKS:

Actual:
3612 ft.

Facility ID: 0045241
 Facility Location: 2601 PARAMOUNT BLVD
 Reported Date: 12/5/1995
 Entered Date: 1/8/1996
 RPR Coordinator: PHG
 Region: 01
 Region City ID: AMARILLO
 LPST Id: 110137
 Responsible Party: DIAMOND SHAMROCK REF & MKTG CO
 RP Contact: HASSAN MOHSENI
 RP Telephone: 972/252-1880
 RP Address: 3900 VALLEY VIEW LN
 IRVING, TX 75062 - 2418
 Priority: GW IMPACTED, NO APPARENT THREATS OR IMPACTS TO RECEPTORS
 Status: **FINAL CONCURRENCE ISSUED, CASE CLOSED**

UST:

Facility ID:	0045241	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1986
Tank Emptied:	No	Status Date:	Not reported
Capacity:	12000	Unit ID:	00118493
Tank Material of Construction:	Composite (steel with FRP laminate)		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	In Use		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	SIR (Stat. Inventory Reconciliation) and Inventory Cntr		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Not reported		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	SIR (Stat. Inventory Reconciliation) and Inventory Cntr		
Pipe Release Detection Method II:	Auto. Line Leak Detector(3.0gph for pressure piping)		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Auto. Flow Restrictor Valve		
Spill and Overfill Protection II:	Automatic Delivery Shut-off Valve		
Spill and Overfill Protection III:	Factory-Built Spill Container/Bucket/Sump		
Tank Corrosion Protection:	Noncorrodible Material (c.g. FRP)		
Tank Corrosion Protection II:	None		
Pipe Corrosion Protection:	None		
Other Corrosion Protection:	Not reported		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TOOT N TOTUM FOOD STORES 81 (Continued)

U003038724

Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	10/08/1987
Installer License Number:	Not reported
Operator Name:	TOOT N TOTUM FOOD STORES LP
Operator Telephone number:	Not reported
Operator Address:	1201 S TAYLOR ST
	AMARILLO, TX 79101 - 4313
Operator Address building:	Not reported
Contact Operator Name:	DAVID HUDSON
Contact Operator title:	PROJECT MANAGER
Contact Operator Phone:	806-373-4351
Self-Certification date:	040506
Signature Name:	David Hudson
Signature Title Name:	Projects Manager
Signature Type Text:	Legally-Authorized Rep of Owner
Certification Submitted Type:	Annual
Registration Self-Certification Flag:	Yes
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Yes
Technical standards Self-Certification flag:	Yes
UST Delivery Certificate Expiration Date:	20/07/05
Compartment letter:	A
Financial Responsibility Type:	Insurance or Risk Retention Group
Corrective Action Met Flag:	Yes
Third Party Met Flag:	Yes
Financial Assurance Beginning Date:	12/31/92
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Pressurized
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	3
Pipe Connectors and Valves 2 :	1
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Tested
Compartment Capacity :	0000000
Owner ID :	21385
Owner Name :	TOOT N TOTUM FOOD STORES LP
Owner Address :	1201 S TAYLOR ST
	AMARILLO, TX 79101
Owner Contact Telephone :	806-373-4351
Owner Type :	Corporation
Owner Amendment Reason Code :	035
Owner Amendment Date :	17/04/03
Owner Tax ID :	10046393213
Number of Facilities reported by Owner :	0092
Mail Undeliverable :	Not reported
Bankruptcy In Effect :	Not reported
# Of Underground Storage Tanks :	0323
# Of Aboveground Storage Tanks :	0002

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

TOOT N TOTUM FOOD STORES 81 (Continued)

U003038724

Operator Effective Date :	Not reported
Operator Type :	Corporation
Owner Contact Name:	DAVID HUDSON
Date Registration Form Received :	08/87/10
Facility Type :	Fleet Refueling
Name of Facility Manager :	.
Title of Facility Manager :	Not reported
Facility Manager Phone :	806-354-7180
Sign Name on Registration Form :	JAMES MANNING
Title of Signer of Registration Form :	DIV MGR
Date of Signature on Registration Form :	050186
Number of USTs:	0004
Number of ASTs:	0000
Facility PO Box :	Not reported
Owner PO Box :	Not reported
Region Number :	01
Facility in Ozone non-attainment area :	Not reported

Facility ID:	0045241	Tank Installer:	Not reported
Tank ID:	2	Installation Date:	01/01/1986
Tank Emptied:	No	Status Date:	Not reported
Capacity:	12000	Unit ID:	00118494

Tank Material of Construction:	Composite (steel with FRP laminate)
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)
Other Materials of Construction:	Not reported
Tank Status:	In Use
Tank Construction & Containment:	Single Wall
Pipe Construction & Containment:	Single Wall
Other Construction & Containment:	Not reported
Compartment Substance Stored:	Gasoline
Compartment Other Substance:	Not reported
Tank Release Detection Method:	SIR (Stat. Inventory Reconciliation) and Inventory Cntr
Tank Release Method Detection II:	Not reported
Tank Release Method Detection III:	Not reported
Other Tank Release Method Detection:	Not reported
Tank Release Detection Variance :	No Variance
Pipe Release Detection Method:	SIR (Stat. Inventory Reconciliation) and Inventory Cntr
Pipe Release Detection Method II:	Auto. Line Leak Detector(3.0gph for pressure piping)
Other Pipe Release Detection Method :	Not reported
Pipe Release Detection Variance :	No Variance
Spill and Overfill Protection:	Auto. Flow Restrictor Valve
Spill and Overfill Protection II:	Automatic Delivery Shut-off Valve
Spill and Overfill Protection III:	Factory-Built Spill Container/Bucket/Sump
Tank Corrosion Protection:	Noncorrodible Material (c.g. FRP)
Tank Corrosion Protection II:	None
Pipe Corrosion Protection:	None
Other Corrosion Protection:	Not reported
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	10/08/1987
Installer License Number:	Not reported
Operator Name:	TOOT N TOTUM FOOD STORES LP
Operator Telephone number:	Not reported
Operator Address:	1201 S TAYLOR ST

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TOOT N TOTUM FOOD STORES 81 (Continued)

U003038724

AMARILLO, TX 79101 - 4313
Operator Address building: Not reported
Contact Operator Name: DAVID HUDSON
Contact Operator title: PROJECT MANAGER
Contact Operator Phone: 806-373-4351
Self-Certification date: 040506
Signature Name: David Hudson
Signature Title Name: Projects Manager
Signature Type Text: Legally-Authorized Rep of Owner
Certification Submitted Type: Annual
Registration Self-Certification Flag: Yes
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Yes
Technical standards Self-Certification flag: Yes
UST Delivery Certificate Expiration Date: 20/07/05
Compartment letter: A
Financial Responsibility Type: Insurance or Risk Retention Group
Corrective Action Met Flag: Yes
Third Party Met Flag: Yes
Financial Assurance Beginning Date: 12/31/92
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Pressurized
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : 3
Pipe Connectors and Valves 2 : 1
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Tested
Compartment Capacity : 0000000
Owner ID : 21385
Owner Name : TOOT N TOTUM FOOD STORES LP
Owner Address : 1201 S TAYLOR ST
AMARILLO, TX 79101
Owner Contact Telephone : 806-373-4351
Owner Type : Corporation
Owner Amendment Reason Code : 035
Owner Amendment Date : 17/04/03
Owner Tax ID : 10046393213
Number of Facilities reported by Owner : 0092
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0323
Of Aboveground Storage Tanks : 0002
Operator Effective Date : Not reported
Operator Type : Corporation
Owner Contact Name: DAVID HUDSON
Date Registration Form Received : 08/87/10
Facility Type : Fleet Refueling
Name of Facility Manager :
Title of Facility Manager : Not reported
Facility Manager Phone : 806-354-7180

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)
EDR ID Number
EPA ID Number

TOOT N TOTUM FOOD STORES 81 (Continued)

U003038724

Sign Name on Registration Form : JAMES MANNING
Title of Signer of Registration Form : DIV MGR
Date of Signature on Registration Form : 050186
Number of USTs: 0004
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : Not reported
Region Number : 01
Facility in Ozone non-attainment area : Not reported

Facility ID: 0045241 Tank Installer: Not reported
Tank ID: 3 Installation Date: 01/01/1986
Tank Emptied: No Status Date: Not reported
Capacity: 12000 Unit ID: 00118495

Tank Material of Construction: Composite (steel with FRP laminate)
Pipe Material of Construction: Fiberglass-Reinforced Plastic (FRP)
Other Materials of Construction: Not reported
Tank Status: In Use
Tank Construction & Containment: Single Wall
Pipe Construction & Containment: Single Wall
Other Construction & Containment: Not reported
Compartment Substance Stored: Gasoline
Compartment Other Substance: Not reported
Tank Release Detection Method: SIR (Stat. Inventory Reconciliation) and Inventory Cntr
Tank Release Method Detection II: Not reported
Tank Release Method Detection III: Not reported
Other Tank Release Method Detection: Not reported
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: SIR (Stat. Inventory Reconciliation) and Inventory Cntr
Pipe Release Detection Method II: Auto. Line Leak Detector(3.0gph for pressure piping)
Other Pipe Release Detection Method : Not reported
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Auto. Flow Restrictor Valve
Spill and Overfill Protection II: Automatic Delivery Shut-off Valve
Spill and Overfill Protection III: Factory-Built Spill Container/Bucket/Sump
Tank Corrosion Protection: None
Tank Corrosion Protection II: Noncorrodible Material (c.g. FRP)
Pipe Corrosion Protection: None
Other Corrosion Protection: Not reported
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 10/08/1987
Installer License Number: Not reported
Operator Name: TOOT N TOTUM FOOD STORES LP
Operator Telephone number: Not reported
Operator Address: 1201 S TAYLOR ST

AMARILLO, TX 79101 - 4313
Operator Address building: Not reported
Contact Operator Name: DAVID HUDSON
Contact Operator title: PROJECT MANAGER
Contact Operator Phone: 806-373-4351
Self-Certification date: 040506
Signature Name: David Hudson
Signature Title Name: Projects Manager

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TOOT N TOTUM FOOD STORES 81 (Continued)

U003038724

Signature Type Text: Legally-Authorized Rep of Owner
Certification Submitted Type: Annual
Registration Self-Certification Flag: Yes
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Yes
Technical standards Self-Certification flag: Yes
UST Delivery Certificate Expiration Date: 20/07/05
Compartment letter: A
Financial Responsibility Type: Insurance or Risk Retention Group
Corrective Action Met Flag: Yes
Third Party Met Flag: Yes
Financial Assurance Beginning Date: 12/31/92
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Pressurized
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : 3
Pipe Connectors and Valves 2 : 1
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Tested
Compartment Capacity : 0000000
Owner ID : 21385
Owner Name : TOOT N TOTUM FOOD STORES LP
Owner Address : 1201 S TAYLOR ST
AMARILLO, TX 79101
Owner Contact Telephone : 806-373-4351
Owner Type : Corporation
Owner Amendment Reason Code : 035
Owner Amendment Date : 17/04/03
Owner Tax ID : 10046393213
Number of Facilities reported by Owner : 0092
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0323
Of Aboveground Storage Tanks : 0002
Operator Effective Date : Not reported
Operator Type : Corporation
Owner Contact Name: DAVID HUDSON
Date Registration Form Received : 08/87/10
Facility Type : Fleet Refueling
Name of Facility Manager :
Title of Facility Manager : Not reported
Facility Manager Phone : 806-354-7180
Sign Name on Registration Form : JAMES MANNING
Title of Signer of Registration Form : DIV MGR
Date of Signature on Registration Form : 050186
Number of USTs: 0004
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : Not reported
Region Number : 01

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s)
 EDR ID Number
 EPA ID Number

TOOT N TOTUM FOOD STORES 81 (Continued)

U003038724

Facility in Ozone non-attainment area : Not reported

Facility ID:	0045241	Tank Installer:	Not reported
Tank ID:	4	Installation Date:	01/01/1986
Tank Emptied:	No	Status Date:	Not reported
Capacity:	12000	Unit ID:	00118496
Tank Material of Construction:	Composite (steel with FRP laminate)		
Pipe Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Other Materials of Construction:	Not reported		
Tank Status:	In Use		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	SIR (Stat. Inventory Reconciliation) and Inventory Cntr		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Not reported		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	SIR (Stat. Inventory Reconciliation) and Inventory Cntr		
Pipe Release Detection Method II:	Auto. Line Leak Detector(3.0gph for pressure piping)		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Auto. Flow Restrictor Valve		
Spill and Overfill Protection II:	Automatic Delivery Shut-off Valve		
Spill and Overfill Protection III:	Factory-Built Spill Container/Bucket/Sump		
Tank Corrosion Protection:	Noncorrodible Material (c.g. FRP)		
Tank Corrosion Protection II:	None		
Pipe Corrosion Protection:	None		
Other Corrosion Protection:	Not reported		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	10/08/1987		
Installer License Number:	Not reported		
Operator Name:	TOOT N TOTUM FOOD STORES LP		
Operator Telephone number:	Not reported		
Operator Address:	1201 S TAYLOR ST		

AMARILLO, TX 79101 - 4313

Operator Address building:	Not reported
Contact Operator Name:	DAVID HUDSON
Contact Operator title:	PROJECT MANAGER
Contact Operator Phone:	806-373-4351
Self-Certification date:	040506
Signature Name:	David Hudson
Signature Title Name:	Projects Manager
Signature Type Text:	Legally-Authorized Rep of Owner
Certification Submitted Type:	Annual
Registration Self-Certification Flag:	Yes
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Yes
Technical standards Self-Certification flag:	Yes
UST Delivery Certificate Expiration Date:	20/07/05
Compartment letter:	A

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

TOOT N TOTUM FOOD STORES 81 (Continued)

U003038724

Financial Responsibility Type: Insurance or Risk Retention Group
Corrective Action Met Flag: Yes
Third Party Met Flag: Yes
Financial Assurance Beginning Date: 12/31/92
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Pressurized
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : 3
Pipe Connectors and Valves 2 : 1
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Tested
Compartment Capacity : 0000000
Owner ID : 21385
Owner Name : TOOT N TOTUM FOOD STORES LP
Owner Address : 1201 S TAYLOR ST
AMARILLO, TX 79101
Owner Contact Telephone : 806-373-4351
Owner Type : Corporation
Owner Amendment Reason Code : 035
Owner Amendment Date : 17/04/03
Owner Tax ID : 10046393213
Number of Facilities reported by Owner : 0092
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0323
Of Aboveground Storage Tanks : 0002
Operator Effective Date : Not reported
Operator Type : Corporation
Owner Contact Name: DAVID HUDSON
Date Registration Form Received : 08/87/10
Facility Type : Fleet Refueling
Name of Facility Manager : .
Title of Facility Manager : Not reported
Facility Manager Phone : 806-354-7180
Sign Name on Registration Form : JAMES MANNING
Title of Signer of Registration Form : DIV MGR
Date of Signature on Registration Form : 050186
Number of USTs: 0004
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : Not reported
Region Number : 01
Facility in Ozone non-attainment area : Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
 EPA ID Number

26
SE
1/4-1/2
1526 ft.

DUPRIEST ACURA
2525 S GEORGIA
AMARILLO, TX 79190

RCRA-SQG
FINDS
UST
Ind. Haz Waste
LTANKS

1000196757
TXD981152077

Relative:
Higher

RCRAInfo:
 Owner: MORBA WOLFLIN
 (806) 358-3333
 EPA ID: TXD981152077
 Contact: LYNN WILSON
 (806) 358-3333
 Classification: Small Quantity Generator
 TSDF Activities: Not reported
 Violation Status: No violations found

Actual:
3617 ft.

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LTANKS:

Facility ID: 0060084
 Facility Location: 2525 S GEORGIA
 Reported Date: 11/23/1991
 Entered Date: 12/16/1991
 RPR Coordinator: RPR
 Region: 01
 Region City ID: AMARILLO
 LPST Id: 101055
 Responsible Party: WOLFLIN MORTGAGE CO
 RP Contact: PATTILOU DAWKINS
 RP Telephone: 806/355-9919
 RP Address: 3401 S AUSTIN ST
 AMARILLO, TX 79109 - 4807
 Priority: SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
 Status: **FINAL CONCURRENCE ISSUED, CASE CLOSED**

TX IHW:

Registration Number: 66730
 Year: 1999
 Registration Initial Notification Date: 09/30/1985
 Registration Last Amendment Date: 12/07/1999
 EPA Identification: TXD981152077
 TNRCC Permit Number: Not reported
 Revcr Has Monthly Reporting Requirement: Not reported
 Description of Facility Site Location: 2525 So. Georgia, Amarillo, Tx 79190
 Site Primary Standard Industrial Code: 00
 Not reported
 Registration is a Generator of Waste: Yes
 Registration is a Receivers of Waste: No
 Registration is a Transporter of Waste: No
 Registration is a Transfer Facility: No
 Mexican Facility: Does not represent a Maquiladora (Mexican Facility)
 Facility Country: Not reported
 Facility Status: Inactive

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

DUPRIEST ACURA (Continued)

1000196757

Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Dupriest Acura
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	Not reported
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	Not reported
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	Not reported
Facility is STEERS Reporter :	Not reported
Fac Req to Submit Annual Waste Summary Rpt :	Not reported
Facility Involved In Recycling:	Not reported
Mailing Address:	2525 S Georgia Amarillo, TX 79190
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Lynn Wilson
Contact Telephone Number:	806-358-3333
Registration Number:	66730
Year:	2000
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981152077
TNRCC Permit Number:	021990
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2525 So. Georgia, Amarillo, Tx 79190
Site Primary Standard Industrial Code:	55110 New And Used Car Dealers Retail Trade
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Dupriest Acura
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	021990
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010130
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	2525 S Georgia Amarillo, TX 79190
Mailing County:	USA
Mailing Add 3:	Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

DUPRIEST ACURA (Continued)

1000196757

Contact:	Lynn Wilson
Contact Telephone Number:	806-358-3333
Registration Number:	66730
Year:	2001
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981152077
TNRCC Permit Number:	021990
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2525 So. Georgia, Amarillo, Tx 79190
Site Primary Standard Industrial Code:	55110 New And Used Car Dealers Retail Trade
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Dupriest Acura
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	021990
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010130
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	2525 S Georgia Amarillo, TX 79190
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Lynn Wilson
Contact Telephone Number:	806-358-3333
Registration Number:	66730
Year:	2002
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981152077
TNRCC Permit Number:	021990
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2525 So. Georgia, Amarillo, Tx 79190
Site Primary Standard Industrial Code:	55110 New And Used Car Dealers Retail Trade
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

DUPRIEST ACURA (Continued)

1000196757

Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Dupriest Acura
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	021990
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010130
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	2525 S Georgia Amarillo, TX 79190
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Lynn Wilson
Contact Telephone Number:	806-358-3333
Registration Number:	66730
Year:	2003
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981152077
TNRCC Permit Number:	021990
Revr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2525 So. Georgia, Amarillo, Tx 79190
Site Primary Standard Industrial Code:	55110 New And Used Car Dealers Retail Trade
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Dupriest Acura
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	021990
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010130
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	2525 S Georgia

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

DUPRIEST ACURA (Continued)

1000196757

Mailing County:	Amarillo, TX 79190
Mailing Add 3:	USA
Contact:	Not reported
Contact Telephone Number:	Lynn Wilson 806-358-3333
Registration Number:	66730
Year:	2004
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	01/27/2001
EPA Identification:	TXD981152077
TNRCC Permit Number:	021990
Revcr Has Monthly Reporting Requirement:	4
Description of Facility Site Location:	2525 So. Georgia, Amarillo, Tx 79190
Site Primary Standard Industrial Code:	55110 New And Used Car Dealers Retail Trade
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No
Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	USA
Facility Status:	Inactive
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Dupriest Acura
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	021990
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	20010130
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	No
Facility is STEERS Reporter :	No
Fac Req to Submit Annual Waste Summary Rpt :	No
Facility Involved In Recycling:	No
Mailing Address:	2525 S Georgia Amarillo, TX 79190
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Lynn Wilson
Contact Telephone Number:	806-358-3333
Registration Number:	66730
Year:	98-99
Registration Initial Notification Date:	09/30/1985
Registration Last Amendment Date:	06/19/1995
EPA Identification:	TXD981152077
TNRCC Permit Number:	Not reported
Revcr Has Monthly Reporting Requirement:	Not reported
Description of Facility Site Location:	2525 So. Georgia, Amarillo, Tx 79190
Site Primary Standard Industrial Code:	00 Not reported
Registration is a Generator of Waste:	Yes
Registration is a Receivers of Waste:	No

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

DUPRIEST ACURA (Continued)

1000196757

Registration is a Transporter of Waste:	No
Registration is a Transfer Facility:	No
Mexican Facility:	Does not represent a Maquiladora (Mexican Facility)
Facility Country:	Not reported
Facility Status:	Active
Type of Generator:	Non-industrial and/or municipal, SQG
Company Name:	Dupriest Acura
Facility County:	Not reported
TNRCC Region:	Not reported
TNRCC Facility ID :	Not reported
Site Owner Tax ID :	Not reported
Site Location Lat/Long :	Not reported
Last Update to NOR Data :	Not reported
Ind. waste permit # :	Not reported
Mun waste permit # :	Not reported
Non Notifier :	Not reported
Facility is STEERS Reporter :	Not reported
Fac Req to Submit Annual Waste Summary Rpt :	Not reported
Facility Involved In Recycling:	Not reported
Mailing Address:	2525 S Georgia Amarillo, TX 79190
Mailing County:	USA
Mailing Add 3:	Not reported
Contact:	Lynn Wilson
Contact Telephone Number:	806-358-3333

[Click this hyperlink](#) while viewing on your computer to access additional TX IHW detail in the EDR Site Report.

UST:

Facility ID:	0060084	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	Not reported
Tank Emptied:	Yes	Status Date:	11/21/1991
Capacity:	550	Unit ID:	00141437
Tank Material of Construction:	Not reported		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Not reported		
Compartment Other Substance:	UNKNOWN		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	None		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

DUPRIEST ACURA (Continued)

1000196757

Contractor Registration Number: Not reported
Tank Registration Date: 09/27/1991
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address:
Operator Address building: Not reported
Contact Operator Name:
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: None
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 35541
Owner Name : WOLFLIN MORTGAGE CO
Owner Address : 2810 BONHAMINGTON
 AMARILLO, TX 79109
Owner Contact Telephone : (806) 355-9291
Owner Type : Private or Corporate
Owner Amendment Reason Code : 001
Owner Amendment Date : 12/93/08
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0001
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Private or Corporate
Owner Contact Name: JIM PATTON

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

DUPRIEST ACURA (Continued)

1000196757

Date Registration Form Received : 27/91/09
 Facility Type : Fleet Refueling
 Name of Facility Manager : JIM PATTON
 Title of Facility Manager : Not reported
 Facility Manager Phone : 8063559291
 Sign Name on Registration Form : JOHN DRAKE
 Title of Signer of Registration Form : CONSULTANT
 Date of Signature on Registration Form : 092591
 Number of USTs: 0001
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

27
SE
1/4-1/2
1826 ft.

WESTGATE CAR WASH & LUBE CENTER
2608 S GEORGIA
AMARILLO, TX 79101

UST U003038722
LTANKS N/A

Relative:
Higher

LTANKS:

Actual:
3619 ft.

Facility ID: 0022381
 Facility Location: 2608 S GEORGIA
 Reported Date: 1/5/1990
 Entered Date: 3/25/1993
 RPR Coordinator: HELEN WELCH
 Region: 01
 Region City ID: AMARILLO
 LPST Id: 104578
 Responsible Party: GAINS GEORGE
 RP Contact: GEORGE GAINES
 RP Telephone: 806/374-5240
 RP Address: 2030 S WASHINGTON
 AMARILLO, TX 79110
 Priority: MINOR SOIL CONTAMINATION - DOES NOT REQUIRE A RAP
 Status: **FINAL CONCURRENCE ISSUED, CASE CLOSED**

UST:

Facility ID:	0022381	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	09/02/1990
Tank Emptied:	No	Status Date:	01/16/1990
Capacity:	1036	Unit ID:	00057304
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Diesel		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Not reported		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WESTGATE CAR WASH & LUBE CENTER (Continued)

U003038722

Spill and Overfill Protection:	Not reported
Tank Corrosion Protection:	Not reported
Pipe Corrosion Protection:	Not reported
Other Corrosion Protection:	Not reported
Vapor Recovery Equipment Status:	Not reported
Equipment Installed Date:	Not reported
Equipment Installer:	Not reported
Contractor Registration Number:	Not reported
Tank Registration Date:	05/08/1986
Installer License Number:	Not reported
Operator Name:	WESTGATE ENTERPRISES LLC
Operator Telephone number:	Not reported
Operator Address:	1201 S TAYLOR ST
	AMARILLO, TX 79101 - 4313
Operator Address building:	Not reported
Contact Operator Name:	CRAIG OWEN
Contact Operator title:	Not reported
Contact Operator Phone:	806-373-4351
Self-Certification date:	020906
Signature Name:	David Hudson
Signature Title Name:	Projects Manager
Signature Type Text:	Legally-Authorized Rep of Owner
Certification Submitted Type:	Annual
Registration Self-Certification Flag:	Yes
Fees Self-Certification Flag:	Not reported
Financial Assurance Self-Certification flag:	Yes
Technical standards Self-Certification flag:	Yes
UST Delivery Certificate Expiration Date:	20/07/03
Compartment letter:	A
Financial Responsibility Type:	Insurance or Risk Retention Group
Corrective Action Met Flag:	Yes
Third Party Met Flag:	Yes
Financial Assurance Beginning Date:	Not reported
Piping Design & Ext. Containment 3 :	Not reported
Piping Design & Ext. Containment 4 :	Not reported
Type of Piping :	Not reported
Internal Tank Lining Date :	00/00/0000
Pipe Connectors and Valves 1 :	Not reported
Pipe Connectors and Valves 2 :	Not reported
Pipe Connectors and Valves 3 :	Not reported
Other Tank Corrosion Protection Text:	Not reported
Tank Corrosion Protection Variance :	No Variance
Pipe Corrosion Protection 3 :	Not reported
Pipe Corrosion Protection Variance :	No Variance
Stage 2 Vapor Recry Equipment Status :	Not reported
Stage 1 Equipment Installed Date :	Not reported
Tank Tested :	Not reported
Compartment Capacity :	0000000
Owner ID :	51953
Owner Name :	WESTGATE ENTERPRISES LLC
Owner Address :	1201 S TAYLOR ST
	AMARILLO, TX 79101
Owner Contact Telephone :	806- 373-4351
Owner Type :	Corporation
Owner Amendment Reason Code :	035
Owner Amendment Date :	18/04/02

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WESTGATE CAR WASH & LUBE CENTER (Continued)

U003038722

Owner Tax ID :	Not reported	
Number of Facilities reported by Owner :	0002	
Mail Undeliverable :	Not reported	
Bankruptcy In Effect :	Not reported	
# Of Underground Storage Tanks :	0011	
# Of Aboveground Storage Tanks :	0000	
Operator Effective Date :	Not reported	
Operator Type :	Corporation	
Owner Contact Name:	DAVID HUDSON	
Date Registration Form Received :	08/86/05	
Facility Type :	Retail	
Name of Facility Manager :	JOE VALDEZ	
Title of Facility Manager :	GENERAL MANAGER	
Facility Manager Phone :	806- 352-9690	
Sign Name on Registration Form :	M.B TYSON	
Title of Signer of Registration Form :	PRES.	
Date of Signature on Registration Form :	042386	
Number of USTs:	0007	
Number of ASTs:	0000	
Facility PO Box :	Not reported	
Owner PO Box :	Not reported	
Region Number :	01	
Facility in Ozone non-attainment area :	Not reported	
Facility ID:	0022381	Tank Installer: Not reported
Tank ID:	3	Installation Date: 09/02/1990
Tank Emptied:	No	Status Date: 01/16/1990
Capacity:	4957	Unit ID: 00057305
Tank Material of Construction:	Steel	
Pipe Material of Construction:	Not reported	
Other Materials of Construction:	Not reported	
Tank Status:	Removed from the Ground	
Tank Construction & Containment:	Not reported	
Pipe Construction & Containment:	Not reported	
Other Construction & Containment:	SCOTCH COAT	
Compartment Substance Stored:	Diesel	
Compartment Other Substance:	Not reported	
Tank Release Detection Method:	Not reported	
Tank Release Method Detection II:	Not reported	
Tank Release Method Detection III:	Not reported	
Other Tank Release Method Detection:	Not reported	
Tank Release Detection Variance :	No Variance	
Pipe Release Detection Method:	Not reported	
Other Pipe Release Detection Method :	Not reported	
Pipe Release Detection Variance :	No Variance	
Spill and Overfill Protection:	Not reported	
Tank Corrosion Protection:	Not reported	
Pipe Corrosion Protection:	Not reported	
Other Corrosion Protection:	Not reported	
Vapor Recovery Equipment Status:	Not reported	
Equipment Installed Date:	Not reported	
Equipment Installer:	Not reported	
Contractor Registration Number:	Not reported	
Tank Registration Date:	05/08/1986	
Installer License Number:	Not reported	
Operator Name:	WESTGATE ENTERPRISES LLC	
Operator Telephone number:	Not reported	

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WESTGATE CAR WASH & LUBE CENTER (Continued)

U003038722

Operator Address: 1201 S TAYLOR ST
AMARILLO, TX 79101 - 4313
Operator Address building: Not reported
Contact Operator Name: CRAIG OWEN
Contact Operator title: Not reported
Contact Operator Phone: 806-373-4351
Self-Certification date: 020906
Signature Name: David Hudson
Signature Title Name: Projects Manager
Signature Type Text: Legally-Authorized Rep of Owner
Certification Submitted Type: Annual
Registration Self-Certification Flag: Yes
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Yes
Technical standards Self-Certification flag: Yes
UST Delivery Certificate Expiration Date: 20/07/03
Compartment letter: A
Financial Responsibility Type: Insurance or Risk Retention Group
Corrective Action Met Flag: Yes
Third Party Met Flag: Yes
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 51953
Owner Name : WESTGATE ENTERPRISES LLC
Owner Address : 1201 S TAYLOR ST
AMARILLO, TX 79101
Owner Contact Telephone : 806- 373-4351
Owner Type : Corporation
Owner Amendment Reason Code : 035
Owner Amendment Date : 18/04/02
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0002
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0011
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Corporation
Owner Contact Name: DAVID HUDSON
Date Registration Form Received : 08/86/05
Facility Type : Retail
Name of Facility Manager : JOE VALDEZ

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WESTGATE CAR WASH & LUBE CENTER (Continued)

U003038722

Title of Facility Manager :	GENERAL MANAGER		
Facility Manager Phone :	806- 352-9690		
Sign Name on Registration Form :	M.B TYSON		
Title of Signer of Registration Form :	PRES.		
Date of Signature on Registration Form :	042386		
Number of USTs:	0007		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0022381	Tank Installer:	Not reported
Tank ID:	2	Installation Date:	09/02/1990
Tank Emptied:	No	Status Date:	01/16/1990
Capacity:	1036	Unit ID:	00057306
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Diesel		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Not reported		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	Not reported		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	WESTGATE ENTERPRISES LLC		
Operator Telephone number:	Not reported		
Operator Address:	1201 S TAYLOR ST		
	AMARILLO, TX 79101 - 4313		
Operator Address building:	Not reported		
Contact Operator Name:	CRAIG OWEN		
Contact Operator title:	Not reported		
Contact Operator Phone:	806-373-4351		
Self-Certification date:	020906		
Signature Name:	David Hudson		
Signature Title Name:	Projects Manager		
Signature Type Text:	Legally-Authorized Rep of Owner		
Certification Submitted Type:	Annual		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WESTGATE CAR WASH & LUBE CENTER (Continued)

U003038722

Registration Self-Certification Flag: Yes
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Yes
Technical standards Self-Certification flag: Yes
UST Delivery Certificate Expiration Date: 20/07/03
Compartment letter: A
Financial Responsibility Type: Insurance or Risk Retention Group
Corrective Action Met Flag: Yes
Third Party Met Flag: Yes
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Not reported
Compartment Capacity : 0000000
Owner ID : 51953
Owner Name : WESTGATE ENTERPRISES LLC
Owner Address : 1201 S TAYLOR ST
AMARILLO, TX 79101
Owner Contact Telephone : 806- 373-4351
Owner Type : Corporation
Owner Amendment Reason Code : 035
Owner Amendment Date : 18/04/02
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0002
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0011
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Corporation
Owner Contact Name: DAVID HUDSON
Date Registration Form Received : 08/86/05
Facility Type : Retail
Name of Facility Manager : JOE VALDEZ
Title of Facility Manager : GENERAL MANAGER
Facility Manager Phone : 806- 352-9690
Sign Name on Registration Form : M.B TYSON
Title of Signer of Registration Form : PRES.
Date of Signature on Registration Form : 042386
Number of USTs: 0007
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : Not reported
Region Number : 01
Facility in Ozone non-attainment area : Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation

MAP FINDINGS

WESTGATE CAR WASH & LUBE CENTER (Continued)

EDR ID Number
 EPA ID Number

Database(s)

U003038722

Facility ID:	0022381	Tank Installer:	Not reported
Tank ID:	5	Installation Date:	09/02/1990
Tank Emptied:	No	Status Date:	01/16/1990
Capacity:	4957	Unit ID:	00057307
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	SCOTCH COAT		
Compartment Substance Stored:	Diesel		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Not reported		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	Not reported		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	Not reported		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	Not reported		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		
Tank Registration Date:	05/08/1986		
Installer License Number:	Not reported		
Operator Name:	WESTGATE ENTERPRISES LLC		
Operator Telephone number:	Not reported		
Operator Address:	1201 S TAYLOR ST		
	AMARILLO, TX 79101 - 4313		
Operator Address building:	Not reported		
Contact Operator Name:	CRAIG OWEN		
Contact Operator title:	Not reported		
Contact Operator Phone:	806-373-4351		
Self-Certification date:	020906		
Signature Name:	David Hudson		
Signature Title Name:	Projects Manager		
Signature Type Text:	Legally-Authorized Rep of Owner		
Certification Submitted Type:	Annual		
Registration Self-Certification Flag:	Yes		
Fees Self-Certification Flag:	Not reported		
Financial Assurance Self-Certification flag:	Yes		
Technical standards Self-Certification flag:	Yes		
UST Delivery Certificate Expiration Date:	20/07/03		
Compartment letter:	A		
Financial Responsibility Type:	Insurance or Risk Retention Group		
Corrective Action Met Flag:	Yes		
Third Party Met Flag:	Yes		
Financial Assurance Beginning Date:	Not reported		
Piping Design & Ext. Containment 3 :	Not reported		

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WESTGATE CAR WASH & LUBE CENTER (Continued)

U003038722

Piping Design & Ext. Containment 4 :	Not reported		
Type of Piping :	Not reported		
Internal Tank Lining Date :	00/00/0000		
Pipe Connectors and Valves 1 :	Not reported		
Pipe Connectors and Valves 2 :	Not reported		
Pipe Connectors and Valves 3 :	Not reported		
Other Tank Corrosion Protection Text:	Not reported		
Tank Corrosion Protection Variance :	No Variance		
Pipe Corrosion Protection 3 :	Not reported		
Pipe Corrosion Protection Variance :	No Variance		
Stage 2 Vapor Recry Equipment Status :	Not reported		
Stage 1 Equipment Installed Date :	Not reported		
Tank Tested :	Not reported		
Compartment Capacity :	0000000		
Owner ID :	51953		
Owner Name :	WESTGATE ENTERPRISES LLC		
Owner Address :	1201 S TAYLOR ST		
	AMARILLO, TX 79101		
Owner Contact Telephone :	806- 373-4351		
Owner Type :	Corporation		
Owner Amendment Reason Code :	035		
Owner Amendment Date :	18/04/02		
Owner Tax ID :	Not reported		
Number of Facilities reported by Owner :	0002		
Mail Undeliverable :	Not reported		
Bankruptcy In Effect :	Not reported		
# Of Underground Storage Tanks :	0011		
# Of Aboveground Storage Tanks :	0000		
Operator Effective Date :	Not reported		
Operator Type :	Corporation		
Owner Contact Name:	DAVID HUDSON		
Date Registration Form Received :	08/86/05		
Facility Type :	Retail		
Name of Facility Manager :	JOE VALDEZ		
Title of Facility Manager :	GENERAL MANAGER		
Facility Manager Phone :	806- 352-9690		
Sign Name on Registration Form :	M.B TYSON		
Title of Signer of Registration Form :	PRES.		
Date of Signature on Registration Form :	042386		
Number of USTs:	0007		
Number of ASTs:	0000		
Facility PO Box :	Not reported		
Owner PO Box :	Not reported		
Region Number :	01		
Facility in Ozone non-attainment area :	Not reported		
Facility ID:	0022381	Tank Installer:	Not reported
Tank ID:	4	Installation Date:	09/02/1990
Tank Emptied:	No	Status Date:	01/16/1990
Capacity:	4957	Unit ID:	00057308
Tank Material of Construction:	Steel		
Pipe Material of Construction:	Not reported		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Not reported		
Pipe Construction & Containment:	Not reported		
Other Construction & Containment:	SCOTCH COAT		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

WESTGATE CAR WASH & LUBE CENTER (Continued)

U003038722

Compartment Substance Stored: Diesel
Compartment Other Substance: Not reported
Tank Release Detection Method: Not reported
Tank Release Method Detection II: Not reported
Tank Release Method Detection III: Not reported
Other Tank Release Method Detection: Not reported
Tank Release Detection Variance : No Variance
Pipe Release Detection Method: Not reported
Other Pipe Release Detection Method : Not reported
Pipe Release Detection Variance : No Variance
Spill and Overfill Protection: Not reported
Tank Corrosion Protection: Not reported
Pipe Corrosion Protection: Not reported
Other Corrosion Protection: None
Vapor Recovery Equipment Status: Not reported
Equipment Installed Date: Not reported
Equipment Installer: Not reported
Contractor Registration Number: Not reported
Tank Registration Date: 05/08/1986
Installer License Number: Not reported
Operator Name: WESTGATE ENTERPRISES LLC
Operator Telephone number: Not reported
Operator Address: 1201 S TAYLOR ST

AMARILLO, TX 79101 - 4313
Operator Address building: Not reported
Contact Operator Name: CRAIG OWEN
Contact Operator title: Not reported
Contact Operator Phone: 806-373-4351
Self-Certification date: 020906
Signature Name: David Hudson
Signature Title Name: Projects Manager
Signature Type Text: Legally-Authorized Rep of Owner
Certification Submitted Type: Annual
Registration Self-Certification Flag: Yes
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Yes
Technical standards Self-Certification flag: Yes
UST Delivery Certificate Expiration Date: 20/07/03
Compartment letter: A
Financial Responsibility Type: Insurance or Risk Retention Group
Corrective Action Met Flag: Yes
Third Party Met Flag: Yes
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Not reported
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

WESTGATE CAR WASH & LUBE CENTER (Continued)

U003038722

Tank Tested : Not reported
 Compartment Capacity : 0000000
 Owner ID : 51953
 Owner Name : WESTGATE ENTERPRISES LLC
 Owner Address : 1201 S TAYLOR ST
 AMARILLO, TX 79101
 Owner Contact Telephone : 806- 373-4351
 Owner Type : Corporation
 Owner Amendment Reason Code : 035
 Owner Amendment Date : 18/04/02
 Owner Tax ID : Not reported
 Number of Facilities reported by Owner : 0002
 Mail Undeliverable : Not reported
 Bankruptcy In Effect : Not reported
 # Of Underground Storage Tanks : 0011
 # Of Aboveground Storage Tanks : 0000
 Operator Effective Date : Not reported
 Operator Type : Corporation
 Owner Contact Name: DAVID HUDSON
 Date Registration Form Received : 08/86/05
 Facility Type : Retail
 Name of Facility Manager : JOE VALDEZ
 Title of Facility Manager : GENERAL MANAGER
 Facility Manager Phone : 806- 352-9690
 Sign Name on Registration Form : M.B TYSON
 Title of Signer of Registration Form : PRES.
 Date of Signature on Registration Form : 042386
 Number of USTs: 0007
 Number of ASTs: 0000
 Facility PO Box : Not reported
 Owner PO Box : Not reported
 Region Number : 01
 Facility in Ozone non-attainment area : Not reported

[Click this hyperlink](#) while viewing on your computer to access
 2 additional TX UST record(s) in the EDR Site Report.

28
WNW
1/4-1/2
2588 ft.

CULLIGAN WATER COND OF AMARILLO
3801 WOLFLIN AVE
AMARILLO, TX 79102

RCRA-SQG **1000696011**
FINDS **TXD988064960**
UST
LTANKS

Relative:
Higher

RCRAInfo:
 Owner: MR ARTHUR W WICKHAM
 (806) 352-1128
 EPA ID: TXD988064960
 Contact: CHARLES JR RIVAS
 (806) 359-1511

Actual:
3612 ft.

Classification: Small Quantity Generator
 TSDF Activities: Not reported

Map ID
 Direction
 Distance
 Distance (ft.)
 Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
 EPA ID Number

CULLIGAN WATER COND OF AMARILLO (Continued)

1000696011

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LTANKS:

Facility ID: 0023968
 Facility Location: 3801 WOLFLIN
 Reported Date: 11/14/1991
 Entered Date: 12/16/1991
 RPR Coordinator: RPR
 Region: 01
 Region City ID: AMARILLO
 LPST Id: 101053
 Responsible Party: WICKHAM INVESTMENT CO
 RP Contact: ARTHUR WICKHAM
 RP Telephone: 806/352-1128
 RP Address: 6007 WINDHAM
 AMARILLO, TX 79109
 Priority: SOIL CONTAMINATION ONLY, REQUIRES FULL SITE ASSESSMENT & RAP
Status: FINAL CONCURRENCE ISSUED, CASE CLOSED

UST:

Facility ID:	0023968	Tank Installer:	Not reported
Tank ID:	1	Installation Date:	01/01/1976
Tank Emptied:	No	Status Date:	11/06/1991
Capacity:	500	Unit ID:	00061709
Tank Material of Construction:	Fiberglass-Reinforced Plastic (FRP)		
Pipe Material of Construction:	Steel		
Other Materials of Construction:	Not reported		
Tank Status:	Removed from the Ground		
Tank Construction & Containment:	Single Wall		
Pipe Construction & Containment:	Single Wall		
Other Construction & Containment:	Not reported		
Compartment Substance Stored:	Gasoline		
Compartment Other Substance:	Not reported		
Tank Release Detection Method:	Not reported		
Tank Release Method Detection II:	Not reported		
Tank Release Method Detection III:	Not reported		
Other Tank Release Method Detection:	Inventory Control		
Tank Release Detection Variance :	No Variance		
Pipe Release Detection Method:	Not reported		
Other Pipe Release Detection Method :	None		
Pipe Release Detection Variance :	No Variance		
Spill and Overfill Protection:	Not reported		
Tank Corrosion Protection:	None		
Tank Corrosion Protection II:	None		
Pipe Corrosion Protection:	Not reported		
Other Corrosion Protection:	None		
Vapor Recovery Equipment Status:	Not reported		
Equipment Installed Date:	Not reported		
Equipment Installer:	Not reported		
Contractor Registration Number:	Not reported		

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s) EDR ID Number
EPA ID Number

CULLIGAN WATER COND OF AMARILLO (Continued)

1000696011

Tank Registration Date: 05/08/1986
Installer License Number: Not reported
Operator Name: Not reported
Operator Telephone number: Not reported
Operator Address:
Operator Address building: Not reported
Contact Operator Name:
Contact Operator title: Not reported
Contact Operator Phone: Not reported
Self-Certification date: Not reported
Signature Name: Not reported
Signature Title Name: Not reported
Signature Type Text: Not reported
Certification Submitted Type: Not reported
Registration Self-Certification Flag: Not reported
Fees Self-Certification Flag: Not reported
Financial Assurance Self-Certification flag: Not reported
Technical standards Self-Certification flag: Not reported
UST Delivery Certificate Expiration Date: Not reported
Compartment letter: Not reported
Financial Responsibility Type: Not reported
Corrective Action Met Flag: Not reported
Third Party Met Flag: Not reported
Financial Assurance Beginning Date: Not reported
Piping Design & Ext. Containment 3 : Not reported
Piping Design & Ext. Containment 4 : Not reported
Type of Piping : Suction
Internal Tank Lining Date : 00/00/0000
Pipe Connectors and Valves 1 : Not reported
Pipe Connectors and Valves 2 : Not reported
Pipe Connectors and Valves 3 : Not reported
Other Tank Corrosion Protection Text: Not reported
Tank Corrosion Protection Variance : No Variance
Pipe Corrosion Protection 3 : Not reported
Pipe Corrosion Protection Variance : No Variance
Stage 2 Vapor Recry Equipment Status : Not reported
Stage 1 Equipment Installed Date : Not reported
Tank Tested : Tested
Compartment Capacity : 0000000
Owner ID : 31443
Owner Name : WICKHAM INVESTMENTS
Owner Address : 6007 WINDHAM
AMARILLO, TX 79109
Owner Contact Telephone : Not reported
Owner Type : Private or Corporate
Owner Amendment Reason Code : 000
Owner Amendment Date : Not reported
Owner Tax ID : Not reported
Number of Facilities reported by Owner : 0001
Mail Undeliverable : Not reported
Bankruptcy In Effect : Not reported
Of Underground Storage Tanks : 0001
Of Aboveground Storage Tanks : 0000
Operator Effective Date : Not reported
Operator Type : Private or Corporate
Owner Contact Name:
Date Registration Form Received : 08/86/05

Map ID
Direction
Distance
Distance (ft.)
Elevation

MAP FINDINGS

CULLIGAN WATER COND OF AMARILLO (Continued)

EDR ID Number
EPA ID Number

Database(s)

Site

1000696011

Facility Type : None of the above, or unidentified
Name of Facility Manager : J.W. GRIMES
Title of Facility Manager : PRES
Facility Manager Phone : 8063554438
Sign Name on Registration Form : J.W. GRIMES
Title of Signer of Registration Form : PRES
Date of Signature on Registration Form : 041186
Number of USTs: 0001
Number of ASTs: 0000
Facility PO Box : Not reported
Owner PO Box : Not reported
Region Number : 01
Facility in Ozone non-attainment area : Not reported

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
AMARILLO	91224866	34TH AND S MONROE	34TH AND S MONROE		ERNS
AMARILLO	1009298297	U. S. DOE - PANTEX PLANT	HIGHWAY 60	79109	ICIS
AMARILLO	S106821239	CITY OF AMARILLO TRANSFER STATION	NO ADDRESS		SWF/LF
AMARILLO	S106821349	HIGH PLAINS BAPTIST HOSPITAL SOLID WASTE	NO ADDRESS		SWF/LF
AMARILLO	S106821416	SAFETY KLEEN AMARILLO LIQUID WASTE TRANS	NO ADDRESS		SWF/LF
AMARILLO	S106821436	TEXAS STATE TECHNICAL INSTITUTE LANDFILL	NO ADDRESS		SWF/LF
AMARILLO	S107790489	CUSTOMIZED SERVICE LANDFILL	NO ADDRESS		SWF/LF
AMARILLO	S106169210	CITY OF AMARILLO LANDFILL	NO ADDRESS		SWF/LF
AMARILLO	S106170027	DWAINE C WARNER LANDFILL	NO ADDRESS		SWF/LF
AMARILLO	S106170659	SMOTHERMAN & SHARP LANDFILL	NO ADDRESS		SWF/LF
AMARILLO	2005708742	1901 S JOHNSON STREET (BNSF AM	1901 S JOHNSON STREET (BNSF AM		HMIRS
AMARILLO	S105778519	U.S. DOE PANTEX PLANT	17 MILES NORTHEAST OF		Ind. Haz Waste
AMARILLO	S105778518	U.S. DOE PANTEX PLANT	17 MILES NORTHEAST OF		Ind. Haz Waste
AMARILLO	1000876586	FORMER ORDNANCE PLANT OF PANTEX	15M NE ON HWY 60	79102	FINDS, RCRA-LQG
MANSFIELD	S107011716	1500 BLOCK OF BROAD ST., SOUTH SIDE OF S	1500 BLOCK OF BROAD ST., SOUTH SIDE OF STREET MANS	79109	TX Spills

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

FEDERAL RECORDS

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/19/2006	Source: EPA
Date Data Arrived at EDR: 05/05/2006	Telephone: N/A
Date Made Active in Reports: 05/22/2006	Last EDR Contact: 05/05/2006
Number of Days to Update: 17	Next Scheduled EDR Contact: 07/31/2006
	Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 8
Telephone: 303-312-6774

EPA Region 4
Telephone 404-562-8033

Proposed NPL: Proposed National Priority List Sites

Date of Government Version: 04/19/2006	Source: EPA
Date Data Arrived at EDR: 05/05/2006	Telephone: N/A
Date Made Active in Reports: 05/22/2006	Last EDR Contact: 05/05/2006
Number of Days to Update: 17	Next Scheduled EDR Contact: 07/31/2006
	Data Release Frequency: Quarterly

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/19/2006	Source: EPA
Date Data Arrived at EDR: 05/05/2006	Telephone: N/A
Date Made Active in Reports: 05/22/2006	Last EDR Contact: 05/05/2006
Number of Days to Update: 17	Next Scheduled EDR Contact: 07/31/2006
	Data Release Frequency: Quarterly

NPL RECOVERY: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991	Source: EPA
Date Data Arrived at EDR: 02/02/1994	Telephone: 202-564-4267
Date Made Active in Reports: 03/30/1994	Last EDR Contact: 05/23/2006
Number of Days to Update: 56	Next Scheduled EDR Contact: 08/21/2006
	Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/01/2006	Source: EPA
Date Data Arrived at EDR: 03/21/2006	Telephone: 703-413-0223
Date Made Active in Reports: 04/13/2006	Last EDR Contact: 06/22/2006
Number of Days to Update: 23	Next Scheduled EDR Contact: 09/18/2006
	Data Release Frequency: Quarterly

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 02/01/2006	Source: EPA
Date Data Arrived at EDR: 03/21/2006	Telephone: 703-413-0223
Date Made Active in Reports: 04/13/2006	Last EDR Contact: 06/23/2006
Number of Days to Update: 23	Next Scheduled EDR Contact: 09/18/2006
	Data Release Frequency: Quarterly

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 03/15/2006	Source: EPA
Date Data Arrived at EDR: 03/17/2006	Telephone: 800-424-9346
Date Made Active in Reports: 04/13/2006	Last EDR Contact: 05/21/2006
Number of Days to Update: 27	Next Scheduled EDR Contact: 09/04/2006
	Data Release Frequency: Quarterly

RCRA: Resource Conservation and Recovery Act Information

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month. Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator off-site to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 03/09/2006	Source: EPA
Date Data Arrived at EDR: 04/27/2006	Telephone: 800-424-9346
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 06/28/2006
Number of Days to Update: 33	Next Scheduled EDR Contact: 08/21/2006
	Data Release Frequency: Quarterly

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2005	Source: National Response Center, United States Coast Guard
Date Data Arrived at EDR: 01/12/2006	Telephone: 202-260-2342
Date Made Active in Reports: 02/21/2006	Last EDR Contact: 04/26/2006
Number of Days to Update: 40	Next Scheduled EDR Contact: 07/24/2006
	Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2005	Source: U.S. Department of Transportation
Date Data Arrived at EDR: 04/14/2006	Telephone: 202-366-4555
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 04/14/2006
Number of Days to Update: 46	Next Scheduled EDR Contact: 07/17/2006
	Data Release Frequency: Annually

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/21/2006	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/27/2006	Telephone: 703-603-8905
Date Made Active in Reports: 05/22/2006	Last EDR Contact: 07/03/2006
Number of Days to Update: 56	Next Scheduled EDR Contact: 10/02/2006
	Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 03/21/2006	Source: Environmental Protection Agency
Date Data Arrived at EDR: 03/27/2006	Telephone: 703-603-8905
Date Made Active in Reports: 05/22/2006	Last EDR Contact: 07/03/2006
Number of Days to Update: 56	Next Scheduled EDR Contact: 10/02/2006
	Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2004	Source: USGS
Date Data Arrived at EDR: 02/08/2005	Telephone: 703-692-8801
Date Made Active in Reports: 08/04/2005	Last EDR Contact: 05/12/2006
Number of Days to Update: 177	Next Scheduled EDR Contact: 08/07/2006
	Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/05/2005	Source: U.S. Army Corps of Engineers
Date Data Arrived at EDR: 01/19/2006	Telephone: 202-528-4285
Date Made Active in Reports: 02/21/2006	Last EDR Contact: 07/03/2006
Number of Days to Update: 33	Next Scheduled EDR Contact: 10/02/2006
	Data Release Frequency: Varies

US BROWNFIELDS: A Listing of Brownfields Sites

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 04/26/2006	Source: Environmental Protection Agency
Date Data Arrived at EDR: 04/27/2006	Telephone: 202-566-2777
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 06/12/2006
Number of Days to Update: 33	Next Scheduled EDR Contact: 09/11/2006
	Data Release Frequency: Semi-Annually

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/14/2004	Source: Department of Justice, Consent Decree Library
Date Data Arrived at EDR: 02/15/2005	Telephone: Varies
Date Made Active in Reports: 04/25/2005	Last EDR Contact: 03/13/2006
Number of Days to Update: 69	Next Scheduled EDR Contact: 07/24/2006
	Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 04/13/2006	Source: EPA
Date Data Arrived at EDR: 04/28/2006	Telephone: 703-416-0223
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 07/06/2006
Number of Days to Update: 32	Next Scheduled EDR Contact: 10/02/2006
	Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 11/04/2005	Source: Department of Energy
Date Data Arrived at EDR: 11/28/2005	Telephone: 505-845-0011
Date Made Active in Reports: 01/30/2006	Last EDR Contact: 06/21/2006
Number of Days to Update: 63	Next Scheduled EDR Contact: 09/18/2006
	Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985	Source: Environmental Protection Agency
Date Data Arrived at EDR: 08/09/2004	Telephone: 800-424-9346
Date Made Active in Reports: 09/17/2004	Last EDR Contact: 06/09/2004
Number of Days to Update: 39	Next Scheduled EDR Contact: N/A
	Data Release Frequency: No Update Planned

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2003	Source: EPA
Date Data Arrived at EDR: 07/13/2005	Telephone: 202-566-0250
Date Made Active in Reports: 08/17/2005	Last EDR Contact: 06/22/2006
Number of Days to Update: 35	Next Scheduled EDR Contact: 09/18/2006
	Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2002	Source: EPA
Date Data Arrived at EDR: 04/14/2006	Telephone: 202-260-5521
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 04/12/2006
Number of Days to Update: 46	Next Scheduled EDR Contact: 07/17/2006
	Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/29/2006	Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Date Data Arrived at EDR: 04/26/2006	Telephone: 202-566-1667
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 06/19/2006
Number of Days to Update: 34	Next Scheduled EDR Contact: 09/18/2006
	Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

Date of Government Version: 03/31/2006	Source: EPA
Date Data Arrived at EDR: 04/26/2006	Telephone: 202-566-1667
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 06/19/2006
Number of Days to Update: 34	Next Scheduled EDR Contact: 09/18/2006
	Data Release Frequency: Quarterly

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2004	Source: EPA
Date Data Arrived at EDR: 05/11/2006	Telephone: 202-564-4203
Date Made Active in Reports: 05/22/2006	Last EDR Contact: 03/06/2006
Number of Days to Update: 11	Next Scheduled EDR Contact: 07/17/2006
	Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 02/13/2006	Source: Environmental Protection Agency
Date Data Arrived at EDR: 04/21/2006	Telephone: 202-564-5088
Date Made Active in Reports: 05/11/2006	Last EDR Contact: 04/11/2006
Number of Days to Update: 20	Next Scheduled EDR Contact: 07/17/2006
	Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 12/27/2005	Source: EPA
Date Data Arrived at EDR: 02/08/2006	Telephone: 202-566-0500
Date Made Active in Reports: 02/27/2006	Last EDR Contact: 06/28/2006
Number of Days to Update: 19	Next Scheduled EDR Contact: 08/07/2006
	Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/12/2006	Source: Nuclear Regulatory Commission
Date Data Arrived at EDR: 04/26/2006	Telephone: 301-415-7169
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 07/03/2006
Number of Days to Update: 34	Next Scheduled EDR Contact: 10/02/2006
	Data Release Frequency: Quarterly

MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/09/2006	Source: Department of Labor, Mine Safety and Health Administration
Date Data Arrived at EDR: 03/29/2006	Telephone: 303-231-5959
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 06/28/2006
Number of Days to Update: 62	Next Scheduled EDR Contact: 09/25/2006
	Data Release Frequency: Semi-Annually

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/27/2006	Source: EPA
Date Data Arrived at EDR: 05/02/2006	Telephone: N/A
Date Made Active in Reports: 05/30/2006	Last EDR Contact: 04/03/2006
Number of Days to Update: 28	Next Scheduled EDR Contact: 07/03/2006
	Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995	Source: EPA
Date Data Arrived at EDR: 07/03/1995	Telephone: 202-564-4104
Date Made Active in Reports: 08/07/1995	Last EDR Contact: 06/05/2006
Number of Days to Update: 35	Next Scheduled EDR Contact: 09/04/2006
	Data Release Frequency: No Update Planned

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/2003
Date Data Arrived at EDR: 06/17/2005
Date Made Active in Reports: 08/04/2005
Number of Days to Update: 48

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 06/30/2006
Next Scheduled EDR Contact: 09/11/2006
Data Release Frequency: Biennially

STATE AND LOCAL RECORDS

SHWS: State Superfund Registry

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 04/07/2006
Date Data Arrived at EDR: 05/19/2006
Date Made Active in Reports: 06/07/2006
Number of Days to Update: 19

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5680
Last EDR Contact: 07/14/2006
Next Scheduled EDR Contact: 10/09/2006
Data Release Frequency: Semi-Annually

IOP: Innocent Owner/Operator Program

Contains information on all sites that are in the IOP. An IOP is an innocent owner or operator whose property is contaminated as a result of a release or migration of contaminants from a source or sources not located on the property, and they did not cause or contribute to the source or sources of contamination.

Date of Government Version: 05/16/2006
Date Data Arrived at EDR: 05/17/2006
Date Made Active in Reports: 06/07/2006
Number of Days to Update: 21

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5894
Last EDR Contact: 05/15/2006
Next Scheduled EDR Contact: 08/07/2006
Data Release Frequency: Quarterly

SWF/LF: Permitted Solid Waste Facilities

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 06/01/2006
Date Data Arrived at EDR: 06/02/2006
Date Made Active in Reports: 07/12/2006
Number of Days to Update: 40

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6706
Last EDR Contact: 05/23/2006
Next Scheduled EDR Contact: 08/21/2006
Data Release Frequency: Quarterly

CLI: Closed Landfill Inventory

Closed and abandoned landfills (permitted as well as unauthorized) across the state of Texas.

Date of Government Version: 08/30/1999
Date Data Arrived at EDR: 09/28/2000
Date Made Active in Reports: 10/30/2000
Number of Days to Update: 32

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6016
Last EDR Contact: 05/01/2006
Next Scheduled EDR Contact: 07/31/2006
Data Release Frequency: Varies

WASTEMGT: Commercial Hazardous & Solid Waste Management Facilities

This list contains commercial recycling facilities and facilities permitted or authorized (interim status) by the Texas Natural Resource Conservation Commission.

Date of Government Version: 11/01/2003
Date Data Arrived at EDR: 02/17/2004
Date Made Active in Reports: 03/04/2004
Number of Days to Update: 16

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2920
Last EDR Contact: 05/04/2006
Next Scheduled EDR Contact: 07/31/2006
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

LTANKS: Leaking Petroleum Storage Tank Database

An inventory of reported leaking petroleum storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 05/04/2006
Date Data Arrived at EDR: 05/08/2006
Date Made Active in Reports: 06/07/2006
Number of Days to Update: 30

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2200
Last EDR Contact: 04/26/2006
Next Scheduled EDR Contact: 07/24/2006
Data Release Frequency: Quarterly

UST: Petroleum Storage Tank Database

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 04/26/2006
Date Data Arrived at EDR: 05/08/2006
Date Made Active in Reports: 05/22/2006
Number of Days to Update: 14

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 04/26/2006
Next Scheduled EDR Contact: 07/24/2006
Data Release Frequency: Quarterly

AST: Petroleum Storage Tank Database

Registered Aboveground Storage Tanks.

Date of Government Version: 04/26/2006
Date Data Arrived at EDR: 05/08/2006
Date Made Active in Reports: 05/25/2006
Number of Days to Update: 17

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 04/26/2006
Next Scheduled EDR Contact: 07/24/2006
Data Release Frequency: Quarterly

LIENS: Environmental Liens Listing

The listing covers TCEQ liens placed against either State Superfund sites or Federal Superfund sites to recover cost incurred by TCEQ.

Date of Government Version: 01/27/2006
Date Data Arrived at EDR: 01/27/2006
Date Made Active in Reports: 02/13/2006
Number of Days to Update: 17

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2209
Last EDR Contact: 07/11/2006
Next Scheduled EDR Contact: 09/18/2006
Data Release Frequency: Varies

DEL SHWS: Deleted Superfund Registry Sites

Sites have been deleted from the state Superfund registry in accordance with the Act, ?361.189

Date of Government Version: 04/07/2006
Date Data Arrived at EDR: 04/26/2006
Date Made Active in Reports: 05/12/2006
Number of Days to Update: 16

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0666
Last EDR Contact: 07/14/2006
Next Scheduled EDR Contact: 10/09/2006
Data Release Frequency: Quarterly

SPILLS: Spills Database

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 04/13/2006
Date Made Active in Reports: 05/12/2006
Number of Days to Update: 29

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0983
Last EDR Contact: 06/19/2006
Next Scheduled EDR Contact: 09/18/2006
Data Release Frequency: Quarterly

AUL: Sites with Controls

Activity and use limitations include both engineering controls and institutional controls.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 04/01/2006
Date Data Arrived at EDR: 05/02/2006
Date Made Active in Reports: 06/07/2006
Number of Days to Update: 36

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5891
Last EDR Contact: 05/02/2006
Next Scheduled EDR Contact: 07/31/2006
Data Release Frequency: Varies

VCP: Voluntary Cleanup Program Database

The Texas Voluntary Cleanup Program was established to provide administrative, technical, and legal incentives to encourage the cleanup of contaminated sites in Texas.

Date of Government Version: 04/01/2006
Date Data Arrived at EDR: 05/02/2006
Date Made Active in Reports: 06/07/2006
Number of Days to Update: 36

Source: Texas Commission on Environmental Quality
Telephone: 512-239-5891
Last EDR Contact: 05/02/2006
Next Scheduled EDR Contact: 07/31/2006
Data Release Frequency: Quarterly

VCP: Voluntary Cleanup Program Sites

The Voluntary Cleanup Program (RRC-VCP) provides an incentive to remediate Oil & Gas related pollution by participants as long as they did not cause or contribute to the contamination. Applicants to the program receive a release of liability to the state in exchange for a successful cleanup.

Date of Government Version: 04/10/2006
Date Data Arrived at EDR: 05/02/2006
Date Made Active in Reports: 05/12/2006
Number of Days to Update: 10

Source: Railroad Commission of Texas
Telephone: 512-463-6969
Last EDR Contact: 05/02/2006
Next Scheduled EDR Contact: 07/31/2006
Data Release Frequency: Varies

DRYCLEANERS: Drycleaner Registration Database Listing

A listing of drycleaning facilities.

Date of Government Version: 04/04/2006
Date Data Arrived at EDR: 04/04/2006
Date Made Active in Reports: 05/12/2006
Number of Days to Update: 38

Source: Texas Commission on Environmental Quality
Telephone: 512-239-2160
Last EDR Contact: 07/03/2006
Next Scheduled EDR Contact: 10/02/2006
Data Release Frequency: Varies

BROWNFIELDS: Brownfields Site Assessments

Brownfield site assessments that are being cleaned under EPA grant monies.

Date of Government Version: 04/01/2006
Date Data Arrived at EDR: 05/02/2006
Date Made Active in Reports: 05/12/2006
Number of Days to Update: 10

Source: TCEQ
Telephone: 512-239-5872
Last EDR Contact: 05/02/2006
Next Scheduled EDR Contact: 07/31/2006
Data Release Frequency: Semi-Annually

ENFORCEMENT: Notice of Violations Listing

A listing of permit violations.

Date of Government Version: 06/21/2006
Date Data Arrived at EDR: 06/27/2006
Date Made Active in Reports: 07/12/2006
Number of Days to Update: 15

Source: Texas Commission on Environmental Quality
Telephone: 512-239-6012
Last EDR Contact: 06/05/2006
Next Scheduled EDR Contact: 09/04/2006
Data Release Frequency: Semi-Annually

Ind. Haz Waste: Industrial & Hazardous Waste Database

Summary reports reported by waste handlers, generators and shippers in Texas.

Date of Government Version: 12/31/2004
Date Data Arrived at EDR: 05/16/2005
Date Made Active in Reports: 06/09/2005
Number of Days to Update: 24

Source: Texas Commission on Environmental Quality
Telephone: 512-239-0985
Last EDR Contact: 05/01/2006
Next Scheduled EDR Contact: 07/31/2006
Data Release Frequency: Annually

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

ED AQUIF: Edwards Aquifer Permits

A listing of permits in the Edwards Aquifer Protection Program database. The information provided is for the counties located in the Austin Region (Hays, Travis, and Williamson counties).

Date of Government Version: 05/10/2006
Date Data Arrived at EDR: 05/11/2006
Date Made Active in Reports: 06/07/2006
Number of Days to Update: 27

Source: Texas Commission on Environmental Quality, Austin Region
Telephone: 512-339-2929
Last EDR Contact: 05/08/2006
Next Scheduled EDR Contact: 07/24/2006
Data Release Frequency: Varies

AIRS: Current Emission Inventory Data

The database lists by company, along with their actual emissions, the TNRCC air accounts that emit EPA criteria pollutants.

Date of Government Version: 08/31/2005
Date Data Arrived at EDR: 01/25/2006
Date Made Active in Reports: 03/08/2006
Number of Days to Update: 42

Source: Texas Commission on Environmental Quality
Telephone: N/A
Last EDR Contact: 07/14/2006
Next Scheduled EDR Contact: 10/09/2006
Data Release Frequency: Semi-Annually

TRIBAL RECORDS

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2004
Date Data Arrived at EDR: 02/08/2005
Date Made Active in Reports: 08/04/2005
Number of Days to Update: 177

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 05/12/2006
Next Scheduled EDR Contact: 08/07/2006
Data Release Frequency: Semi-Annually

INDIAN UST: USTs on Indian Land

Date of Government Version: 12/14/2005
Date Data Arrived at EDR: 12/14/2005
Date Made Active in Reports: 01/23/2006
Number of Days to Update: 40

Source: Environmental Protection Agency, Region 6
Telephone: 214-665-7591
Last EDR Contact: 05/23/2006
Next Scheduled EDR Contact: 08/21/2006
Data Release Frequency: Varies

EDR PROPRIETARY RECORDS

Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Historical Auto Stations: EDR Proprietary Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Historical Cleaners: EDR Proprietary Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2004
Date Data Arrived at EDR: 02/17/2006
Date Made Active in Reports: 04/07/2006
Number of Days to Update: 49

Source: Department of Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 06/14/2006
Next Scheduled EDR Contact: 09/11/2006
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2004
Date Data Arrived at EDR: 04/24/2006
Date Made Active in Reports: 05/02/2006
Number of Days to Update: 8

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 07/05/2006
Next Scheduled EDR Contact: 10/02/2006
Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 05/02/2006
Date Data Arrived at EDR: 05/31/2006
Date Made Active in Reports: 06/27/2006
Number of Days to Update: 27

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/31/2006
Next Scheduled EDR Contact: 08/28/2006
Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 05/04/2006
Date Made Active in Reports: 06/06/2006
Number of Days to Update: 33

Source: Department of Environmental Protection
Telephone: N/A
Last EDR Contact: 06/12/2006
Next Scheduled EDR Contact: 09/11/2006
Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 09/30/2005
Date Data Arrived at EDR: 05/09/2006
Date Made Active in Reports: 05/24/2006
Number of Days to Update: 15

Source: Department of Environmental Management
Telephone: 401-222-2797
Last EDR Contact: 06/19/2006
Next Scheduled EDR Contact: 09/18/2006
Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data

Hazardous waste manifest information.

Date of Government Version: 12/31/2004
Date Data Arrived at EDR: 03/17/2006
Date Made Active in Reports: 05/17/2006
Number of Days to Update: 61

Source: Department of Environmental Conservation
Telephone: 802-241-3443
Last EDR Contact: 05/15/2006
Next Scheduled EDR Contact: 08/14/2006
Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 03/17/2006
Date Made Active in Reports: 05/02/2006
Number of Days to Update: 46

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 07/11/2006
Next Scheduled EDR Contact: 10/09/2006
Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data

Source: PennWell Corporation

Telephone: (800) 823-6277

This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Child Care Facility List

Source: Department of Protective & Regulatory Services

Telephone: 512-438-3269

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2006 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

GEOCHECK[®] - PHYSICAL SETTING SOURCE ADDENDUM

TARGET PROPERTY ADDRESS

BLUCHER S. THARP MEMORIAL USARC
2801 DUNIVEN CIRCLE
AMARILLO, TX 79109

TARGET PROPERTY COORDINATES

Latitude (North):	35.19010 - 35° 11' 24.4"
Longitude (West):	101.8706 - 101° 52' 14.2"
Universal Tranverse Mercator:	Zone 14
UTM X (Meters):	238617.2
UTM Y (Meters):	3897702.0
Elevation:	3612 ft. above sea level

USGS TOPOGRAPHIC MAP

Target Property Map:	35101-B8 AMARILLO WEST, TX
Most Recent Revision:	1973
East Map:	35101-B7 AMARILLO EAST, TX
Most Recent Revision:	1973

EDR's GeoCheck Physical Setting Source Addendum is provided to assist the environmental professional in forming an opinion about the impact of potential contaminant migration.

Assessment of the impact of contaminant migration generally has two principle investigative components:

1. Groundwater flow direction, and
2. Groundwater flow velocity.

Groundwater flow direction may be impacted by surface topography, hydrology, hydrogeology, characteristics of the soil, and nearby wells. Groundwater flow velocity is generally impacted by the nature of the geologic strata.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW DIRECTION INFORMATION

Groundwater flow direction for a particular site is best determined by a qualified environmental professional using site-specific well data. If such data is not reasonably ascertainable, it may be necessary to rely on other sources of information, such as surface topographic information, hydrologic information, hydrogeologic data collected on nearby properties, and regional groundwater flow information (from deep aquifers).


TOPOGRAPHIC INFORMATION

Surface topography may be indicative of the direction of surficial groundwater flow. This information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

TARGET PROPERTY TOPOGRAPHY

General Topographic Gradient: General SSW

SURROUNDING TOPOGRAPHY: ELEVATION PROFILES



Source: Topography has been determined from the USGS 7.5' Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

HYDROLOGIC INFORMATION

Surface water can act as a hydrologic barrier to groundwater flow. Such hydrologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Refer to the Physical Setting Source Map following this summary for hydrologic information (major waterways and bodies of water).

FEMA FLOOD ZONE

<u>Target Property County</u> POTTER, TX	FEMA Flood <u>Electronic Data</u> YES - refer to the Overview Map and Detail Map
Flood Plain Panel at Target Property:	4805290023A
Additional Panels in search area:	4805290022A 4805290033A 4805290032A

NATIONAL WETLAND INVENTORY

<u>NWI Quad at Target Property</u> AMARILLO EAST	NWI Electronic <u>Data Coverage</u> Not Available
---	---

HYDROGEOLOGIC INFORMATION

Hydrogeologic information obtained by installation of wells on a specific site can often be an indicator of groundwater flow direction in the immediate area. Such hydrogeologic information can be used to assist the environmental professional in forming an opinion about the impact of nearby contaminated properties or, should contamination exist on the target property, what downgradient sites might be impacted.

Site-Specific Hydrogeological Data:*

Search Radius:	1.25 miles
Status:	Not found

AQUIFLOW®

Search Radius: 1.000 Mile.

EDR has developed the AQUIFLOW Information System to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted by environmental professionals to regulatory authorities at select sites and has extracted the date of the report, groundwater flow direction as determined hydrogeologically, and the depth to water table.

<u>MAP ID</u>	<u>LOCATION</u> <u>FROM TP</u>	<u>GENERAL DIRECTION</u> <u>GROUNDWATER FLOW</u>
Not Reported		

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

GROUNDWATER FLOW VELOCITY INFORMATION

Groundwater flow velocity information for a particular site is best determined by a qualified environmental professional using site specific geologic and soil strata data. If such data are not reasonably ascertainable, it may be necessary to rely on other sources of information, including geologic age identification, rock stratigraphic unit and soil characteristics data collected on nearby properties and regional soil information. In general, contaminant plumes move more quickly through sandy-gravelly types of soils than silty-clayey types of soils.

GEOLOGIC INFORMATION IN GENERAL AREA OF TARGET PROPERTY

Geologic information can be used by the environmental professional in forming an opinion about the relative speed at which contaminant migration may be occurring.

ROCK STRATIGRAPHIC UNIT

Era: Cenozoic
System: Tertiary
Series: Pliocene
Code: Tpc (*decoded above as Era, System & Series*)

GEOLOGIC AGE IDENTIFICATION

Category: Continental Deposits

Geologic Age and Rock Stratigraphic Unit Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - a digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

DOMINANT SOIL COMPOSITION IN GENERAL AREA OF TARGET PROPERTY

The U.S. Department of Agriculture's (USDA) Soil Conservation Service (SCS) leads the National Cooperative Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps. The following information is based on Soil Conservation Service STATSGO data.

Soil Component Name: PULLMAN

Soil Surface Texture: silty clay loam

Hydrologic Group: Class D - Very slow infiltration rates. Soils are clayey, have a high water table, or are shallow to an impervious layer.

Soil Drainage Class: Well drained. Soils have intermediate water holding capacity. Depth to water table is more than 6 feet.

Hydric Status: Soil does not meet the requirements for a hydric soil.

Corrosion Potential - Uncoated Steel: HIGH

Depth to Bedrock Min: > 60 inches

Depth to Bedrock Max: > 60 inches

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

Soil Layer Information							
Layer	Boundary		Soil Texture Class	Classification		Permeability Rate (in/hr)	Soil Reaction (pH)
	Upper	Lower		AASHTO Group	Unified Soil		
1	0 inches	6 inches	silty clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay Soils.	Max: 0.60 Min: 0.20	Max: 7.30 Min: 6.60
2	6 inches	38 inches	clay	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay Soils.	Max: 0.20 Min: 0.06	Max: 7.80 Min: 7.40
3	38 inches	52 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay Soils.	Max: 0.20 Min: 0.06	Max: 8.40 Min: 7.40
4	52 inches	78 inches	clay loam	Silt-Clay Materials (more than 35 pct. passing No. 200), Clayey Soils.	FINE-GRAINED SOILS, Silts and Clays (liquid limit less than 50%), Lean Clay Soils.	Max: 0.20 Min: 0.06	Max: 8.40 Min: 7.90

OTHER SOIL TYPES IN AREA

Based on Soil Conservation Service STATSGO data, the following additional subordinant soil types may appear within the general area of target property.

Soil Surface Textures: clay loam
clay

Surficial Soil Types: clay loam
clay

Shallow Soil Types: No Other Soil Types

Deeper Soil Types: clay
loam

LOCAL / REGIONAL WATER AGENCY RECORDS

EDR Local/Regional Water Agency records provide water well information to assist the environmental professional in assessing sources that may impact ground water flow direction, and in forming an opinion about the impact of contaminant migration on nearby drinking water wells.

GEOCHECK® - PHYSICAL SETTING SOURCE SUMMARY

WELL SEARCH DISTANCE INFORMATION

<u>DATABASE</u>	<u>SEARCH DISTANCE (miles)</u>
Federal USGS	1.000
Federal FRDS PWS	Nearest PWS within 1 mile
State Database	1.000

FEDERAL USGS WELL INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>	<u>LOCATION FROM TP</u>
No Wells Found		

FEDERAL FRDS PUBLIC WATER SUPPLY SYSTEM INFORMATION


<u>MAP ID</u>	<u>WELL ID</u>	<u>LOCATION FROM TP</u>
No PWS System Found		

Note: PWS System location is not always the same as well location.

STATE DATABASE WELL INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>	<u>LOCATION FROM TP</u>
A1	TXD1041034	1/8 - 1/4 Mile SE
A2	TXD1041035	1/8 - 1/4 Mile SE
3	TXD1041095	1/4 - 1/2 Mile NNE
4	TXD1041052	1/4 - 1/2 Mile East
5	TXD1041024	1/4 - 1/2 Mile SE
B6	TXD1041047	1/2 - 1 Mile West
B7	TXD1041048	1/2 - 1 Mile West
B8	TXD1041049	1/2 - 1 Mile West
C9	TXD1041059	1/2 - 1 Mile West
D10	TXD1041081	1/2 - 1 Mile WNW
C11	TXD1041069	1/2 - 1 Mile West
C12	TXD1041068	1/2 - 1 Mile West
D13	TXD1041080	1/2 - 1 Mile WNW
C14	TXD1041063	1/2 - 1 Mile West
C15	TXD1041062	1/2 - 1 Mile West
C16	TXD1041061	1/2 - 1 Mile West
C17	TXD1041066	1/2 - 1 Mile West
C18	TXD1041065	1/2 - 1 Mile West
C19	TXD1041064	1/2 - 1 Mile West
C20	TXD1041060	1/2 - 1 Mile West
C21	TXD1041067	1/2 - 1 Mile West
E22	TXD1041057	1/2 - 1 Mile West
E23	TXD1041056	1/2 - 1 Mile West
E24	TXD1041058	1/2 - 1 Mile West

PHYSICAL SETTING SOURCE MAP - 1715338.2s



- County Boundary
- Major Roads
- Contour Lines
- Earthquake epicenter, Richter 5 or greater
- Water Wells
- Public Water Supply Wells
- Cluster of Multiple Icons

- Groundwater Flow Direction
- Indeterminate Groundwater Flow at Location
- Groundwater Flow Varies at Location
- Closest Hydrogeological Data
- Oil or gas wells (in certain Texas counties)

SITE NAME: Blucher S. Tharp Memorial USARC
 ADDRESS: 2801 Duniven Circle
 Amarillo TX 79109
 LAT/LONG: 35.1901 / 101.8706

CLIENT: ENSAFE
 CONTACT: Phil Hardy
 INQUIRY #: 1715338.2s
 DATE: July 14, 2006

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
 Direction
 Distance
 Elevation

Database EDR ID Number

A1
SE
1/8 - 1/4 Mile
Higher

TX WELLS TXD1041034

Rec id:	38814		
Edr site i:	12145	Edr record:	1
Owner name:	Home Depot	Ownerwell:	MW-3, 4 & 5
Address:	2455 Paces Ferry Rd. NW	Citystatez:	Atlanta ,GA30303
Grid:	06-50-4		
Waddress:	Georgia & Duniven Circle		
Wcitystate:	Amarillo ,TX79109	Lat:	35° 11 17N
Wcounty:	Randall	Lon:	101° 52 05 W
Elevation:	No Data	Gpsused:	No Data
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	7/12/2005	Completedd:	7/13/2005
Diameter:	6.25 in From Surface To	85 ft	
Dmethod:	Air Rotary		
Bcompleto:	Not Reported		
Packedfrom:	60 ft to	85 ft	
Packsiz:	Not Reported		
Finterval:	From 0 ft to	60 ft with	20 (#sacks and material)
Sinterval:	No Data		
Tinterval:	No Data		
Usedmethod:	Positive Placement	Cementedby:	Peterson Drilling & Testing, Inc.
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No Data	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companynam:	Peterson Drilling & Testing, Inc.	Companyadd:	P.O. Box 30699
Ccitystate:	Amarillo , TX 79120	Licensenum:	54243
Wsignature:	Roy Wedell	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescrip:	0-1 - Concrete1-17 - Reddish Brown Silty Clay17-85 - Reddish Brown Silty Clay with Caliche		
Typesettin:	2 - New - PVC Casing - 0 to 65 - SCH.402 - New - PVC Screen - 65 to 85 - .020		
Oid :	633		

A2
SE
1/8 - 1/4 Mile
Higher

TX WELLS TXD1041035

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Rec id:	38816	Edr record:	1
Edr site i:	12143	Ownerwell:	MW-1 & MW-2
Owner name:	Home Depot	Citystatez:	Atlanta ,GA30303
Address:	2455 Paces Ferry Rd. NW		
Grid:	06-50-4		
Waddress:	Georgia & Duniven Circle		
Wcitystate:	Amarillo ,TX79109	Lat:	35° 11 17N
Wcounty:	Randall	Lon:	101° 52 05 W
Elevation:	No Data	Gpsused:	No Data
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	7/11/2005	Completedd:	7/11/2005
Diameter:	6.25 in From Surface To	90 ft	
Dmethod:	Air Rotary		
Bcompletio:	Not Reported		
Packedfrom:	59 ft to	90 ft	
Packsize:	Not Reported		
Finterval:	From 0 ft to	59 ft with	20 (#sacks and material)
Sinterval:	No Data		
Tinterval:	No Data		
Usedmethod:	Positive Placement	Cementedby:	Peterson Drilling & Testing, Inc.
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No Data	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	Peterson Drilling & Testing, Inc.	Companyadd:	P.O. Box 30699
Ccitystate:	Amarillo , TX 79120	Licensenum:	54243
Wsignature:	Roy Wedell	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	0-1 - Concrete1-17 - Reddish Brown Silty Clay17-90 - Reddish Brown Silty Clay with Caliche		
Typesettin:	2 - New - PVC Casing - 0 to 64 - SCH.402 - New - PVC Screen - 64 to 84 - .020		
Oid :	633		

3

**NNE
1/4 - 1/2 Mile
Higher**

TX WELLS TXD1041095

Rec id:	38630	Edr record:	1
Edr site i:	68850	Ownerwell:	B1-B7
Owner name:	Burger King	Citystatez:	Amarillo ,TX
Address:	1800 S. Georgia Street		
Grid:	06-50-4		
Waddress:	1800 S. Georgia Atreet		
Wcitystate:	Amarillo ,TX	Lat:	35° 11 42N
Wcounty:	Potter	Lon:	101° 52 01 W
Elevation:	No Data	Gpsused:	Magellan 315

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Typeofwork:	New Well	Propuse:	Environmental Soil Boring
Sdate:	12/19/2003	Completedd:	12/19/2003
Diameter:	2 in From Surface To	30 ft	
Dmethod:	Not Reported		
Bcompletio:	Not Reported		
Packedfrom:	Not Reported		
Packsize:	Not Reported		
Finterval:	From 0 ft to 30 ft with 2 (#sacks and material)		
Sinterval:	No Data		
Tinterval:	No Data		
Usedmethod:	Bentonite	Cementedby:	Walter Crabb
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	No Data	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No Data	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	CM2, Inc.	Companyadd:	11836 Judd Court 304-C
Ccitystate:	Dallas, TX 75243	Licensenum:	50264
Wsignature:	Walter Crabb	Dsignature:	No Data
Regnum:	No Data		
Comments:	Seven (7) soil borings at this location		
Ftdescript:	0 to 9 feet brown silty clay 9 to 17 feet reddish brown sandy clay 17 to 25 feet brown silty sandy clay 15 to 30 feet brown clay		
Typesettin:	Not Reported		
Oid :	419		

**4
East
1/4 - 1/2 Mile
Higher**

TX WELLS TXD1041052

Rec id:	38305	Edr record:	1
Edr site i:	27529	Edr well:	MW-1
Owner name:	James B. Smithson Bankruptcy Estate	Citystatez:	Amarillo, TX79105
Address:	600 S. Tyler		
Grid:	06-50-4		
Waddress:	Southwest Corner of Wolflin & Civic Circle		
Wcitystate:	Amarillo, TX79109	Lat:	35° 11 27N
Wcounty:	Potter	Lon:	101° 51 48 W
Elevation:	No Data	Gpsused:	No Data
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	2/3/2005	Completedd:	2/3/2005
Diameter:	12.25 in From Surface To	20 ft	
Dmethod:	Mud Rotary		
Bcompletio:	Not Reported		
Packedfrom:	55 ft to 95 ft		
Packsize:	Not Reported		
Finterval:	From 0 ft to 55 ft with 15 (#sacks and material)		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Sinterval: From 0 ft to 20 ft with 10 (#sacks and material)
 Tinterval: No Data
 Usedmethod: Positive Placement Cementedby: Peterson Drilling & Testing, Inc.
 Contaminat: No Data Propertyli: No Data
 Verrimetho: No Data Variance: No Data
 Surface: Surface Slab Installed Staticleve: No Data
 Flow: No Data
 Packers: No Data
 Cementinwe: No Data Typepump: No Data
 Pumpbowl: Not Reported Welltests: No Data
 Yield: Not Reported
 Watertype: No Data Stratadept: No Data
 Chemicalma: No Undesirabl: No
 Certificat: The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required
 Companynam: Peterson Drilling & Testing, Inc. Companyadd: P.O. Box 30699
 Ccitystate: Amarillo, TX 79120 Licensenum: 54243
 Wsignature: Roy Wedell Dsignature: No Data
 Regnum: No Data
 Comments: No Data
 Ftdescription: 0-17 - Reddish Brown Silty Clay17-95 - Reddish Brown Silty Clay with Caliche
 Typesettin: 4 - New - PVC Casing - 0 to 60 - SCH.404 - New - PVC Screen - 60 to 90 - .0108 - New - PVC Casing - 0 to 20 - 200 p.s.i.
 Oid : 633

5
SE
1/4 - 1/2 Mile
Higher

TX WELLS TXD1041024

Rec id: 38356
 Edr site i: 13001 Edr record: 1
 Owner name: United Supermarket Ownerwell: No Data
 Address: 7830 Orlando Avenue Citystatez: Lubbock, TX79423
 Grid: 06-50-4
 Waddress: 2730 S. Georgia St
 Wcitystate: Amarillo, TX79109 Lat: 35° 11 07N
 Wcounty: Potter Lon: 101° 51 57 W
 Elevation: No Data Gpsused: No Data
 Typeofwork: New Well Propuse: Environmental Soil Boring
 Sdate: 11/19/2004 Completedd: 11/19/2004
 Diameter: 2.25 in From Surface To 20 ft
 Dmethod: Not Reported
 Bcompletio: Not Reported
 Packedfrom: Not Reported
 Packsize: Not Reported
 Finterval: From 0 ft to 20 ft with 2 (#sacks and material)
 Sinterval: No Data
 Tinterval: No Data
 Usedmethod: Positive Placement Cementedby: Peterson Drilling & Testing, Inc.
 Contaminat: No Data Propertyli: No Data
 Verrimetho: No Data Variance: No Data
 Surface: No Data Staticleve: No Data
 Flow: No Data
 Packers: No Data
 Cementinwe: No Data Typepump: No Data

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	Peterson Drilling & Testing, Inc.	Companyadd:	P.O. Box 30699
Ccitystate:	Amarillo , TX 79120	Licensenum:	54243
Wsignature:	Roy Wedell	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	0-17 - Reddish Brown Silty Clay17-20 - Reddish Brown Silty Clay with Caliche		
Typesettin:	Not Reported		
Oid :	633		

**B6
West
1/2 - 1 Mile
Higher**

TX WELLS TXD1041047

Rec id:	38223				
Edr site i:	49181	Edr record:	1		
Owner name:	Triple Net Properties, LLC	Ownerwell:	See Comments		
Address:	1551 N. Tustin Avenue,Ste. 200	Citystatez:	Santa Ana	,CA	92705
Grid:	06-49-6				
Waddress:	2201 S. Western				
Wcitystate:	Amarillo ,TX79109	Lat:	35°	11	21N
Wcounty:	Potter	Lon:	101°	52	51 W
Elevation:	No Data	Gpsused:	No Data		
Typeofwork:	New Well	Propuse:	Environmental Soil Boring		
Sdate:	9/27/2005	Completedd:	9/28/2005		
Diameter:	2.25 in From Surface To	10	ft		
Dmethod:	Not Reported				
Bcompleteio:	Not Reported				
Packedfrom:	Not Reported				
Packsiz:	Not Reported				
Finterval:	From 0	ft to	10	ft with	1 Cement (#sacks and material)
Sinterval:	No Data				
Tinterval:	No Data				
Usedmethod:	Positive Placement	Cementedby:	Peterson Drilling & Testing, Inc.		
Contaminat:	No Data	Propertyli:	No Data		
Verrimetho:	No Data	Variance:	No Data		
Surface:	No Data	Staticleve:	No Data		
Flow:	No Data				
Packers:	No Data				
Cementinwe:	No Data	Typepump:	No Data		
Pumpbowl:	Not Reported	Welltests:	No Data		
Yield:	Not Reported				
Watertype:	No Data	Stratadept:	No Data		
Chemicalma:	No Data	Undesirabl:	No		
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required				
Companyname:	Peterson Drilling & Testing, Inc.	Companyadd:	P.O. Box 30699		
Ccitystate:	Amarillo , TX 79120	Licensenum:	54243		
Wsignature:	Roy Wedell	Dsignature:	No Data		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Regnum: No Data
 Comments: MTB-1 thru 16 and STB-1 thru 4
 Ft descript: 0-0.5 - Concrete and Sand 0.5-4 - Dark Grayish Brown Clay 4-8 - Dark Gray Clay 8-9.5 - Reddish Brown Silty Clay 9.5-10 - Light Grayish Pink Silty Clay
 Typesettin: Not Reported
 Oid : 633

**B7
West
1/2 - 1 Mile
Higher**

TX WELLS TXD1041048

Rec id:	38225	Edr record:	1
Edr site i:	48829	Ownerwell:	OMTB-1
Owner name:	Triple Net Properties, LLC	Citystatez:	Santa Ana ,CA92705
Address:	1551 N. Tustin Avenue, Ste. 200		
Grid:	06-49-6		
Waddress:	2201 S. Western		
Wcitystate:	Amarillo ,TX79109	Lat:	35° 11 21N
Wcounty:	Potter	Lon:	101° 52 51 W
Elevation:	No Data	Gpsused:	No Data
Typeofwork:	New Well	Propuse:	Environmental Soil Boring
Sdate:	9/28/2005	Completedd:	9/28/2005
Diameter:	2.25 in From Surface To		35 ft
Dmethod:	Not Reported		
Bcompleto:	Not Reported		
Packedfrom:	Not Reported		
Packsiz:	Not Reported		
Finterval:	From 0 ft to 35 ft with		4 Cement (#sacks and material)
Sinterval:	No Data		
Tinterval:	No Data		
Usedmethod:	Positive Placement	Cementedby:	Peterson Drilling & Testing, Inc.
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	No Data	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No Data	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companynam:	Peterson Drilling & Testing, Inc.	Companyadd:	P.O. Box 30699
Ccitystate:	Amarillo , TX 79120	Licensenum:	54243
Wsignature:	Roy Wedell	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ft descript:	0-0.5 - Concrete and Sand 0.5-2 - Dark Brown Clay 2-9 - Brown Hard Clay 9-35 - Light Red Silty Clay		
Typesettin:	Not Reported		
Oid :	633		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
 Direction
 Distance
 Elevation

Database EDR ID Number

B8
West
1/2 - 1 Mile
Higher

TX WELLS TXD1041049

Rec id:	38226		
Edr site i:	48813	Edr record:	1
Owner name:	Triple Net Properties, LLC	Ownerwell:	OSTB-1
Address:	1551 N. Tustin Avenue, Ste. 200	Citystatez:	Santa Ana ,CA92705
Grid:	06-49-6		
Waddress:	2201 S. Western		
Wcitystate:	Amarillo ,TX79109	Lat:	35° 11 21N
Wcounty:	Potter	Lon:	101° 52 51 W
Elevation:	No Data	Gpsused:	No Data
Typeofwork:	New Well	Propuse:	Environmental Soil Boring
Sdate:	9/28/2005	Completedd:	9/28/2005
Diameter:	2.25 in From Surface To	35 ft	
Dmethod:	Not Reported		
Bcompleto:	Not Reported		
Packedfrom:	Not Reported		
Packsizes:	Not Reported		
Finterval:	From 0 ft to 35 ft with	4 Cement	(#sacks and material)
Sinterval:	No Data		
Tinterval:	No Data		
Usedmethod:	Positive Placement	Cementedby:	Peterson Drilling & Testing, Inc.
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	No Data	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No Data	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companynam:	Peterson Drilling & Testing, Inc.	Companyadd:	P.O. Box 30699
Ccitystate:	Amarillo , TX 79120	Licensenum:	54243
Wsignature:	Roy Wedell	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	0-0.5 - Asphalt0.5-1.5 - Clay and Sand1.5-2.5 - Dark Brown Clay2.4-8 - Brown Clay8-15 - Light Brown Silt with Clay15-21 - Orange and Grayish Clay with Silt21-35 - Light Brown Silt with Clay		
Typesettin:	Not Reported		
Oid :	633		

C9
West
1/2 - 1 Mile
Higher

TX WELLS TXD1041059

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Rec id:	38227	Edr record:	1
Edr site i:	48685	Ownerwell:	MW-7
Owner name:	Conoco Phillips	Citystatez:	Houston ,TX77252
Address:	600 N. Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 I-40 West		
Wcitystate:	Amarillo ,TX79106	Lat:	35° 11 30N
Wcounty:	Potter	Lon:	101° 53 03 W
Elevation:	No Data	Gpsused:	Garmin GPS 315
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	10/11/2005	Completedd:	10/12/2005
Diameter:	2 in From Surface To	100 ft	
Dmethod:	Air Rotary		
Bcompletio:	Not Reported		
Packedfrom:	60 ft to	100 ft	
Packsizes:	8/16		
Finterval:	From 0 ft to	2 ft with	2 Concrete (#sacks and material)
Sinterval:	From 2 ft to	60 ft with	25 Bentonite (#sacks and material)
Tinterval:	No Data		
Usedmethod:	Tremmie	Cementedby:	Talon Drilling, LP
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	Fresh	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	Talon Drilling, LP	Companyadd:	921 N. Bivins
Ccitystate:	Amarillo , TX 79107	Licensenum:	54499
Wsignature:	Shane Currie	Dsignature:	Jose Salas, Jr.
Regnum:	3008		
Comments:	No Data		
Ftdescript:	0-0.5 Brown Sandy Clay0.5-12 Gravel12-21 Reddish Brown Sandy Clay21-31 Reddish Brown, Tan, & Light Brown Sand Layers31-39 Reddish Brown Sand w/Caliche39-56 Tan Sandstone w/Layers of Brown Sand56-83 Light Brown, Tan, & Reddish Brown Sand Layers		
Typesettin:	2 N PVC Riser	0-70 Sch. 40	2 N
Oid :	PVC Screen	70-100	0.010
	180		

**D10
WNW
1/2 - 1 Mile
Higher**

TX WELLS TXD1041081

Rec id:	38232	Edr record:	1
Edr site i:	46735	Ownerwell:	MW-3
Owner name:	Conoco Phillips	Citystatez:	Houston ,TX77252
Address:	600 N. Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 I-40 West		
Wcitystate:	Amarillo ,TX79106	Lat:	35° 11 35N
Wcounty:	Potter	Lon:	101° 53 03 W
Elevation:	No Data	Gpsused:	Garmin GPS 315

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Type of work:	New Well	Propose:	Monitor
Sdate:	10/11/2005	Completedd:	10/12/2005
Diameter:	2 in From Surface To	100 ft	
Dmethod:	Air Rotary		
Bcompletio:	Not Reported		
Packedfrom:	60 ft to	100 ft	
Packsizes:	8/16		
Finterval:	From 0 ft to	2 ft with	2 Concrete (#sacks and material)
Sinterval:	From 2 ft to	60 ft with	25 Bentonite (#sacks and material)
Tinterval:	No Data		
Usedmethod:	Tremmie	Cementedby:	Talon Drilling, LP
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	Fresh	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	Talon Drilling, LP	Companyadd:	921 N. Bivins
Ccitystate:	Amarillo, TX 79107	Licensenum:	54499
Wsignature:	Shane Currie	Dsignature:	Jose Salas, Jr.
Regnum:	3008		
Comments:	No Data		
Ftdescript:	0-0.5 Brown Sandy Clay0.5-12 Gravel12-21 Reddish Brown Sandy Clay21-31 Reddish Brown, Tan, & Light Brown Sand Layers31-39 Reddish Brown Sand w/Caliche39-56 Tan Sandstone w/Layers of Brown Sand56-83 Light Brown, Tan, & Reddish Brown Sand Layers		
Typesettin:	2 N PVC Riser	0-70 Sch. 40	2 N
Oid :	PVC Screen	70-100	0.010

**C11
West
1/2 - 1 Mile
Higher**

TX WELLS TXD1041069

Rec id:	38369	Edr record:	1
Edr site i:	9385	Ownerwell:	MW-2
Owner name:	Conoco Phillips	Citystatez:	Houston, TX77252
Address:	600 N. Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 I-40 West		
Wcitystate:	Amarillo, TX	Lat:	35° 11 32N
Wcounty:	Potter	Lon:	101° 53 04 W
Elevation:	No Data	Gpsused:	Garmin 12xl
Type of work:	New Well	Propose:	Monitor
Sdate:	10/25/2004	Completedd:	10/25/2004
Diameter:	6 1/4 in From Surface To	100.0 ft	
Dmethod:	Air Rotary		
Bcompletio:	Open Hole		
Packedfrom:	100.0 ft to	68.0 ft	
Packsizes:	8/16		
Finterval:	From 68.0 ft to	66.0 ft with	.5/Bent. Pellet (#sacks and material)

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Sinterval: From 66.0 ft to 0.0 ft with 20/cement (#sacks and material)
 Tinterval: No Data
 Usedmethod: Hand Mix Cementedby: White Drilling Company, Inc.
 Contaminat: No Data Propertyli: No Data
 Verrimetho: No Data Variance: No Data
 Surface: Alternative Procedure Used Staticleve: 84.0 ft. below land surface on10/25/2004
 Flow: No Data
 Packers: No Data
 Cementinwe: No Data Typepump: No Data
 Pumpbowl: Not Reported Welltests: No Data
 Yield: Not Reported
 Watertype: Hydrocarbon Stratadept: 30.0 ft.
 Chemicalma: No Undesirabl: Yes
 Certificat: The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required
 Companynam: White Drilling Company, Inc. Companyadd: P.O. Box 906
 Ccitystate: Clyde, TX 79510 Licensenum: 54977
 Wsignature: William B. Atkins Dsignature: No Data
 Regnum: No Data
 Comments: No Data
 Ftdescript: 0.0 to 10.0 Brown sandy clay.10.0 to 12.0 Brown clayey sand.12.0 to 21.0 Light brown & reddish brown clayey sand layers.21.0 to 26.0 Light brown silty sand w/caliche.26.0 to 44.0 Reddish brown & light brown & tan sand
 Typesettin: 2.0 New PVC Riser 0.0 to 70.0 sch. 402.0 New PVC Screen
 70.0 to 100.0 .020
 Oid : 143

**C12
West
1/2 - 1 Mile
Higher**

TX WELLS TXD1041068

Rec id: 38367
 Edr site i: 9701 Edr record: 1
 Owner name: Conoco Phillips Ownerwell: MW-3
 Address: 600 N. Dairy Ashford Citystatez: Houston, TX77252
 Grid: 06-49-6
 Waddress: 4206 I-40 West
 Wcitystate: Amarillo, TX Lat: 35° 11 32N
 Wcounty: Potter Lon: 101° 53 04 W
 Elevation: No Data Gpsused: Garmin 12xl
 Typeofwork: New Well Propuse: Monitor
 Sdate: 10/25/2004 Completedd: 10/25/2004
 Diameter: 6 1/4 in From Surface To 100.0 ft
 Dmethod: Air Rotary
 Bcompletio: Open Hole
 Packedfrom: 100.0 ft to 68.0 ft
 Packsize: 8/16
 Finterval: From 68.0 ft to 65.0 ft with .5/Bent. Pellet (#sacks and material)
 Sinterval: From 65.0 ft to 0.0 ft with 20/cement (#sacks and material)
 Tinterval: No Data
 Usedmethod: Hand Mix Cementedby: White Drilling Company, Inc.
 Contaminat: No Data Propertyli: No Data
 Verrimetho: No Data Variance: No Data
 Surface: Alternative Procedure Used Staticleve: 83.0 ft. below land surface on10/25/2004
 Flow: No Data
 Packers: No Data
 Cementinwe: No Data Typepump: No Data

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	Hydrocarbon	Stratadept:	21.0 ft.
Chemicalma:	No	Undesirabl:	Yes
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	White Drilling Company, Inc.	Companyadd:	P.O. Box 906
Ccitystate:	Clyde, TX 79510	Licensenum:	54977
Wsignature:	William B. Atkins	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	0.0 to 0.5 Brown sandy clay (fill).0.5 to 12.0 Gravel.12.0 to 21.0 Reddish brown sandy clay.21.0 to 31.0 Reddish brown tan & light brown sand layers.31.0 to 39.0 Reddish brown sand w/caliche.39.0 to 56.0 Tan sa		
Typesettin:	2.0 New PVC Riser	0.0 to 70.0 sch. 402.0	New PVC Screen
Oid :	70.0 to 100.0 .020		
	143		

**D13
WNW
1/2 - 1 Mile
Higher**

TX WELLS TXD1041080

Rec id:	38231	Edr record:	1
Edr site i:	46903	Ownerwell:	MW-4
Owner name:	Conoco Phillips	Citystatez:	Houston, TX77252
Address:	600 N. Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 I-40 West		
Wcitystate:	Amarillo, TX79106	Lat:	35° 11 34N
Wcounty:	Potter	Lon:	101° 53 04 W
Elevation:	No Data	Gpsused:	Garmin GPS 315
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	10/11/2005	Completedd:	10/12/2005
Diameter:	2 in From Surface To	100 ft	
Dmethod:	Air Rotary		
Bcompleto:	Not Reported		
Packedfrom:	60 ft to	100 ft	
Packsiz:	8/16		
Finterval:	From 0 ft to	2 ft with	2 Concrete (#sacks and material)
Sinterval:	From 2 ft to	60 ft with	25 Bentonite (#sacks and material)
Tinterval:	No Data		
Usedmethod:	Tremmie	Cementedby:	Talon Drilling, LP
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	Fresh	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	Talon Drilling, LP	Companyadd:	921 N. Bivins
Ccitystate:	Amarillo, TX 79107	Licensenum:	54499
Wsignature:	Shane Currie	Dsignature:	Jose Salas, Jr.

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Regnum: 3008
 Comments: No Data
 Ftdescription: 0-0.5 Brown Sandy Clay0.5-12 Gravel12-21 Reddish Brown Sandy Clay21-31 Reddish Brown, Tan, & Light Brown Sand Layers31-39 Reddish Brown Sand w/Caliche39-56 Tan Sandstone w/Layers of Brown Sand56-83 Light Brown, Tan, & Reddish Brown Sand Layers
 Typesettin: 2 N PVC Riser 0-70 Sch. 40 2 N
 PVC Screen 70-100 0.010
 Oid : 180

**C14
 West
 1/2 - 1 Mile
 Higher**

TX WELLS TXD1041063

Rec id:	38553	Edr record:	1
Edr site i:	31310	Ownerwell:	SB-4
Owner name:	Conoco Phillips/Andrew Stow	Citystatez:	Houston ,TX77079
Address:	600 North Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 West I-40		
Wcitystate:	Amarillo ,TX	Lat:	35° 11 31N
Wcounty:	Potter	Lon:	101° 53 05 W
Elevation:	No Data	Gpsused:	No Data
Typeofwork:	New Well	Propuse:	Environmental Soil Boring
Sdate:	1/27/2004	Completedd:	1/29/2004
Diameter:	12 1/4 in From Surface To		21 ft
Dmethod:	Hollow Stem Auger		
Bcompletio:	No Data		
Packedfrom:	Not Reported		
Packsizes:	Not Reported		
Finterval:	No Data		
Sinterval:	No Data		
Tinterval:	No Data		
Usedmethod:	Not Reported	Cementedby:	Not Reported
Contaminat:	Not Reported	Propertyli:	Not Reported
Verrimetho:	Not Reported	Variance:	Not Reported
Surface:	No Data	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	dba Universal Drilling Services	Companyadd:	3532 Maggie blvd.
Ccitystate:	Orlando , FL 32811	Licensenum:	3150
Wsignature:	Robert Hubler	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescription:	2-2 Clayey Silt: Dark brown, minor sand, slightly moist, loose, no petroleum odor5-5 Clayey Silt: Brown, minor sand, slightly moist, loose, no petroleum9-11 Silty Clay: Dark brown, stiff to friable, slightly moist, no petroleum odor14-16 Clay and Silt		
Typesettin:	Not Reported		
Oid :	633		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
 Direction
 Distance
 Elevation

Database EDR ID Number

C15
West
1/2 - 1 Mile
Higher

TX WELLS TXD1041062

Rec id:	38522	Edr record:	1
Edr site i:	45696	Ownerwell:	SB-5
Owner name:	Conoco Phillips/Andrew Stow	Citystatez:	Houston ,TX77079
Address:	600 North Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 West I-40		
Wcitystate:	Amarillo ,TX	Lat:	35° 11 31N
Wcounty:	Potter	Lon:	101° 53 05 W
Elevation:	No Data	Gpsused:	No Data
Typeofwork:	New Well	Propuse:	Environmental Soil Boring
Sdate:	1/27/2004	Completedd:	1/29/2004
Diameter:	12 1/4 in From Surface To		21 ft
Dmethod:	Hollow Stem Auger		
Bcompleto:	No Data		
Packedfrom:	Not Reported		
Packsizes:	Not Reported		
Finterval:	No Data		
Sinterval:	No Data		
Tinterval:	No Data		
Usedmethod:	Not Reported	Cementedby:	Not Reported
Contaminat:	Not Reported	Propertyli:	Not Reported
Verrimetho:	Not Reported	Variance:	Not Reported
Surface:	No Data	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	dba Universal Drilling Services	Companyadd:	3532 Maggie blvd.
Ccitystate:	Orlando , FL 32811	Licensenum:	3150
Wsignature:	Robert Hubler	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	2.50-2.50 Clayey Silt: Dark brown, minor sand, slightly moist, firm, no petroleum odor5-5 Clayey Silt: Brown, minor sand, slightly moist, firm, no petroleum9-11 Clay and Silt: Dark brown,clay/silt mix, stiff to fiabile, slightly moist, petroleum odor1		
Typesettin:	Not Reported		
Oid :	633		

C16
West
1/2 - 1 Mile
Higher

TX WELLS TXD1041061

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Rec id:	38229	Edr record:	1
Edr site i:	47933	Ownerwell:	MW-6
Owner name:	Conoco Phillips	Citystatez:	Houston ,TX77252
Address:	600 N. Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 I-40 West		
Wcitystate:	Amarillo ,TX79106	Lat:	35° 11 31N
Wcounty:	Potter	Lon:	101° 53 05 W
Elevation:	No Data	Gpsused:	Garmin GPS 315
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	10/11/2005	Completedd:	10/12/2005
Diameter:	2 in From Surface To		100 ft
Dmethod:	Air Rotary		
Bcompletio:	Not Reported		
Packedfrom:	60 ft to		100 ft
Packsizes:	8/16		
Finterval:	From 0 ft to	2 ft with	2 Concrete (#sacks and material)
Sinterval:	From 2 ft to	60 ft with	25 Bentonite (#sacks and material)
Tinterval:	No Data		
Usedmethod:	Tremmie	Cementedby:	Talon Drilling, LP
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	Fresh	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	Talon Drilling, LP	Companyadd:	921 N. Bivins
Ccitystate:	Amarillo ,TX 79107	Licensenum:	54499
Wsignature:	Shane Currie	Dsignature:	Jose Salas, Jr.
Regnum:	3008		
Comments:	No Data		
Ftdescript:	0-0.5 Brown Sandy Clay0.5-12 Gravel12-21 Reddish Brown Sandy Clay21-31 Reddish Brown, Tan, & Light Brown Sand Layers31-39 Reddish Brown Sand w/Caliche39-56 Tan Sandstone w/Layers of Brown Sand56-83 Light Brown, Tan, & Reddish Brown Sand Layers		
Typesettin:	2 N PVC Riser	0-70 Sch. 40	2 N
Oid :	PVC Screen	70-100	0.010
	180		

**C17
West
1/2 - 1 Mile
Higher**

TX WELLS TXD1041066

Rec id:	38598	Edr record:	1
Edr site i:	17318	Ownerwell:	SB-1
Owner name:	Conoco Phillips/Andrew Stow	Citystatez:	Houston ,TX77079
Address:	600 North Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 West I-40		
Wcitystate:	Amarillo ,TX	Lat:	35° 11 31N
Wcounty:	Potter	Lon:	101° 53 05 W
Elevation:	No Data	Gpsused:	No Data

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Typeofwork:	New Well	Propuse:	Environmental Soil Boring
Sdate:	1/27/2004	Completedd:	1/29/2004
Diameter:	12 1/4 in From Surface To	51	ft
Dmethod:	Hollow Stem Auger		
Bcompletio:	No Data		
Packedfrom:	Not Reported		
Packsiz:	Not Reported		
Finterval:	No Data		
Sinterval:	No Data		
Tinterval:	No Data		
Usedmethod:	Not Reported	Cementedby:	Not Reported
Contaminat:	Not Reported	Propertyli:	Not Reported
Verrimetho:	Not Reported	Variance:	Not Reported
Surface:	No Data	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	dba Universal Drilling Services	Companyadd:	3532 Maggie blvd.
Ccitystate:	Orlando , FL 32811	Licensenum:	3150
Wsignature:	Robert Hubler	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	2-2 Clayey Silt: Dark brown, trace fine, sand, slightly moist, soft4-4 Clayey Silt: Brown, slightly moist, medium stiff, no petroleum odor4-6 Clayey Silt: Same soil6-9 Silty Clay: Dark brown, medium stiff, slightly moist, no petroleum odor9-11 Silty		
Typesettin:	Not Reported		
Oid :	633		

**C18
West
1/2 - 1 Mile
Higher**

TX WELLS TXD1041065

Rec id:	38597	Edr record:	1
Edr site i:	19081	Ownerwell:	SB-2
Owner name:	Conoco Phillips/Andrew Stow	Citystatez:	Houston ,TX77079
Address:	600 North Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 West I-40		
Wcitystate:	Amarillo ,TX	Lat:	35° 11 31N
Wcounty:	Potter	Lon:	101° 53 05 W
Elevation:	No Data	Gpsused:	No Data
Typeofwork:	New Well	Propuse:	Environmental Soil Boring
Sdate:	1/27/2004	Completedd:	1/29/2004
Diameter:	12 1/4 in From Surface To	51	ft
Dmethod:	Hollow Stem Auger		
Bcompletio:	No Data		
Packedfrom:	Not Reported		
Packsiz:	Not Reported		
Finterval:	No Data		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Sinterval:	No Data		
Tinterval:	No Data		
Usedmethod:	Not Reported	Cementedby:	Not Reported
Contaminat:	Not Reported	Propertyli:	Not Reported
Verrimetho:	Not Reported	Variance:	Not Reported
Surface:	No Data	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	dba Universal Drilling Services	Companyadd:	3532 Maggie blvd.
Ccitystate:	Orlando , FL 32811	Licensenum:	3150
Wsignature:	Robert Hubler	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	2-2 Clayey Silt: Dark brown, slightly moist, loose, no petroleum odor 5-5 Clayey Silt: Red brown, loose, slightly moist, no petroleum odor 9-11 Clayey Silt: Brown, slightly moist, friable, no petroleum odor 14-16 Clay and Silt: Red/brown clay/silt mix,		
Typesettin:	Not Reported		
Oid :	633		

**C19
West
1/2 - 1 Mile
Higher**

TX WELLS TXD1041064

Rec id:	38596			
Edr site i:	19521	Edr record:	1	
Owner name:	Conoco Phillips/Andrew Stow	Ownerwell:	SB-6	
Address:	600 North Dairy Ashford	Citystatez:	Houston	,TX77079
Grid:	06-49-6			
Waddress:	4206 West I-40			
Wcitystate:	Amarillo ,TX	Lat:	35°	11 31N
Wcounty:	Potter	Lon:	101°	53 05 W
Elevation:	No Data	Gpsused:	No Data	
Typeofwork:	New Well	Propuse:	Environmental Soil Boring	
Sdate:	1/27/2004	Completedd:	1/29/2004	
Diameter:	12 1/4 in	From Surface To	51	ft
Dmethod:	Hollow Stem Auger			
Bcompletio:	No Data			
Packedfrom:	Not Reported			
Packsizes:	Not Reported			
Finterval:	No Data			
Sinterval:	No Data			
Tinterval:	No Data			
Usedmethod:	Not Reported	Cementedby:	Not Reported	
Contaminat:	Not Reported	Propertyli:	Not Reported	
Verrimetho:	Not Reported	Variance:	Not Reported	
Surface:	No Data	Staticleve:	No Data	
Flow:	No Data			
Packers:	No Data			
Cementinwe:	No Data	Typepump:	No Data	

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	dba Universal Drilling Services	Companyadd:	3532 Maggie blvd.
Ccitystate:	Orlando , FL 32811	Licensenum:	3150
Wsignature:	Robert Hubler	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	2-2 Clayey Silt: Dark brown, trace sand, slightly moist, loose, no petroleum odor5-5 Clayey Silt: Brown, minor sand, loose, slightly moist, no petroleum odor9-11 Sandy Clay: Dark brown, soft, slightly moist, no petroleum odor; small sample; per drill		
Typesettin:	Not Reported		
Oid :	633		

**C20
West
1/2 - 1 Mile
Higher**

TX WELLS TXD1041060

Rec id:	27161	Edr record:	1		
Edr site i:	58539	Ownerwell:	SB-3		
Owner name:	Conoco Phillips/Andrew Stow	Citystatez:	Houston ,TX	77079	
Address:	600 North Dairy Ashford				
Grid:	06-49-6				
Waddress:	4206 West I-40				
Wcitystate:	Amarillo ,TX	Lat:	35°	11	31N
Wcounty:	Potter	Lon:	101°	53	05 W
Elevation:	No Data	Gpsused:	No Data		
Typeofwork:	New Well	Propuse:	Environmental Soil Boring		
Sdate:	1/27/2004	Completedd:	1/29/2004		
Diameter:	12 1/4 in	From Surface To	21	ft	
Dmethod:	Hollow Stem Auger				
Bcompletio:	No Data				
Packedfrom:	Not Reported				
Packsizes:	Not Reported				
Finterval:	No Data				
Sinterval:	No Data				
Tinterval:	No Data				
Usedmethod:	Not Reported	Cementedby:	Not Reported		
Contaminat:	Not Reported	Propertyli:	Not Reported		
Verrimetho:	Not Reported	Variance:	Not Reported		
Surface:	No Data	Staticleve:	No Data		
Flow:	No Data				
Packers:	No Data				
Cementinwe:	No Data	Typepump:	No Data		
Pumpbowl:	Not Reported	Welltests:	No Data		
Yield:	Not Reported				
Watertype:	No Data	Stratadept:	No Data		
Chemicalma:	No	Undesirabl:	No		
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required				
Companyname:	dba Universal Drilling Services	Companyadd:	3532 Maggie blvd.		
Ccitystate:	Orlando , FL 32811	Licensenum:	3150		
Wsignature:	Robert Hubler	Dsignature:	No Data		

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Regnum: No Data
 Comments: No Data
 Ftdescription: 2-2 Clayey Silt: Dark brown, minor sand, slightly moist, loose, no petroleum odor5-5 Clayey Silt: Brown, minor sand, slightly moist, loose, no petroleum9-11 Silty Clay: Dark brown, medium stiff, slightly friable, slightly moist, no petroleum odor14-1
 Typesettin: Not Reported
 Oid : 633

**C21
 West
 1/2 - 1 Mile
 Higher**

TX WELLS TXD1041067

Rec id:	38230	Edr record:	1
Edr site i:	47355	Ownerwell:	MW-5
Owner name:	Conoco Phillips	Citystatez:	Houston ,TX77252
Address:	600 N. Dairy Ashford		
Grid:	06-49-6		
Waddress:	4206 I-40 West		
Wcystate:	Amarillo ,TX79106	Lat:	35° 11 32N
Wcounty:	Potter	Lon:	101° 53 05 W
Elevation:	No Data	Gpsused:	Garmin GPS 315
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	10/11/2005	Completedd:	10/12/2005
Diameter:	2 in From Surface To		100 ft
Dmethod:	Air Rotary		
Bcompletio:	Not Reported		
Packedfrom:	60 ft to		100 ft
Packsiz:	8/16		
Finterval:	From 0 ft to	2 ft with	2 Concrete (#sacks and material)
Sinterval:	From 2 ft to	60 ft with	25 Bentonite (#sacks and material)
Tinterval:	No Data		
Usedmethod:	Tremmie	Cementedby:	Talon Drilling, LP
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Surface Slab Installed	Staticleve:	No Data
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	Fresh	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	Talon Drilling, LP	Companyadd:	921 N. Bivins
Ccitystate:	Amarillo , TX 79107	Licensenum:	54499
Wsignature:	Shane Currie	Dsignature:	Jose Salas, Jr.
Regnum:	3008		
Comments:	No Data		
Ftdescription:	0-0.5 Brown Sandy Clay0.5-12 Gravel12-21 Reddish Brown Sandy Clay21-31 Reddish Brown, Tan, & Light Brown Sand Layers31-39 Reddish Brown Sand w/Caliche39-56 Tan Sandstone w/Layers of Brown Sand56-83 Light Brown, Tan, & Reddish Brown Sand Layers		
Typesettin:	2 N PVC Riser	0-70 Sch. 40	2 N
Oid :	PVC Screen	70-100	0.010
			180

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Map ID
 Direction
 Distance
 Elevation

Database EDR ID Number

E22
West
1/2 - 1 Mile
Higher

TX WELLS TXD1041057

Rec id:	38659	Edr record:	1
Edr site i:	48944	Ownerwell:	MW-14
Owner name:	EZ Mart Stores	Citystatez:	Texarkana ,TX75501
Address:	602 West Falvey		
Grid:	06-49-6		
Waddress:	#323 - 2015 South Western		
Wcitystate:	Amarillo ,TX	Lat:	35° 11 30N
Wcounty:	Potter	Lon:	101° 53 09 W
Elevation:	No Data	Gpsused:	Garmin 12
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	8/19/2003	Completedd:	8/19/2003
Diameter:	6.5 in From Surface To		110.0 ft
Dmethod:	Air Rotary		
Bcompleto:	Open Hole		
Packedfrom:	110.0 ft to 48.0 ft		
Packsiz:	Not Reported		
Finterval:	From 48.0 ft to 8.0 ft with	Bent. Pell	(#sacks and material)
Sinterval:	From 8.0 ft to 0.0 ft with	7.0	(#sacks and material)
Tinterval:	No Data		
Usedmetho:	Pump mix - tremmie pipe	Cementedby:	White Drilling Company, Inc.
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Alternative Procedure Used	Staticleve:	89.0 ft. below land surface on8/19/2003
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companynam:	White Drilling Company, Inc.	Companyadd:	P.O. Box 906
Ccitystate:	Clyde , TX 79510	Licensenum:	5044
Wsignature:	John W. White	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescrip:	0.0 to 2.0 Brown sandy clay.2.0 to 18.0 Red sand w/caliche.18.0 to 34.0 Red sandy clay.34.0 to 50.0 Red sand w/caliche.50.0 to 58.0 White caliche.58.0 to 71.0 Tan sand w/caliche.71.0 to 92.0 Red sand.92.0 to 110.0		
Typesettin:	2.0 New PVC Riser 0.0 to 50.0 sch. 402.0 New PVC Screen 50.0 to 110.0 .020		
Oid :	139		

E23
West
1/2 - 1 Mile
Higher

TX WELLS TXD1041056

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Rec id:	38658	Edr record:	1
Edr site i:	49358	Ownerwell:	MW-13
Owner name:	EZ Mart Stores	Citystatez:	Texarkana ,TX75501
Address:	602 West Falvey		
Grid:	06-49-6		
Waddress:	#323 - 2015 South Western		
Wcitystate:	Amarillo ,TX	Lat:	35° 11 30N
Wcounty:	Potter	Lon:	101° 53 09 W
Elevation:	No Data	Gpsused:	Garmin 12
Typeofwork:	New Well	Propuse:	Monitor
Sdate:	8/19/2003	Completedd:	8/19/2003
Diameter:	6.5 in From Surface To		110.0 ft
Dmethod:	Air Rotary		
Bcompletio:	Open Hole		
Packedfrom:	110.0 ft to		48.0 ft
Packsize:	Not Reported		
Finterval:	From 48.0 ft to	8.0 ft with	Bent. Pell (#sacks and material)
Sinterval:	From 8.0 ft to	0.0 ft with	7.0 (#sacks and material)
Tinterval:	No Data		
Usedmethod:	Pump mix - tremmie pipe	Cementedby:	White Drilling Company, Inc.
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Alternative Procedure Used	Staticleve:	96.0 ft. below land surface on8/19/2003
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the drillers direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	White Drilling Company, Inc.	Companyadd:	P.O. Box 906
Ccitystate:	Clyde , TX 79510	Licensenum:	5044
Wsignature:	John W. White	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	0.0 to 16.0 Dark brown clayey sand.16.0 to 29.0 Reddish tan sandy caliche.29.0 to 38.0 Red sand w/caliche.38.0 to 45.0 Red sand.45.0 to 49.0 Red sand w/caliche.49.0 to 68.0 Tan sand w/sandstone layers.68.0 to 79.0 Red s		
Typesettin:	2.0 New PVC Riser	0.0 to 50.0 sch.	402.0 New
	PVC Screen	50.0 to 110.0	.020
Oid :	139		

**E24
West
1/2 - 1 Mile
Higher**

TX WELLS TXD1041058

Rec id:	38660	Edr record:	1
Edr site i:	48941	Ownerwell:	MW-15
Owner name:	EZ Mart Stores	Citystatez:	Texarkana ,TX75501
Address:	602 West Falvey		
Grid:	06-49-6		
Waddress:	#323 - 2015 South Western		
Wcitystate:	Amarillo ,TX	Lat:	35° 11 30N
Wcounty:	Potter	Lon:	101° 53 09 W
Elevation:	No Data	Gpsused:	Garmin 12

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS

Type of work:	New Well	Propose:	Monitor
Sdate:	8/19/2003	Completedd:	8/19/2003
Diameter:	6.5 in	From Surface To	110.0 ft
Dmethod:	Air Rotary		
Bcompleteio:	Open Hole		
Packedfrom:	110.0 ft to	48.0 ft	
Packsize:	Not Reported		
Finterval:	From 48.0 ft to	8.0 ft with	Bent. Pell (#sacks and material)
Sinterval:	From 8.0 ft to	0.0 ft with	7.0 (#sacks and material)
Tinterval:	No Data		
Usedmethod:	Pump mix - tremmie pipe	Cementedby:	White Drilling Company, Inc.
Contaminat:	No Data	Propertyli:	No Data
Verrimetho:	No Data	Variance:	No Data
Surface:	Alternative Procedure Used	Staticleve:	82.0 ft. below land surface on 8/19/2003
Flow:	No Data		
Packers:	No Data		
Cementinwe:	No Data	Typepump:	No Data
Pumpbowl:	Not Reported	Welltests:	No Data
Yield:	Not Reported		
Watertype:	No Data	Stratadept:	No Data
Chemicalma:	No	Undesirabl:	No
Certificat:	The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required		
Companyname:	White Drilling Company, Inc.	Companyadd:	P.O. Box 906
Ccitystate:	Clyde, TX 79510	Licensenum:	5044
Wsignature:	John W. White	Dsignature:	No Data
Regnum:	No Data		
Comments:	No Data		
Ftdescript:	0.0 to 10.0 Brown clay. 10.0 to 21.0 Tan clayey sand w/caliche. 21.0 to 40.0 Tan sand w/caliche. 40.0 to 49.0 White caliche. 49.0 to 61.0 Tan sand w/caliche. 61.0 to 80.0 Tan sand. 80.0 to 84.0 Tan sand w/caliche. 84.0 to 110		
Typesettin:	2.0 New PVC Riser	0.0 to 50.0 sch.	402.0 New PVC Screen
Oid :	139	50.0 to 110.0 .020	

GEOCHECK® - PHYSICAL SETTING SOURCE MAP FINDINGS RADON

AREA RADON INFORMATION

State Database: TX Radon

Radon Test Results

County	Mean	Total Sites	%>4 pCi/L	%>20 pCi/L	Min pCi/L	Max pCi/L
POTTER	2.8	32	28.1	.0	<.5	6.6

Federal EPA Radon Zone for POTTER County: 2

- Note: Zone 1 indoor average level > 4 pCi/L.
 : Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L.
 : Zone 3 indoor average level < 2 pCi/L.

Federal Area Radon Information for Zip Code: 79109

Number of sites tested: 13

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area - 1st Floor	4.477 pCi/L	54%	46%	0%
Living Area - 2nd Floor	Not Reported	Not Reported	Not Reported	Not Reported
Basement	10.850 pCi/L	50%	50%	0%

PHYSICAL SETTING SOURCE RECORDS SEARCHED

TOPOGRAPHIC INFORMATION

USGS 7.5' Digital Elevation Model (DEM)

Source: United States Geologic Survey

EDR acquired the USGS 7.5' Digital Elevation Model in 2002 and updated it in 2006. The 7.5 minute DEM corresponds to the USGS 1:24,000- and 1:25,000-scale topographic quadrangle maps. The DEM provides elevation data with consistent elevation units and projection.

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

HYDROLOGIC INFORMATION

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

HYDROGEOLOGIC INFORMATION

AQUIFLOW^R Information System

Source: EDR proprietary database of groundwater flow information

EDR has developed the AQUIFLOW Information System (AIS) to provide data on the general direction of groundwater flow at specific points. EDR has reviewed reports submitted to regulatory authorities at select sites and has extracted the date of the report, hydrogeologically determined groundwater flow direction and depth to water table information.

GEOLOGIC INFORMATION

Geologic Age and Rock Stratigraphic Unit

Source: P.G. Schruben, R.E. Arndt and W.J. Bawiec, Geology of the Conterminous U.S. at 1:2,500,000 Scale - A digital representation of the 1974 P.B. King and H.M. Beikman Map, USGS Digital Data Series DDS - 11 (1994).

STATSGO: State Soil Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services

The U.S. Department of Agriculture's (USDA) Natural Resources Conservation Service (NRCS) leads the national Conservation Soil Survey (NCSS) and is responsible for collecting, storing, maintaining and distributing soil survey information for privately owned lands in the United States. A soil map in a soil survey is a representation of soil patterns in a landscape. Soil maps for STATSGO are compiled by generalizing more detailed (SSURGO) soil survey maps.

SSURGO: Soil Survey Geographic Database

Source: Department of Agriculture, Natural Resources Conservation Services (NRCS)

Telephone: 800-672-5559

SSURGO is the most detailed level of mapping done by the Natural Resources Conservation Services, mapping scales generally range from 1:12,000 to 1:63,360. Field mapping methods using national standards are used to construct the soil maps in the Soil Survey Geographic (SSURGO) database. SSURGO digitizing duplicates the original soil survey maps. This level of mapping is designed for use by landowners, townships and county natural resource planning and management.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

LOCAL / REGIONAL WATER AGENCY RECORDS

FEDERAL WATER WELLS

PWS: Public Water Systems

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Public Water System data from the Federal Reporting Data System. A PWS is any water system which provides water to at least 25 people for at least 60 days annually. PWSs provide water from wells, rivers and other sources.

PWS ENF: Public Water Systems Violation and Enforcement Data

Source: EPA/Office of Drinking Water

Telephone: 202-564-3750

Violation and Enforcement data for Public Water Systems from the Safe Drinking Water Information System (SDWIS) after August 1995. Prior to August 1995, the data came from the Federal Reporting Data System (FRDS).

USGS Water Wells: USGS National Water Inventory System (NWIS)

This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on wells, springs, and other sources of groundwater.

STATE RECORDS

Texas Groundwater Database

Source: Texas Water Development Board

Telephone: 512-936-0837

Texas Public Water Supply Database on Ground and Surface Water

Source: Texas Commission on Environmental Quality

Texas Water Wells DOL

Source: Texas Department of Licensing and Regulation

Telephone: 512-463-6599

OTHER STATE DATABASE INFORMATION

Texas Oil and Gas Wells: Inventory of oil and gas wells in select Texas counties

Source: Texas Railroad Commission

Oil and gas well locations in the following counties: Bexar, Brazoria, Collin, Dallas, Denton, El Paso, Fort Bend, Galveston, Gregg, Harris, Hidalgo, Jefferson, Lubbock, Montgomery, Nueces, Tarrant, and Travis.

RADON

State Database: TX Radon

Source: Department of Health

Telephone: 512-834-6688

Final Report of the Texas Indoor Radon Survey

Area Radon Information

Source: USGS

Telephone: 703-356-4020

The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

EPA Radon Zones

Source: EPA

Telephone: 703-356-4020

Sections 307 & 309 of IRAA directed EPA to list and identify areas of U.S. with the potential for elevated indoor radon levels.

PHYSICAL SETTING SOURCE RECORDS SEARCHED

OTHER

Airport Landing Facilities: Private and public use landing facilities
Source: Federal Aviation Administration, 800-457-6656

Epicenters: World earthquake epicenters, Richter 5 or greater
Source: Department of Commerce, National Oceanic and Atmospheric Administration

STREET AND ADDRESS INFORMATION

© 2006 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.



EDR® Environmental
Data Resources Inc

The EDR-City Directory
Abstract

Blucher S. Tharp Memorial USARC
2801 Duniven Circle
Amarillo, TX 79109

Inquiry Number: 1715338.6

Tuesday, July 18, 2006

**The Standard in
Environmental Risk
Management Information**

440 Wheelers Farms Road
Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

EDR City Directory Abstract

Environmental Data Resources, Inc.'s (EDR) City Directory Abstract is a screening report designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Abstract includes a search and abstract of available city directory data. For each address, the directory lists the name of the corresponding occupant at five year intervals.

Thank you for your business.

Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.**

Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2006 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

SUMMARY

- ***City Directories:***

Business directories including city, cross reference and telephone directories were reviewed, if available, at approximately five year intervals for the years spanning 1921 through 1994. (These years are not necessarily inclusive.) A summary of the information obtained is provided in the text of this report.

Date EDR Searched Historical Sources: July 18, 2006

Target Property:

2801 Duniven Circle
Amarillo, TX 79109

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1921	Street Not Listed in Research Source	Hudspeth's City Directory
1931	Street Not Listed in Research Source	Hudspeth's City Directory
1939	Street Not Listed in Research Source	Hudspeth's City Directory
1947	Street Not Listed in Research Source	Hudspeth's City Directory
1952	Street Not Listed in Research Source	Hudspeth's City Directory
1956	Street Not Listed in Research Source	Hudspeth's City Directory
1960	U S Army Reserve Training Center	Hudspeth's City Directory
1965	Govt Ofcs Dept Of Defs	Hudspeth's City Directory
1970	U S A Reserve Training Center	Hudspeth's City Directory
1975	U S A Reserve Training Center	Polk's City Directory
1980	Tharp Army Reserve Center	Polk's City Directory
1985	Blucher S Tharp Army Reserve Center	Polk's City Directory
1990	U S Tharp Army Reserve Center	Polk's City Directory
1994	U S Army Reserve Cntr	Polk's City Directory

Adjoining Properties

SURROUNDING

Multiple Addresses
Amarillo, TX 79109

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1921	Street Not Listed in Research Source	Hudspeth's City Directory
1931	Street Not Listed in Research Source	Hudspeth's City Directory

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1939	Street Not Listed in Research Source	Hudspeth's City Directory
1947	Street Not Listed in Research Source	Hudspeth's City Directory
1952	Street Not Listed in Research Source	Hudspeth's City Directory
1956	Street Not Listed in Research Source	Hudspeth's City Directory
1960	*Duniven Cir*	Hudspeth's City Directory
	Autry Bruce Stationery & Printing (2764)	Hudspeth's City Directory
	Vetesk's Bakery (2766)	Hudspeth's City Directory
	Vetesk's Market (2770)	Hudspeth's City Directory
	Address not listed in research source (2776)	Hudspeth's City Directory
	Vol's Hickory Broiled Steaks (2800)	Hudspeth's City Directory
	Address not listed in research source (2806)	Hudspeth's City Directory
	Residence (2810)	Hudspeth's City Directory
	Address not listed in research source (2823)	Hudspeth's City Directory
	Address not listed in research source (2900)	Hudspeth's City Directory
	Address not listed in research source (2902)	Hudspeth's City Directory
	Address not listed in research source (2904)	Hudspeth's City Directory
	Address not listed in research source (2906)	Hudspeth's City Directory
	Blackburn Street	Hudspeth's City Directory
	Cross street no longer in address range	Hudspeth's City Directory
1965	*Duniven Cir*	Hudspeth's City Directory
	Autry Bruce Stationery & Printing (2764)	Hudspeth's City Directory
	Petroleum Life Insurance Co. (2766)	Hudspeth's City Directory

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1965	Vetesk's Market (2770)	Hudspeth's City Directory
	Address not listed in research source (2776)	Hudspeth's City Directory
	Vacant (2806)	Hudspeth's City Directory
	Great National Life Insurance Co. (2810)	Hudspeth's City Directory
	Suburban Insurance Agency (2810)	Hudspeth's City Directory
	Suburban Realty (2810)	Hudspeth's City Directory
	Address not listed in research source (2823)	Hudspeth's City Directory
	Autry's Studio (2900)	Hudspeth's City Directory
	Reserve Life Insurance Co. (2902)	Hudspeth's City Directory
	Address not listed in research source (2904)	Hudspeth's City Directory
	Meade Foot Clinic (2906)	Hudspeth's City Directory
	Blackburn Street	Hudspeth's City Directory
	Cross street no longer in address range	Hudspeth's City Directory
1970	*Duniven Cir*	Hudspeth's City Directory
	Autry Bruce Printing (2764)	Hudspeth's City Directory
	Acme Answering & Letter Service (2766)	Hudspeth's City Directory
	Pennyrich Bro (2766)	Hudspeth's City Directory
	Vacant (2770)	Hudspeth's City Directory
	Bellett's Letter Service (2776)	Hudspeth's City Directory
	Sumner's Gourmet Shop (2806)	Hudspeth's City Directory
	Budd & Associates (2810)	Hudspeth's City Directory
	Amarillo Air Force Base Credit Union (2810)	Hudspeth's City Directory

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1970	Address not listed in research source (2823)	Hudspeth's City Directory
	Autry's Studio (2900)	Hudspeth's City Directory
	Address not listed in research source (2902)	Hudspeth's City Directory
	Suburban Realty (2904)	Hudspeth's City Directory
	American Insurance Co. (2904)	Hudspeth's City Directory
	Solar Systems Inv Inc. (2904)	Hudspeth's City Directory
	Amyx Bill Realty (2904)	Hudspeth's City Directory
	Meade Foot Clinic (2906)	Hudspeth's City Directory
	Blackburn Street	Hudspeth's City Directory
	Cross street no longer in address range	Hudspeth's City Directory
1975	*Duniven Cir*	Polk's City Directory
	Autry Bruce Printing (2764)	Polk's City Directory
	Acme Answering & Letter Service (2766)	Polk's City Directory
	Employers Insurance Of Wausau (2766)	Polk's City Directory
	Car Parts Co. (2770)	Polk's City Directory
	Super Save Liquors (2806)	Polk's City Directory
	Prudential Insurance Co. (2810)	Polk's City Directory
	Amarillo A F B Credit Union (2810)	Polk's City Directory
	Address not listed in research source (2823)	Polk's City Directory
	Blairhouse (2900)	Polk's City Directory
	Vacant (2902)	Polk's City Directory
	Government Employees Insurance Co. (2904)	Polk's City Directory

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1975	Meade Foot Clinic (2906)	Polk's City Directory
	Blackburn Street	Polk's City Directory
	Cross street no longer in address range	Polk's City Directory
1980	*Duniven Cir*	Polk's City Directory
	Autry Bruce Sprint Printing (2764)	Polk's City Directory
	Bellett Secritarial & Bkpg Servs (2766)	Polk's City Directory
	Number Tw o Lift (2770)	Polk's City Directory
	Pinkie's Liquor Store (2806)	Polk's City Directory
	Mc Clendon & Blank (2810)	Polk's City Directory
	Mason Reporting (2810)	Polk's City Directory
	Address not listed in research source (2823)	Polk's City Directory
	Salon Tw enty-Nine Hundred (2900)	Polk's City Directory
	Southw est Orthopedic Footw ear (2906)	Polk's City Directory
	Blackburn Street	Polk's City Directory
	Cross street no longer in address range	Polk's City Directory
1985	*Duniven Cir*	Polk's City Directory
	Autry Bruce Sprint Printing (2764)	Polk's City Directory
	Raines Boot & Shoe Repair (2766)	Polk's City Directory
	Webb Galleries (2770)	Polk's City Directory
	Pinkie's Liquor Store (2806)	Polk's City Directory
	Mason Reporting (2810)	Polk's City Directory
	E R A-American Realtors (2810)	Polk's City Directory

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1985	American Properties (2810)	Polk's City Directory
	Address not listed in research source (2823)	Polk's City Directory
	Southw est Orthopedic Footw ear (2906)	Polk's City Directory
	Walking Shop The (2906)	Polk's City Directory
	Blackburn Street	Polk's City Directory
	Cross street no longer in address range	Polk's City Directory
1990	*Duniven Cir*	Polk's City Directory
	Autry Bruce Printing (2764)	Polk's City Directory
	Raines Boot & Shoe Repair (2766)	Polk's City Directory
	Webb Galleries (2770)	Polk's City Directory
	Pinkie's Liquor Store (2806)	Polk's City Directory
	Vacant (2810)	Polk's City Directory
	Address not listed in research source (2823)	Polk's City Directory
	Vacant (2906)	Polk's City Directory
	Blackburn Street	Polk's City Directory
	Cross street no longer in address range	Polk's City Directory
1994	*Duniven Cir*	Polk's City Directory
	Autry Bruce Printing (2764)	Polk's City Directory
	Cottle's Boot & Shoe Repair (2766)	Polk's City Directory
	Vacant (2770)	Polk's City Directory
	Blackburn Street Intersects	Polk's City Directory
	Lavin Associates (2806)	Polk's City Directory

<u>Year</u>	<u>Uses</u>	<u>Source</u>
1994	Eliza Jas D C P A (2806)	Polk's City Directory
	Pay Systems Inc. (2806)	Polk's City Directory
	Clean Air Group (2823)	Polk's City Directory
	Al-Anon Meeting Pl (2906)	Polk's City Directory
	Blackburn Street	Polk's City Directory
	Unable To Determine Cross Street Intersection	Polk's City Directory



EDR® Environmental
Data Resources Inc

The EDR Aerial Photo Decade Package

**Blucher S. Tharp Memorial USARC
2801 Duniven Circle
Amarillo, TX 79109**

Inquiry Number: 1715338.5

July 17, 2006

The Standard in Environmental Risk Management Information

440 Wheelers Farms Road
Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

EDR Aerial Photo Decade Package

Environmental Data Resources, Inc. (EDR) Aerial Photo Decade Package is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDRs professional researchers provide digitally reproduced historical aerial photographs, and when available, provide one photo per decade.

When delivered electronically by EDR, the aerial photo images included with this report are for ONE TIME USE ONLY. Further reproduction of these aerial photo images is prohibited without permission from EDR. For more information contact your EDR Account Executive.

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2006 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Date EDR Searched Historical Sources:

Aerial Photography July 17, 2006

Target Property:

2801 Duniven Circle

Amarillo, TX 79109

<u>Year</u>	<u>Scale</u>	<u>Details</u>	<u>Source</u>
1959	Aerial Photograph. Scale: 1"=500'	Flight Year: 1959	ASCS
1967	Aerial Photograph. Scale: 1"=500'	Flight Year: 1967	ASCS
1978	Aerial Photograph. Scale: 1"=500'	Flight Year: 1978	TXDOT
1988	Aerial Photograph. Scale: 1"=500'	Flight Year: 1988	TXDOT
1995	Aerial Photograph. Scale: 1"=500'	Flight Year: 1995	TXDOT
2001	Aerial Photograph. Scale: 1"=500'	Flight Year: 2001	USGS



"Linking Technology with Tradition"®

Sanborn® Map Report

Ship To: Phil Hardy
ENSAFE
5724 Summer Trees Drive
Memphis, TN 38134

Order Date: 7/14/2006 **Completion Date:** 7/14/2006
Inquiry #: 1715338.3s
P.O. #: 0888802978 0037 TS01
Site Name: Blucher S. Tharp Memorial USARC

Customer Project: TEJV-ECP Proj.
1013941ERN 901-372-7962

Address: 2801 Duniven Circle
City/State: Amarillo, TX 79109
Cross Streets:

This document reports that the largest and most complete collection of Sanborn fire insurance maps has been reviewed based on client supplied information, and fire insurance maps depicting the target property at the specified address were not identified.

NO COVERAGE

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report AS IS. Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.



EDR® Environmental
Data Resources Inc

**EDR Historical
Topographic Map
Report**

**Blucher S. Tharp Memorial USARC
2801 Duniven Circle
Amarillo, TX 79109**

Inquiry Number: 1715338.4

July 14, 2006

**The Standard in
Environmental Risk
Management Information**

440 Wheelers Farms Road
Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802
Internet: www.edrnet.com

EDR Historical Topographic Map Report

Environmental Data Resources, Inc.'s (EDR) Historical Topographic Map Report is designed to assist professionals in evaluating potential liability on a target property resulting from past activities. EDR's Historical Topographic Map Report includes a search of a collection of public and private color historical topographic maps, dating back to the early 1900's.

Thank you for your business.

Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES.** It can not be concluded from this report that coverage information for the target and surrounding properties does not exist from other sources. Any analyses, estimates, ratings or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Any liability on the part of EDR is strictly limited to a refund of the amount paid for this report.

Copyright © 2006 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.