



Photograph 1. Administration Building facing southwest



Photograph 2. Administration Building facing west



Photograph 3. POV facing west



Photograph 4. AMSA facing north



Photograph 5. MEP facing north



Photograph 6. MEP facing east at south end of Site



Photograph 7. AMSA Work Bays at southern end of AMSA



Photograph 8. Used Oil AST Hazardous Waste Storage Shed



Photograph 9. AMSA facing south



Photograph 10. Insulation in Boiler Room



Photograph 11. Loose floor tiles in Fan/Air Conditioning Room next to Boiler Room



Photograph 12. AMSA Hazmat Storage Cages in AMSA



Photograph 13. Waste oil storage sheds near southeast end of AMSA



Photograph 14. Hazmat Shed # 3



Photograph 15. Hazmat Shed # 2 containing new oil and diesel



Photograph 16. Hazmat Shed # 1



Photograph 17. CONEX Units



Photograph 18. Used batteries with secondary containment



Photograph 19. Used batteries wash and drain area with white staining



Photograph 20. Used batteries in Hazmat Room



Photograph 21. Former Hydraulic Lift area at northern end of AMSA



Photograph 22. Hazmat cabinet #1 in Hazmat Room



Photograph 23. Hazmat cabinet #2 in Hazmat Room



Photograph 24. Hazmat cabinet #3 in Hazmat Room



Photograph 25. Hazmat cabinet #4 in Hazmat Room



Photograph 26. Hazmat cabinet #5 in Hazmat Room



Photograph 27. New Oil Supply Room



Photograph 28. Solvent Cleaning Station



Photograph 29. Medical Exam Room



Photograph 30. Off Site facing east toward Preschool



Photograph 31. Off Site facing south



Photograph 32. Residences facing southwest



Photograph 33. Off Site facing northwest



Photograph 34. Former UST and OWS-1



Photograph 35. OWS – 2



Photograph 36. Rebuilt OWS – 3



Photograph 37. Former Indoor Firing Range



Photograph 38. Pole Mounted Transformer



Photograph 39. Former Dental X-Ray Room