

Appendix B
Site Reconnaissance Photos

**Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas**



Photo 1: Facing north along the northern Hot Springs USAR Center property boundary. The Hot Springs Rehabilitation Center is across Reserve Street from the Site.



Photo 2: Facing north along northern USAR Center property boundary and another view of the rehab center.

**Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas**



Photo 3: Facing north along west Site boundary on Opera Street. Hot Springs Rehabilitation Center is across Reserve Street from the Site. Note the transformer on the west side of Opera Street.



Photo 4: Facing west from the west Site boundary. The Federal building and parking lot is west of the Site across Opera Street.

**Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas**



Photo 5: Facing southwest from the southwest corner of Site. St. Luke's Episcopal Church is at southwest corner of Spring and Opera Streets.



Photo 6: Facing south from the southwest corner of the Site. Across Spring Street is the Sentinel Record building.

**Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas**



Photo 7: Facing southwest from the southeast corner of the Site. Across Spring Street is a vacant lot, east of the Sentinel Record building.



Photo 8: Facing east from the southeast corner of the Site. Across Civic Street is a residential area.

**Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas**



Photo 9: Facing east from the northeast corner of the Site. Across Civic Street is a vacant lot, then a residence.



Photo 10: Looking east at the northern side of the USAR Center building and entrance.

Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas



Photo 11: View of the maintenance shop looking east.



Photo 12: Floor drain in maintenance shop. There are three of these drains which connect to the main collection drain.

Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas



Photo 13: Main collection drain in maintenance shop.



Photo 14: Facing west. From left to right is a view of the wash rack, a roll-up door to the maintenance shop, and the POL storage room (yellow sign on door). The abandoned in place UST is believed to be partially covered by the POL storage room.

Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas



Photo 15: Interior of POL storage room. Note booms around drums and concrete threshold.



Photo 16: Southeast corner of POL storage room, where UST was formerly located. A flammable storage locker is visible to the east.

Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas



Photo 17: M-8 chemical alarms which contain radioactive source.



Photo 18: New asphalt area is the former location of the gymnasium and Hotel Eastman laundry.

**Hot Springs USAR Center (AR020)
200 Reserve Street
Hot Springs, Arkansas**



Photo 19: Looking northwest at a deteriorating retaining wall and an area of discoloration on the concrete.



Photo 20: View of floor tile in the maintenance shop restroom.